Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District I - (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283		WELL API NO. 30-025-25046
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE 🗹
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
	ICES AND REPORTS ON WELLS OBES OCD	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPEN OR PLUT BACK TO A CATION FOR PERMIT" (FORM C-101) FOR SUCH	WEST JAL B' DEEP
PROPOSALS.)	1111 1 1 0044	
1. Type of Well: Oil Well	Gas Well Other JUL 11 2014	8. Well Number
2. Name of Operator	and: To	9. OGRID Number
3. Address of Operator	Rating, Inc. RECEIVED	025670 10. Pool name or Wildcat
	2, Hobbs, nm 88241	
4. Well Location	, AUDE, 1111 00 914.	- al, WEST WOLF Camp
Unit Letter \mathcal{H} :	1980 feet from the N line and	660 feet from the E line
Section 17	Township 355 Range 36E	NMPM County LEA
Section	11. Elevation (Show whether DR, RKB, RT, GR, etc.	
	3150' RKB	
The second secon		
12. Check	Appropriate Box to Indicate Nature of Notice	e. Report or Other Data
		BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WO	
TEMPORARILY ABANDON DULL OR ALTER CASING	CHANGE PLANS COMMENCE DI MULTIPLE COMPL CASING/CEMEI	RILLING OPNS.□ P AND A □ NT JOB □
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL (CASING/CEME)	NI JOB
CLOSED-LOOP SYSTEM		
OTHER: Convert TO		
	oleted operations. (Clearly state all pertinent details, a	
	ork). SEE RULE 19.15.7.14 NMAC. For Multiple C	ompletions: Attach wellbore diagram of
proposed completion or rec	completion.	
* Please	. SEE ATTachment.	
* Preuse	. SEE HYTUUMMANI.	
Spud Date:	Rig Release Date:	
-		
I hereby certify that the information	above is true and complete to the best of my knowled	lge and belief.
\wedge		
SIGNATURE LONGE	Mel TITLE Pariset	DATE 7/11/2014
SIGNATURE / W///W/	TITLE Resident Chille well consu E-mail address:	DATE 7/11/2014 CHANT. COM PHONE: 575: 390, 1626
Type or print name Donnis	E-mail address:	Hone: 575.390.1626
For State Use Only	740	1 1
VI Alain	MANNENIT S. O	11/14 00 DUTE 7/15/2014
Conditions of Americal (if an)	CALLE VIEW COLL	WAR I I STORY
Conditions of Approval (if any):	1	•
	1	•
		JUL 1 5 2014

JUL 11 2014

WEST JAL B DEEP # 1 30-025-25046

RECEIVED

UNIT "H", 1980' FNL, 660' FEL, SEC. 17, T25S, R36E

Well Data

Elevation: 3151' KB, 3123' GL TD: 18945', PBTD: 11650' CIBPI@ 11650' & 14200'

Conductor: 20" 94# @ 767' w/ 1700 sxs

Surface Csg: 13 3/8" 68# & 72# @ 5159' w/ 5300 sxs, Toc @ 590' Intermediate Csg: 10 ¾" 60.7# @ 11263' w/ 2950 sxs, Toc @ 5140'

Intermediate Liner: 7 3/4" 46.1# S-105 Liner, 10917' to 14685' w/ 1300 sxs (Tested 2500 Psig on 2/2/76,

held 30 minutes, Good test)

Production Liner: 5" 23.08# S-95 Liner @ 14332' to 18930' w/ 750 sxs (Tested 2500 Psig on 2/2/76,

held 30 minutes, Good test)

Perfs:

Wolf Camp	@	11379'- 11381', 11395'-11399'		
Wolf Camp	@	11416' -11425',	(Squeezed)	
Strawn	@	11708' – 11995',	CIBP @ 11650'	
Atoka	@	12682' – 12706'		
Fusselman	@	16411' - 16439'	CIBP @ 14200'	
Ellenburger	@	18444' - 18858'	CIBP @ 17065'	

Current Equipment in the hole:

Tubing 345 jts 2 3.8" 4.7# P-110 7 5/8" TAC @ ~11268'

3 jts 2 3/8" 4.7# P-110

SN @ 11369'

4' PS

2 3/8" 4.7# P-110 Mud Jt @ ~11401'

Rods

1 - Polish Rod 141 - 7/8" Norris 97 316 – ¾" Norris 97 2" x 1 1/4" x 20' Pump

Objective:

Pooh w/ rods and tbg, Recover fish (4 jts 2 3/8" tbg & packer), Cement Squeeze Wolf

Camp, Drill CIBP @ 11,650', Prepare well for injection test capabilities in the

Strawn/Atoka prior to drilling out CIBP 14,200'.

Introduction: This procedure presents the proposed steps for working over BC & D Operating, Inc's

West Jal "B" Deep # 1. These steps are intended as a guideline, conditions

encountered during the actual work will dictate the appropriate steps to be taken.

Any significant deviation from the proposed program will require prior approval by Project Manager and BC & D Operating, Inc.

Contact Info:

BC & D Operating, Inc. P.O. Box 302

Hobbs, New Mexico 88241

Donnie Hill – Project Manager 575.390.7626 dhill@wellconsultant.com

Donnie Hill Jr. – Well-Site Supervisor 576.30.1207

Our work is never so urgent or important that we cannot take the time to do it safely and environmentally friendly.

- a) Safe and environmentally friendly operations are of the utmost importance to all BC & D properties and facilities. To further this goal, the BC & D Supervisor at the location shall request tailgate safety meeting prior to initiation of work and also prior to any critical operations. All Company, contact, and service personnel then present at the location shall attend these tailgate safety meetings to review proposed upcoming steps, procedures, and potentially hazardous situations. Occurrence of these meetings shall be recorded in the Daily Reports. Prepare or review a Job Safety Analysis before each and every task. STOP WORK OBSERVATIONS are expected and encouraged.
- b) Keep Material Safety Data Sheets, (MSDS), on location, for all mud products and chemicals, available to all well-site personnel for review.
- c) Post Emergency Numbers near your telephone.
- d) All service company representatives working on a BC & D location are required to have a minimum training prior to beginning of work.
- e) HOLD OPERATIONAL AND SAFETY MEETING WITH ALL PERSONNEL ON LOCATION. Review the objective of the task at hand, the procedure, critical parameters.

PROCEDURE:


1.	Clean	location	of all	debris.

- 2. Test anchors and replace if necessary,
- 3. MIRU Completion Rig, conduct safety meeting, brief all Company, Contract and service personnel then present at location of task at hand, the procedure, critical parameters, weather conditions, potential H2s issues, contingency plans, etc..
- 4. Unseat 2" x 1.250" x 20' pump, (Rod weight should be ~20,000 lbs), POOH and lay down polish rod, 141 7/8" rods, (need a good count), & 316 ¾" Rods, (need a good count), once good rod count is achieved make calculation to determine where seating nipple is landed, (make arrangements to ship rods to Hobbs yard asap)
- 5. ND well head, NU 10K BOP, Rls Tac @ ~11,268' (tubing weight at TAC should be ~52 to 53 points), once TAC is released first movement will be down to confirm TAC has been released,
- 6. POOH and lay down 2 3/8" tbg, (get a good count, make arrangements to ship to Hobbs yard asap)
- 7. P/U and Tih w/ shoe (cut-rite on bottom only), ~155' wash pipe w/ T doors and wire rope internally, ¼" drain port at ~10' above shoe, collars, bumper sub, jars and 2 7/8" work string,
- 8. Tag fish @ ~11,500', attempt to break circ, get over fish, wash down to packer @ ~11,640',
- 9. Dry drill on packer for app 30 minutes,
- 10. POOH w/ tbg, stand back wash pipe, check shoe for indications of progress made,
- 11. PU and TIH W/ over shot x grapple to get on fish, collars, bumper sub, jars & work string,
- 12. Engage fish @ ~11,500', get over fish, confirm over shot is over fish and engaged,
- 13. Work fish free and Pooh w/ same, stand back collars, and work string lay down fish,
- 14. Pu and Tih w/ cement retainer, and work string, set retainer @ ~11,340', sting out, load hole and test casing @ 500 Psig, sting back into retainer test tbg to 2000 Psig, Miru Warrior cement wagons, squeeze Wolf Camp Perfs @ 11,379'-11,399', if squeeze is not achieved over displace to clear perfs of cement and resqueeze, If squeeze is achieved pull out of retainer and circulate tbg clean, Pooh w/ tbg,
- 15. Pu and Tih w/ bit, collars and work string, tag TOC and drill out cement and retainer, test squeeze to 1500 Psig, drill out retainer and cement down to 11,400', test casing to 1500 Psig, report results to Donnie Hill if not on location,
- 16. Once Wolf Camp is successfully squeezed, Pooh w/ work string,
- 17. Pu and Tih w/ new bit and work string to drill out CIBP @ 11,650', be prepared for pressure below CIBP, (well may go on a vacuum?) if well goes on vacuum be prepared for Atoka to kick,
- 18. Once CIBP is drilled out continue Tih to below Strawn perfs @ 11,708'- 14,200',
- 19. Establish rate and pressure into Strawn perfs and report results,
- 20. Pooh and lay down work string and BHA,
- 21. MIRU Archer Wire Line unit and Tih w/ gauge ring/junk basket, Pooh, Pu and Tih w/ GR/CCL/CBL and log from 14,200' to 7 ¾" liner top @ 10,917'.
- 22. Report CBL results to NMOCD District 1 office along with a copy of the CBL.
- 23. Pu and Tih w/ 7 5/8" Arrow Set 1-X packer with profile nipple, on/off tool, and 4 ½" IPC 11.60 PPF L-80 tubing, set packer at ~11,650', set pkr in tension, (10 pts), get off

- on/off tool, pump casing capacity with packer fluid, (~871 bbls) will have 1500 bbls on location treated) latch back onto packer,
- 24. ND BOP, NU well head, conduct preliminary MIT, if successful notify NMOCD to witness test following morning. If MIT is not successful take action to identify and correct problem and retest.
- 25. Providing a successful MIT is established, Rd and Rls all contractors and rental equipment,
- 26. Clean location and prepare to run injection test on Strawn and Atoka prior to drilling out CIBP @ 14,200'.

NO. OF COPIES RECEIVED		•		,	Form C-103	
DISTUITED		\smile			Supersedes	
SANTA FE		NEW MEXICO OIL C	ONSERVATION COMM	ISSION	C-102 and C Effective 1-1	
FILE						-
U.S.G.S.					5a. Indicate Typ	e of Lease
LAND OFFICE					State	Fee X
OPERATOR					5. State Oil & G	
	_ -L1					
	SUNDRY MOTIC	ES AND DEDODTS	ON WELLS		mmm	mmmm
(DO NOT USE THIS F US	FORM FOR PROPOSALS TO E "APPLICATION FOR PER	CES AND REPORTS ORILL OR TO DEEPEN OR PL IMIT - (FORM C-101) FOR	UG BACK TO A DIFFERENT I	ESERVOIR.		
1.					7. Unit Agreeme	ent Name
OIL GA	X OTHER.					
2. Name of Operator					8. Farm or Leas	e Name
Skelly Oil Comp	anv			•	West Jal '	'B" Deen
3. Address of Operator					9. Well No.	
P. O. Box 1351,	Midland, Texa	as 79701			1	
4. Location of Well					10. Field and P	ool, or Wildcat
บ	1080	Nort!	660	•	i	•
UNIT LETTER H		FEET FROM THE NOTE	LINE AND OUT	FEET FROM	WEST SAT I	CLLLLLLLLL
Foot	17	9 !	5.0	260		
THE East	LINE, SECTION	TOWNSHIP 2	RANGE	JUE NMPM.	IIIIIII	
mmmm	mmm	15. Elevation (Show whe	ther DF RT GR etc.		12. County	444444444444444444444444444444444444444
		•	171' KB		1_	
/////////////////////////////////////	minini				Lea	_0711111111
	Check Appropris	ate Box To Indicat	e Nature of Notice	, Report or Oth	ier Data	•
NOT	ICE OF INTENTIO	N TO:		SUBSEQUENT	REPORT OF	:
	 1	ı			4	
PERFORM REMEDIAL WORK	ᆜ	PLUG AND ABANDON	REMEDIAL WORK		ALTE	RING CASING
TEMPORARILY ABANDON		(COMMENCE DRILLING	OPNS.	PLUG	AND ABANDONMENT
PULL OR ALTER CASING	_]	CHANGE PLANS	CASING TEST AND CI			
		1		orate and to		urger
OTHER			and	Fusselman zo	ones.	
		27	1			
17. Describe Proposed or C work) SEE RULE 1103	· Ompreted Operations (C	tearty state air periment	detaits, and give pertine	ent dates, including	estimatea aate oj	starting any proposed
1) Drilled 9-1	/2" hole 11,26	53-14,686'.				
		3/4" OD 46.10# A	Atlas Bradford	S-105 F1-4F	casing lin	er at
10,917-14,6		•				
		with 1300 sacks	Class "C" cem	ent mixed O.	.3% D65. 0.	2% D13 and
0.4 gal. D7					,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
		7-11,011' and 14	4.200-14.686	Pressure te	ested top o	£ 7-3/4" OD
		nutes, held okay			out top t	_ , 0, , 02
5) Drilled 6-1			, •			
		OD 23.08# T&C 1	Buttress casing	and 64 ioir	its (26551)	5" OD
		FL-4S casing at			(2033)	
		h 725 sacks Cla			talid 22. 0	.4% CFR-2
and 3# KC1		.n /25 backs of	ibo ii coment	mired 0.0% i	mila 22, 0	. 4% OIK 2,
		9-14,332' and 18	3 775-18 885	Presenta tod	eted top of	5" OD
		ntes, held okay		rresoure res	,cea cop or	J VD
		18,444', 18,451		/881 18 /no)	1/21 18 5261
		', 18,552', 18,				
		', 18,666-1/2',				
						,/10', 10,/31
18,//4-1/2	, 10,000', 18,	,852' and 18,858	with one sho	т еасп ртасе	3.	
				+		
18. I hereby certify that the	information above is tr	rue and complete to the bo	est of my knowledge and	belief.		
	. ,					
51GNED	D. R. C	Crow TITLE_	Lead Clerk		DATE	2-2-76
	1					
•	Succe Sussess		**		197	-a
APPROVED BY	Len J. Sweet	TITLE			DATE	uye :
A PROTES OF						

CONDITIONS OF APPROVAL, IF ANY:



State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez Governor

David Martin
Cabinet Secretary

Brett F. Woods, Ph.D. Deputy Cabinet Secretary Jami Bailey, Division Director
Oil Conservation Division



Administrative Order SWD-1482 June 10, 2014

ADMINISTRATIVE ORDER OF THE OIL CONSERVATION DIVISION

Pursuant to the provisions of Division Rule 19.15.26.8B. NMAC, BC & D Operating, Incorporated (the "operator") seeks an administrative order to re-enter and re-complete its West Jal B Deep Well No. 1 with a location of 1980 feet from the North line and 660 feet from the East line, Unit letter H of Section 17, Township 25 South, Range 36 East, NMPM, Lea County, New Mexico, for produced water, commercial disposal purposes. The subject well was previously approved for injection into the Silurian Fusselman formation under Administrative Order SWD-1328 approved April 20, 2012.

THE DIVISION DIRECTOR FINDS THAT:

The application has been duly filed under the provisions of 19.15.26.8B. NMAC and satisfactory information has been provided that affected parties as defined in said rule have been notified and no objections have been received within the prescribed waiting period. The applicant has presented satisfactory evidence that all requirements prescribed in 19.15.26.8 NMAC have been met and the operator is in compliance with 19.15.5.9 NMAC.

IT IS THEREFORE ORDERED THAT:

The applicant, BC & D Operating, Incorporated (OGRID 25670), is hereby authorized to utilize its West Jal B Deep Well No. 1 (API 30-025-25046) with a location of 1980 feet from the North line and 660 feet from the East line, Unit letter H of Section 17, Township 25 South, Range 36 East, NMPM, Lea County, for commercial disposal of oil field produced water (UIC Class II only) through perforations into an interval consisting of the Strawn, Atoka, Mississippian, Devonian, and Fusselman formations from 11708 feet to 16439 feet. Injection will occur through internally-coated, 4 ½-inch or smaller tubing and a packer set within 100 feet of the permitted interval.

IT IS FURTHER ORDERED THAT:

The operator shall take all steps necessary to ensure that the disposed water enters only the approved disposal interval and is not permitted to escape to other formations or onto the surface. This includes the well construction proposed and described in the application with the following stipulations.

The operator shall squeeze cement the open perforations located from 11379 feet to

Administrative Order SWD-1482 BC & D Operating, Inc. June 10, 2014 Page 2 of 3

11399 feet that are located in the Wolfcamp formation. Accordingly, the packer set and tubing shall be lowered to be within 100 feet of the upper peroration 11708 feet.

The operator shall run a cement bond log following the cement squeeze of the perforations showing the cement placement for the 7 ¾-inch and 5-inch liners. The operator shall supply the Division's district I office with a copy prior to commencing injection.

The operator of this well shall run an injection survey (tracer/temperature or equivalent) of the injection interval within two (2) years after commencing disposal into this well. The operator will supply both the Division district I office and Santa Fe Bureau office with a copy of each survey log. If the Division does not receive of the log within the prescribed time period, then this disposal permit shall be terminated ipso facto.

After installing tubing, the casing-tubing annulus shall be loaded with an inert fluid and equipped with a pressure gauge or an approved leak detection device in order to determine leakage in the casing, tubing, or packer. The casing shall be pressure tested from the surface to the packer setting depth to assure casing integrity.

The well shall pass an initial mechanical integrity test ("MIT") prior to initially commencing disposal and prior to resuming disposal each time the disposal packer is unseated. All MIT procedures and schedules shall follow the requirements in Division Rule 19.15.26.11A. NMAC. The Division Director retains the right to require at any time wireline verification of completion and packer setting depths in this well.

The wellhead injection pressure on the well shall be limited to **no more than 2342 psi**. In addition, the disposal well or system shall be equipped with a pressure limiting device in workable condition which shall, at all times, limit surface tubing pressure to the maximum allowable pressure for this well.

The Director of the Division may authorize an increase in tubing pressure upon a proper showing by the operator of said well that such higher pressure will not result in migration of the disposed fluid from the target formation. Such proper showing shall be demonstrated by sufficient evidence including but not limited to an acceptable Step-Rate Test.

The operator shall notify the supervisor of the Division's district I office of the date and time of the installation of disposal equipment and of any MIT so that the same may be inspected and witnessed. The operator shall provide written notice of the date of commencement of disposal to the Division's district office. The operator shall submit monthly reports of the disposal operations on Division Form C-115, in accordance with Division Rules 19.15.26.13 and 19.15.7.24 NMAC.

Without limitation on the duties of the operator as provided in Division Rules 19.15.29 and 19.15.30 NMAC, or otherwise, the operator shall immediately notify the Division's district I office of any failure of the tubing, casing or packer in the well, or of any leakage or release of water, oil or gas from around any produced or plugged and abandoned well in the area, and shall take such measures as may be timely and necessary to correct such failure or leakage.

The injection authority granted under this order is not transferable except upon division approval. The Division may require the operator to demonstrate mechanical integrity of any injection well that will be transferred prior to approving transfer of authority to inject.

The Division may revoke this injection permit after notice and hearing if the operator is in violation of 19.15.5.9 NMAC.

The disposal authority granted herein shall terminate two (2) years after the effective date of this order if the operator has not commenced injection operations into the subject well. One year after the last date of reported disposal into this well, the Division shall consider the well abandoned, and the authority to dispose will terminate *ipso facto*. The Division, upon written request mailed by the operator prior to the termination date, may grant an extension thereof for good cause.

Compliance with this order does not relieve the operator of the obligation to comply with other applicable federal, state or local laws or rules, or to exercise due care for the protection of fresh water, public health and safety and the environment.

Jurisdiction is retained by the Division for the entry of such further orders as may be necessary for the prevention of waste and/or protection of correlative rights or upon failure of the operator to conduct operations (1) to protect fresh or protectable waters or (2) consistent with the requirements in this order, whereupon the Division may, after notice and hearing, terminate the disposal authority granted herein.

IAMIBAILEY

Director

JB/prg

cc:

Oil Conservation Division – Hobbs District Office