
State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

	OIL CONSERV.	ATION DIVISION	
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240		St. Francis Dr. NM 87505	WELL API NO. 30-025-05480
<u>DISTRICT II</u>			5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210			STATE X FEE
DISTRICT III			6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410			
SUNDRY NO	TICES AND REPORTS ON WE	LLS	7. Lease Name or Unit Agreement Name
	ROPOSALS TO DRILL OR TO DEEPEN		North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "A	APPLICATION FOR PERMIT" (Form C-		Section 24
1. Type of Well: Oil Well X	Gas Well Other	HOBBS OCD	8. Well No. 321
Name of Operator Occidental Permian Ltd.		11 11 9 A 2014	9. OGRID No. 157984
3. Address of Operator	7 50222	- JUL 3 W 2014	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX	. 79323		
		RECEIVED	
Unit Letter G : 2310	Feet From The North	Line and <u>2310</u> Fe	eet From The East Line
Section 24	Township 18-S	Range 37-	E NMPM Lea County
	11. Elevation (Show whether DF, Ri		
	3664' GR		
Pit or Below-grade Tank Application	or Closure		
Pit Type Depth of Groun	d Water Distance from r	nearest fresh water well	Distance from nearest surface water
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material			
THE Ellier Thicknessniii	Below-Glade Falls. Volume	oois, construction w	utor tai
12. Chec	k Appropriate Box to Indicate Na		Other Data SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	X ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OF	PNS PLUG & ABANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEME	NT JOB
OTHER:		OTHER:	
13. Describe Proposed or Completed Op	perations (Clearly state all pertinent d For Multiple Completions: Attach v	etails, and give pertinent date	es, including estimated date of starting any completion or recompletion.
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. 1. RUPU & RU.		etails, and give pertinent date	
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. 1. RUPU & RU. 2. RU wire line & perforate tu 3. ND well head/NU BOP.	For Multiple Completions: Attach vibing @3899'. RD wire line	etails, and give pertinent date wellbore diagram of proposed	
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. 1. RUPU & RU. 2. RU wire line & perforate tu 3. ND well head/NU BOP. 4. POOH & lay down ESP equ	For Multiple Completions: Attach vibing @3899'. RD wire line aipment. Found motor and cable gr	etails, and give pertinent date wellbore diagram of proposed	
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. 1. RUPU & RU. 2. RU wire line & perforate tu 3. ND well head/NU BOP. 4. POOH & lay down ESP equ 5. RIH w/bit. Tagged @4308	For Multiple Completions: Attach vibing @3899'. RD wire line aipment. Found motor and cable gr. POOH w/bit.	etails, and give pertinent date vellbore diagram of proposed rounded.	
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. 1. RUPU & RU. 2. RU wire line & perforate tu 3. ND well head/NU BOP. 4. POOH & lay down ESP equ 5. RIH w/bit. Tagged @4308 6. RIH w/ESP equipment set of	For Multiple Completions: Attach vibing @3899'. RD wire line aipment. Found motor and cable gr	etails, and give pertinent date vellbore diagram of proposed rounded.	
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. 1. RUPU & RU. 2. RU wire line & perforate tu 3. ND well head/NU BOP. 4. POOH & lay down ESP equ 5. RIH w/bit. Tagged @4308 6. RIH w/ESP equipment set of 7. ND BOP/NU wellhead.	For Multiple Completions: Attach vibing @3899'. RD wire line aipment. Found motor and cable gr. POOH w/bit. on 124 jts of 2-7/8" tubing. Intake	etails, and give pertinent date vellbore diagram of proposed rounded.	
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. 1. RUPU & RU. 2. RU wire line & perforate tu 3. ND well head/NU BOP. 4. POOH & lay down ESP equ 5. RIH w/bit. Tagged @4308 6. RIH w/ESP equipment set of 7. ND BOP/NU wellhead.	For Multiple Completions: Attach vibing @3899'. RD wire line aipment. Found motor and cable gr. POOH w/bit.	etails, and give pertinent date vellbore diagram of proposed rounded.	
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. 1. RUPU & RU. 2. RU wire line & perforate tu 3. ND well head/NU BOP. 4. POOH & lay down ESP equ 5. RIH w/bit. Tagged @4308 6. RIH w/ESP equipment set of 7. ND BOP/NU wellhead. 8. RDPU & RU. Clean location	For Multiple Completions: Attach vibing @3899'. RD wire line aipment. Found motor and cable gr. POOH w/bit. on 124 jts of 2-7/8" tubing. Intake	etails, and give pertinent date vellbore diagram of proposed rounded.	
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. 1. RUPU & RU. 2. RU wire line & perforate tu 3. ND well head/NU BOP. 4. POOH & lay down ESP equ 5. RIH w/bit. Tagged @4308 6. RIH w/ESP equipment set of 7. ND BOP/NU wellhead. 8. RDPU & RU. Clean location	For Multiple Completions: Attach vibing @3899'. RD wire line aipment. Found motor and cable gr. POOH w/bit. on 124 jts of 2-7/8" tubing. Intake	etails, and give pertinent date vellbore diagram of proposed rounded.	
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. 1. RUPU & RU. 2. RU wire line & perforate tu 3. ND well head/NU BOP. 4. POOH & lay down ESP equ 5. RIH w/bit. Tagged @4308 6. RIH w/ESP equipment set of 7. ND BOP/NU wellhead. 8. RDPU & RU. Clean location RUPU 06/24/2014 RDPU 06//26/2014	For Multiple Completions: Attach vibing @3899'. RD wire line uipment. Found motor and cable grown 124 jts of 2-7/8" tubing. Intakeon and return well to production.	etails, and give pertinent date vellbore diagram of proposed rounded.	completion or recompletion.
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. 1. RUPU & RU. 2. RU wire line & perforate tu 3. ND well head/NU BOP. 4. POOH & lay down ESP equ 5. RIH w/bit. Tagged @4308 6. RIH w/ESP equipment set of 7. ND BOP/NU wellhead. 8. RDPU & RU. Clean location RUPU 06/24/2014 RDPU 06//26/2014	For Multiple Completions: Attach vibing @3899'. RD wire line uipment. Found motor and cable grown 124 jts of 2-7/8" tubing. Intakeon and return well to production.	etails, and give pertinent date vellbore diagram of proposed rounded.	
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. 1. RUPU & RU. 2. RU wire line & perforate tu 3. ND well head/NU BOP. 4. POOH & lay down ESP equ 5. RIH w/bit. Tagged @4308 6. RIH w/ESP equipment set of 7. ND BOP/NU wellhead. 8. RDPU & RU. Clean location RUPU 06/24/2014 RDPU 06//26/2014	For Multiple Completions: Attach vibing @3899'. RD wire line aipment. Found motor and cable gr. POOH w/bit. on 124 jts of 2-7/8" tubing. Intake on and return well to production.	etails, and give pertinent date vellbore diagram of proposed rounded. e set @3918'.	y that any pit or below-grade tank has been/will be
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. 1. RUPU & RU. 2. RU wire line & perforate tu 3. ND well head/NU BOP. 4. POOH & lay down ESP equ 5. RIH w/bit. Tagged @4308 6. RIH w/ESP equipment set of 7. ND BOP/NU wellhead. 8. RDPU & RU. Clean location RUPU 06/24/2014 RDPU 06//26/2014	For Multiple Completions: Attach vibing @3899'. RD wire line aipment. Found motor and cable gr. POOH w/bit. on 124 jts of 2-7/8" tubing. Intake on and return well to production.	etails, and give pertinent date vellbore diagram of proposed rounded.	y that any pit or below-grade tank has been/will be
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. 1. RUPU & RU. 2. RU wire line & perforate tu 3. ND well head/NU BOP. 4. POOH & lay down ESP equ 5. RIH w/bit. Tagged @4308 6. RIH w/ESP equipment set of 7. ND BOP/NU wellhead. 8. RDPU & RU. Clean location RUPU 06/24/2014 RDPU 06//26/2014	For Multiple Completions: Attach vibing @3899'. RD wire line aipment. Found motor and cable graph. POOH w/bit. In 124 jts of 2-7/8" tubing. Intake on and return well to production.	etails, and give pertinent date vellbore diagram of proposed counded. eset @3918'.	y that any pit or below-grade tank has been/will be ve OCD-approved
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. 1. RUPU & RU. 2. RU wire line & perforate tu 3. ND well head/NU BOP. 4. POOH & lay down ESP equ 5. RIH w/bit. Tagged @4308 6. RIH w/ESP equipment set of 7. ND BOP/NU wellhead. 8. RDPU & RU. Clean location RUPU 06/24/2014 RDPU 06//26/2014 Thereby certify that the information above is constructed or closed according to NMOCD guidelines. SIGNATURE	For Multiple Completions: Attach vibing @3899'. RD wire line supposed in the s	etails, and give pertinent date vellbore diagram of proposed counded. eset @3918'.	y that any pit or below-grade tank has been/will be ve OCD-approved B Associate DATE 07/29/2014
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. 1. RUPU & RU. 2. RU wire line & perforate tu. 3. ND well head/NU BOP. 4. POOH & lay down ESP equ. 5. RIH w/bit. Tagged @4308. 6. RIH w/ESP equipment set of the complete to the compl	For Multiple Completions: Attach vibing @3899'. RD wire line supposed in the s	etails, and give pertinent date vellbore diagram of proposed vounded. Test @3918'. Pledge and belief. I further certification or an (attached) alternation plan TITLE Administrative	y that any pit or below-grade tank has been/will be ve OCD-approved B Associate DATE 07/29/2014
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. 1. RUPU & RU. 2. RU wire line & perforate tu 3. ND well head/NU BOP. 4. POOH & lay down ESP equ 5. RIH w/bit. Tagged @4308 6. RIH w/ESP equipment set of 7. ND BOP/NU wellhead. 8. RDPU & RU. Clean location RUPU 06/24/2014 RDPU 06//26/2014 Thereby certify that the information above is constructed or closed according to NMOCD guidelines SIGNATURE TYPE OR PRINT NAME Mendy A.J.	For Multiple Completions: Attach vibing @3899'. RD wire line supposed in the s	etails, and give pertinent date vellbore diagram of proposed vounded. Test @3918'. Pledge and belief. I further certification or an (attached) alternation plan TITLE Administrative	y that any pit or below-grade tank has been/will be ve OCD-approved B Associate DATE 07/29/2014
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. 1. RUPU & RU. 2. RU wire line & perforate tu 3. ND well head/NU BOP. 4. POOH & lay down ESP equ 5. RIH w/bit. Tagged @4308 6. RIH w/ESP equipment set of 7. ND BOP/NU wellhead. 8. RDPU & RU. Clean location RUPU 06/24/2014 RDPU 06//26/2014 Thereby certify that the information above is constructed or closed according to NMOCD guidelines SIGNATURE TYPE OR PRINT NAME Mendy A J For State Use Only	For Multiple Completions: Attach vibing @3899'. RD wire line supposed in the s	etails, and give pertinent date vellbore diagram of proposed rounded. Tounded. Test @3918'. Teledge and belief. I further certified or an (attached) alternative plan TITLE Administrative mendy johnson@oxy.com	y that any pit or below-grade tank has been/will be ve OCD-approved B Associate DATE 07/29/2014

Work Plan Report for Well: NHSAU 321-24



Survey Viewer