State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004


FILE IN TRIPLICATE	OIL CONSERV.	ATION DIVISION	101.100 5 27 2001
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240		St. Francis Dr. NM 87505	WELL API NO. 30-025-38110
DISTRICT II	Sama 1 e,	1441 07505	5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210			STATE FEE X
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410			6. State Oil & Gas Lease No.
	OTICES AND REPORTS ON WE	LLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR F	PROPOSALS TO DRILL OR TO DEEPEN	OR PLUG BACK TO A	North Hobbs (G/SA) Unit
· · · · · · · · · · · · · · · · · · ·	APPLICATION FOR PERMIT" (Form C-I	101 HOBBS GGB)	Section 18
Type of Well: Oil Well X	Gas Well Other		8. Well No. 529
2. Name of Operator	Gas Well Other	jul 2 9 2014	9. OGRID No. 157984
Occidental Permian Ltd.			10.0
3. Address of Operator HCR 1 Box 90 Denver City, T.	X 79323	RECEIVED	10. Pool name or Wildcat Hobbs (G/SA)
4. Well Location			,
Unit Letter N : 780	Feet From The South	Line and 1940 Fee	t From The West Line
Section 18	Township 18-S	Range 38-E	NMPM Lea County
11. Elevation (Show whether DF, RKB, RT GR, etc.) 3642' KB			
Pit or Below-grade Tank Application	or Closure		
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water			
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	X ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPI	NS. PLUG & ABANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN	т јов
OTHER:		OTHER:	
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any			
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. RUPU & RU.			
2. RU wire line and perforate tubing @3915'. RD wire line.			
3. ND wellhead/NU BOP.			
 POH & lay down ESP equipment. RIH w/bit and drill collars. Tag @4120'. RU power swivel & stripper head. Took several attempts to get well to circulate. Drill on cement 			
from 4120-4155'. Drill on CIBP from 4155-4157'. Fell thru to 4370'. Circulate clean. RD power swivel & stripper head. POOH w/bit			
and drill collars. 6. RIH w/packer set @3950'. RU wire line and tagged TD @4425'. Log perfs at 4380-4000'. RD wire line. Sent log to engineers. POOH			
w/packer.			
 RIH w/CIBP set @4195' and CICR ser @4000'. RU Warrior Energy & pump 50 bbl of 50/50 POZ cement. Pressure started to go up. Pumped 30 bbl of .2% Super CBL cement. Stung out of CICR and reversed out 23 bbl of cement. RD Warrior Energy. 			
See attached sheet for additional data			
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or			
closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved			
SIGNATURE TITLE Administrative Associate DATE 07/28/2014			
	of May wow	TITLE Administrative	
TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy johnson@oxy.com TELEPHONE NO. 806-592-6280			
APPROVED BY Maleux Strown TITLE Dist. Supervisorate 7/30/2014			
CONDITIONS OF APPROVAL IF ANY			
v v v v v v v v v v v v v v v v v v v			JUL 3 0 20141 W
			De an sold

NHU 18-529 API #30-025-38110

- 8. RIH w/bit & drill collars. Tag @3985'. RU power swivel & stripper head. Drill cement from 3985-4000'. Drill CICR @4000-4003'. Continue drilling on cement from 4003-4165'. Fell thru to CIBP @4195'. Drilled on CIBP to 4198'. Fell thru and pushed down to 4336'. Drilled on asphaltenes from 4336-4460'. Would not make any more hole. RD power swivel & stripper head. POOH w/bit & drill collars.
- 9. RIH w/treating packer set @4192'. RU Pate and pump 15 bbl of Xylene mixed with 20 gal of EC 6495B chemical down tubing. Flush w/30 bbl brine. RD Pate truck. POOH w/packer.
- 10. RIH w/ESP equipment set on 124 jts of 2-7/8" tubing. Intake set @3982'
- 11. ND BOP/NU wellhead.
- 12. RDPU & RU. Clean location and return well to production.

RUPU 05/20/2014 RDPU 06/05/2014

Work Plan Report for Well: NHSAU 529-18



Survey Viewer