<u>District 1</u> – (575) 393-6161		New Mexico and Natural Resources	Form C-103 Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283			WELL API NO
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		5. Indicate Type of Lease
<u>District III</u> - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410			STATE FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa F	e, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NO (DO NOT USE THIS FORM FOR PRO		PEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name T. Anderson
DIFFERENT RESERVOIR. USE "APP PROPOSALS.)		HOBBS OCD	8. Well Number 2
 Type of Well: Oil Welł Name of Operator 	Gas Well 🗌 Other	HOBBOT	9. OGRID Number
Apache Corporation	1	AUG 0 5 2014	873
3. Address of Operator		400 .	10. Pool name or Wildcat
303 Veterans Airpark Lane, Ste	3000, Midland, TX 79705	RECEIVED	Eumont-Yates/7 RvrsQn
4. Well Location Unit Letter N	: 660 feet from the	S 1	980 W feet from the line
Section 8	Township 2(feet from theline 1 NMPM County Lea
		hether DR, RKB, RT, GR, e	
	3540' DF	· · · · · · · · · · · · · · · · · · ·	
12. Check	Appropriate Box to Ir	ndicate Nature of Notic	e, Report or Other Data
E-PERMITTING	-		IBSEQUENT REPORT OF:
PERFO P&A NR P.M.	P&A R)ON		
TEMPC INT to P&A			
DOWNI CSNG	CHG Loc		
TA		· · · · ·	
OTHER:			
			and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
proposed completion or			
proposed completion or 1 7/16/14 Notify OCD of MIRU. RIH tag	recompletion. CIBP @ 3425'.		
proposed completion or 1 7/16/14 Notify OCD of MIRU. RIH tag 7/17/14 Attempt to load well. Did not	recompletion. CIBP @ 3425'. load. Spot 140 x class "c" cmt @	Q,	
proposed completion or 1 7/16/14 Notify OCD of MIRU. RIH tag 7/17/14 Attempt to load well. Did not 7/18/14 RIH tag TOC @ 2607' load we	recompletion. CIBP @ 3425'. load. Spot 140 x class "c" cmt @ ell pressure test casing to 1000	psi ok.	
proposed completion or 1 7/16/14 Notify OCD of MIRU. RIH tag 7/17/14 Attempt to load well. Did not 7/18/14 RIH tag TOC @ 2607' load we 7/21/14 POH perf @ 2454' sqz 70 x cl 7/22/14 RIH tag TOC @ 1995' POH p	recompletion. CIBP @ 3425'. load. Spot 140 x class "c" cmt @ ell pressure test casing to 1000 ass "c" cmt displace to 2050' W erf @ 1160' sqz 45 x class "c" c	ያ bsi ok. /OC 4 hrs. mt djsplace to 1100' WOC 4 hr	s. RIH tag TOC @ 1077' POH perf @ 250'.
proposed completion or 17/16/14 Notify OCD of MIRU. RIH tag 7/17/14 Attempt to load well. Did not 7/18/14 RIH tag TOC @ 2607' load we 7/21/14 POH perf @ 2454' sqz 70 x cl 7/22/14 RIH tag TOC @ 1995' POH p	recompletion. CIBP @ 3425'. load. Spot 140 x class "c" cmt @ ell pressure test casing to 1000 ass "c" cmt displace to 2050' W erf @ 1160' sqz 45 x class "c" c	ያ bsi ok. /OC 4 hrs. mt djsplace to 1100' WOC 4 hr	s. RIH tag TOC @ 1077' POH perf @ 250'. t anchors, wellhead and cleaned location.
proposed completion or 17/16/14 Notify OCD of MIRU. RIH tag 7/17/14 Attempt to load well. Did not 7/18/14 RIH tag TOC @ 2607' load we 7/21/14 POH perf @ 2454' sqz 70 x cl 7/22/14 RIH tag TOC @ 1995' POH p	recompletion. CIBP @ 3425'. load. Spot 140 x class "c" cmt @ ell pressure test casing to 1000 ass "c" cmt displace to 2050' W erf @ 1160' sqz 45 x class "c" c ' to surf. Cmt was circ behind 6	ያ bsi ok. /OC 4 hrs. mt djsplace to 1100' WOC 4 hr	
proposed completion or 1 7/16/14 Notify OCD of MIRU. RIH tag 7/17/14 Attempt to load well. Did not 7/18/14 RIH tag TOC @ 2607' load w 7/21/14 POH perf @ 2454' sqz 70 x cl 7/22/14 RIH tag TOC @ 1995' POH p 7/23/14 Sqz 75 class "c" cmt from 250	recompletion. CIBP @ 3425'. load. Spot 140 x class "c" cmt @ ell pressure test casing to 1000 ass "c" cmt displace to 2050' W erf @ 1160' sqz 45 x class "c" c ' to surf. Cmt was circ behind 6	ያ bsi ok. /OC 4 hrs. mt djsplace to 1100' WOC 4 hr	
proposed completion or 1 7/16/14 Notify OCD of MIRU. RIH tag 7/17/14 Attempt to load well. Did not 7/18/14 RIH tag TOC @ 2607' load w 7/21/14 POH perf @ 2454' sqz 70 x cl 7/22/14 RIH tag TOC @ 1995' POH p 7/23/14 Sqz 75 class "c" cmt from 250	recompletion. CIBP @ 3425'. load. Spot 140 x class "c" cmt @ ell pressure test casing to 1000 ass "c" cmt displace to 2050' W erf @ 1160' sqz 45 x class "c" c ' to surf. Cmt was circ behind 6	ያ bsi ok. /OC 4 hrs. mt djsplace to 1100' WOC 4 hr	
proposed completion or 1 7/16/14 Notify OCD of MIRU. RIH tag 7/17/14 Attempt to load well. Did not 7/18/14 RIH tag TOC @ 2607' load w 7/21/14 POH perf @ 2454' sqz 70 x cl 7/22/14 RIH tag TOC @ 1995' POH p 7/23/14 Sqz 75 class "c" cmt from 250	recompletion. CIBP @ 3425'. load. Spot 140 x class "c" cmt @ ell pressure test casing to 1000 ass "c" cmt displace to 2050' W erf @ 1160' sqz 45 x class "c" c ' to surf. Cmt was circ behind 6	ያ bsi ok. /OC 4 hrs. mt djsplace to 1100' WOC 4 hr	
proposed completion or 1 7/16/14 Notify OCD of MIRU. RIH tag 7/17/14 Attempt to load well. Did not 7/18/14 RIH tag TOC @ 2607' load w 7/21/14 POH perf @ 2454' sqz 70 x cl 7/22/14 RIH tag TOC @ 1995' POH p 7/23/14 Sqz 75 class "c" cmt from 250	recompletion. CIBP @ 3425'. load. Spot 140 x class "c" cmt @ ell pressure test casing to 1000 ass "c" cmt displace to 2050' W erf @ 1160' sqz 45 x class "c" c ' to surf. Cmt was circ behind 6	ያ bsi ok. /OC 4 hrs. mt djsplace to 1100' WOC 4 hr	
proposed completion or 1 7/16/14 Notify OCD of MIRU. RIH tag 7/17/14 Attempt to load well. Did not 7/18/14 RIH tag TOC @ 2607' load we 7/21/14 POH perf @ 2454' sqz 70 x cl 7/22/14 RIH tag TOC @ 1995' POH p 7/23/14 Sqz 75 class "c" cmt from 250 Install dryhole marker. P&A co	recompletion. CIBP @ 3425'. load. Spot 140 x class "c" cmt @ ell pressure test casing to 1000 ⁰ ass "c" cmt displace to 2050' W erf @ 1160' sqz 45 x class "c" c ' to surf. Cmt was circ behind 6 ompleted.	Psi ok. OC 4 hrs. mt displace to 1100' WOC 4 hr 5/8 casing. RD P&A equip, cut	
proposed completion or 1 7/16/14 Notify OCD of MIRU. RIH tag 7/17/14 Attempt to load well. Did not 7/18/14 RIH tag TOC @ 2607' load we 7/21/14 POH perf @ 2454' sqz 70 x cl 7/22/14 RIH tag TOC @ 1995' POH perf 7/23/14 Sqz 75 class "c" cmt from 250	recompletion. CIBP @ 3425'. load. Spot 140 x class "c" cmt @ ell pressure test casing to 1000 ⁰ ass "c" cmt displace to 2050' W erf @ 1160' sqz 45 x class "c" c ' to surf. Cmt was circ behind 6 ompleted.	ያ bsi ok. /OC 4 hrs. mt djsplace to 1100' WOC 4 hr	
proposed completion or 1 7/16/14 Notify OCD of MIRU. RIH tag 7/17/14 Attempt to load well. Did not 7/18/14 RIH tag TOC @ 2607' load we 7/21/14 POH perf @ 2454' sqz 70 x cl 7/22/14 RIH tag TOC @ 1995' POH p 7/23/14 Sqz 75 class "c" cmt from 250 Install dryhole marker. P&A co	recompletion. CIBP @ 3425'. load. Spot 140 x class "c" cmt @ ell pressure test casing to 1000 ⁰ ass "c" cmt displace to 2050' W erf @ 1160' sqz 45 x class "c" c ' to surf. Cmt was circ behind 6 ompleted.	Psi ok. OC 4 hrs. mt displace to 1100' WOC 4 hr 5/8 casing. RD P&A equip, cut	
proposed completion or 1 7/16/14 Notify OCD of MIRU. RIH tag 7/17/14 Attempt to load well. Did not 7/18/14 RIH tag TOC @ 2607' load we 7/21/14 POH perf @ 2454' sqz 70 x cl 7/22/14 RIH tag TOC @ 1995' POH p 7/23/14 Sqz 75 class "c" cmt from 250 Install dryhole marker. P&A co	recompletion. CIBP @ 3425'. load. Spot 140 x class "c" cmt @ ell pressure test casing to 1000 ass "c" cmt displace to 2050' W erf @ 1160' sqz 45 x class "c" c ' to surf. Cmt was circ behind 6 ompleted. Rig	Psi ok. OC 4 hrs. mt displace to 1100' WOC 4 hr 5/8 casing. RD P&A equip, cut Release Date:	t anchors, wellhead and cleaned location.
proposed completion or 1 7/16/14 Notify OCD of MIRU. RIH tag 7/17/14 Attempt to load well. Did not 7/18/14 RIH tag TOC @ 2607' load we 7/21/14 POH perf @ 2454' sqz 70 x cl 7/22/14 RIH tag TOC @ 1995' POH p 7/23/14 Sqz 75 class "c" cmt from 250 Install dryhole marker. P&A co	recompletion. CIBP @ 3425'. load. Spot 140 x class "c" cmt @ ell pressure test casing to 1000 ass "c" cmt displace to 2050' W erf @ 1160' sqz 45 x class "c" c ' to surf. Cmt was circ behind 6 ompleted. Rig	Psi ok. OC 4 hrs. mt displace to 1100' WOC 4 hr 5/8 casing. RD P&A equip, cut Release Date:	t anchors, wellhead and cleaned location.
proposed completion or 1 7/16/14 Notify OCD of MIRU. RIH tag 7/17/14 Attempt to load well. Did not 7/18/14 RIH tag TOC @ 2607' load we 7/21/14 POH perf @ 2454' sqz 70 x cl 7/22/14 RIH tag TOC @ 1995' POH p 7/23/14 Sqz 75 class "c" cmt from 250 Install dryhole marker. P&A co	recompletion. CIBP @ 3425'. load. Spot 140 x class "c" cmt @ ell pressure test casing to 1000 ass "c" cmt displace to 2050' W erf @ 1160' sqz 45 x class "c" c ' to surf. Cmt was circ behind 6 ompleted. Rig	Psi ok. OC 4 hrs. mt displace to 1100' WOC 4 hr 5/8 casing. RD P&A equip, cut Release Date:	t anchors, wellhead and cleaned location.
Proposed completion or 1 7/16/14 Notify OCD of MIRU. RIH tag 7/17/14 Attempt to load well. Did not 7/18/14 RIH tag TOC @ 2607' load we 7/21/14 POH perf @ 2454' sqz 70 x cl 7/22/14 RIH tag TOC @ 1995' POH p 7/23/14 Sqz 75 class "c" cmt from 250 Install dryhole marker. P&A co Install dryhole marker. P&A co Spud Date:	recompletion. CIBP @ 3425'. load. Spot 140 x class "c" cmt @ ell pressure test casing to 1000' ass "c" cmt displace to 2050' W erf @ 1160' sqz 45 x class "c" c ' to surf. Cmt was circ behind 6 ompleted. Rig 1 on above is true and completed TIT	Psi ok. OC 4 hrs. mt displace to 1100' WOC 4 hr 5/8 casing. RD P&A equip, cut Release Date:	t anchors, wellhead and cleaned location.
proposed completion or 1 7/16/14 Notify OCD of MIRU. RIH tag 7/17/14 Attempt to load well. Did not 7/18/14 RIH tag TOC @ 2607' load we 7/21/14 POH perf @ 2454' sqz 70 x cl 7/22/14 RIH tag TOC @ 1995' POH p 7/23/14 Sqz 75 class "c" cmt from 250 Install dryhole marker. P&A cd Spud Date: I hereby certify that the information SIGNATURE Type or print name	recompletion. CIBP @ 3425'. load. Spot 140 x class "c" cmt @ ell pressure test casing to 1000' ass "c" cmt displace to 2050' W erf @ 1160' sqz 45 x class "c" c ' to surf. Cmt was circ behind 6 ompleted. Rig 1 on above is true and completed TIT	Psi ok. OC 4 hrs. mt displace to 1100' WOC 4 hr 5/8 casing. RD P&A equip, cut Release Date:	t anchors, wellhead and cleaned location.
Proposed completion or 1 7/16/14 Notify OCD of MIRU. RIH tag 7/17/14 Attempt to load well. Did not 7/18/14 RIH tag TOC @ 2607' load we 7/21/14 POH perf @ 2454' sqz 70 x cl 7/22/14 RIH tag TOC @ 1995' POH p 7/23/14 Sqz 75 class "c" cmt from 250 Install dryhole marker. P&A co Install dryhole marker. P&A co Spud Date:	recompletion. CIBP @ 3425'. load. Spot 140 x class "c" cmt @ ell pressure test casing to 1000' ass "c" cmt displace to 2050' W erf @ 1160' sqz 45 x class "c" c ' to surf. Cmt was circ behind 6 ompleted. Rig on above is true and completed TIT E-m	Psi ok. OC 4 hrs. mt displace to 1100' WOC 4 hr 5/8 casing. RD P&A equip, cut Release Date: te to the best of my knowle LEAgent hail address: sunsetwellservice	t anchors, wellhead and cleaned location.
proposed completion or 17716/14 Notify OCD of MIRU. RIH tag 7/17/14 Attempt to load well. Did not 7/18/14 RIH tag TOC @ 2607' load we 7/21/14 POH perf @ 2454' sqz 70 x cl 7/22/14 RIH tag TOC @ 1995' POH p 7/23/14 Sqz 75 class "c" cmt from 250 Install dryhole marker. P&A cc Install dryhole marker. P&A cc Spud Date: I hereby certify that the information SIGNATURE Type or print name For State Use Only APPROVED BY:	recompletion. CIBP @ 3425'. load. Spot 140 x class "c" cmt @ ell pressure test casing to 1000' ass "c" cmt displace to 2050' W erf @ 1160' sqz 45 x class "c" c ' to surf. Cmt was circ behind 6 ompleted. Rig on above is true and completed TIT E-m	Psi ok. OC 4 hrs. mt displace to 1100' WOC 4 hr 5/8 casing. RD P&A equip, cut Release Date: te to the best of my knowle LEAgent hail address: sunsetwellservice	t anchors, wellhead and cleaned location.
proposed completion or 17716/14 Notify OCD of MIRU. RIH tag 7/17/14 Attempt to load well. Did not 7/18/14 RIH tag TOC @ 2607' load we 7/21/14 POH perf @ 2454' sqz 70 x cl 7/22/14 RIH tag TOC @ 1995' POH p 7/23/14 Sqz 75 class "c" cmt from 250 Install dryhole marker. P&A cc Install dryhole marker. P&A cc Spud Date: I hereby certify that the information SIGNATURE Type or print name For State Use Only APPROVED BY: Conditions of Approval (if any):	recompletion. CIBP @ 3425'. load. Spot 140 x class "c" cmt @ ell pressure test casing to 1000' ass "c" cmt displace to 2050' W erf @ 1160' sqz 45 x class "c" c ' to surf. Cmt was circ behind 6 completed. Rig 1 on above is true and completed TIT E-m MADUM TITI	Psi ok. OC 4 hrs. mt displace to 1100' WOC 4 hr 5/8 casing. RD P&A equip, cut Release Date: te to the best of my knowle LEAgent hail address: sunsetwellservice	t anchors, wellhead and cleaned location. dge and belief. <u>DATE</u> 7/23/14 <u>PHONE</u> : 432-561-8600 <u>PHONE</u> : 432-561-8600 <u>ATE</u> 8 5 2014
proposed completion or 1 7/16/14 Notify OCD of MIRU. RIH tag 7/17/14 Attempt to load well. Did not 7/18/14 RIH tag TOC @ 2607' load we 7/18/14 RIH tag TOC @ 2607' load we 7/21/14 POH perf @ 2454' sqz 70 x cl 7/22/14 RIH tag TOC @ 1995' POH p 7/23/14 Sqz 75 class "c" cmt from 250 Install dryhole marker. P&A cd Spud Date: I hereby certify that the information SIGNATURE Jmmy Bagle For State Use Only APPROVED BY:	recompletion. CIBP @ 3425'. load. Spot 140 x class "c" cmt @ ell pressure test casing to 1000' ass "c" cmt displace to 2050' W erf @ 1160' sqz 45 x class "c" c ' to surf. Cmt was circ behind 6 completed. Rig 1 on above is true and completed TIT E-m MADUM TITI	psi ok. OC 4 hrs. mt displace to 1100' WOC 4 hr 5/8 casing. RD P&A equip, cut Release Date: te to the best of my knowle LEAgent ail address: sunsetwellservice	t anchors, wellhead and cleaned location.

.