State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

David Martin

Cabinet Secretary

Brett F. Woods, Ph.D. Deputy Cabinet Secretary Jami Bailey, Division Director Oil Conservation Division



Response Required - Deadline Enclosed

Underground Injection Control Program "Protecting Our Underground Sources of Drinking Water"

14-Aug-14

-MAR-OIL-&-GAS-CORP-PO BOX 5155 SANTA FE, NM 87502-5155

LETTER-OF-VIOLATION-and-SHUT-IN-DIRECTIVE----

Failed-Mechanical-Integrity-Test-

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

EUMONT HARDY UNIT No.023

Active Injection - (All Types)

30-025-06216-00-00 P-36-20S-37E

Test Date:

8/14/2014

Permitted Injection PSI:

Actual PSI:

Test Reason:

Annual IMIT

Test Result:

Repair Due:

11/17/2014

11/17/2014

Test Type:

Std. Annulus Pres. Test

FAIL TYPE: Other Internal Failure

Expired TA Injection - (All Types)

Comments on MIT:

FAIL CAUSE:

Rule 19.15.26.11. Well would not pressure up. Pumped 12+ bbls and would not load up.

EUMONT HARDY UNIT No.019

30-025-06227-00-00 L-36-20S-37E

Test Date:

8/14/2014

Permitted Injection PSI:

Actual PSI:

Test Reason:

TA Status Test

Test Result:

Repair Due:

Test Type:

Std. Annulus Pres. Test

FAIL TYPE: Other Internal Failure

FAIL CAUSE:

Comments on MIT: Rule 19.15.24.14. Failed T/A Test. Pressured up to 580#, dropped to 480 # in 30 minutes.

AUG 1-5 20141

THE RESIDENCE OF THE PROPERTY				THE RESIDENCE AND THE PROPERTY OF THE PROPERTY
Sincerely,	200			
Sta	orge Down			
Hobbs OCD Distr	Ici Office			
Information in Detail any Comments are	sts are performed prior to initial inject Section comes directly from field insp not to be interpreted as a diagnosis of the nature of the actual failure. * Sig	pector data entries - not all bla f the condition of the wellbore	nks will contain data. "Failure . Additional testing should be	Type" and "Failure Cause" conducted by the operator t
nga gapamanya nggap ^{ala} naman 1964 na mananangapangapangapangapa sinias naga dana 1984.		adada sindanusan sun, dalamas erradi hillistikliklingir —ni dirist Graftis—res bibelia ashqa arra		

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



015H14150977

\$0.48

S0.48

08/14/14

Mailed From88240

MAR OIL & GAS CORP. PO BOX 5155 SANTA FE, N.M. 87502