

Tina Huerta

From: Tina Huerta
Sent: Friday, July 11, 2014 4:09 PM
To: Sonnamaker, William, EMNRD
Cc: Donna Mull (donna.mull@state.nm.us)
Subject: Jackson Federal SWD #1 - Retest
Attachments: MX-5111N_20140711_171625.pdf

HOBBS OCD

AUG 07 2014

RECEIVED

Good afternoon Mr. Sonnamaker,
Here is the MIT chart that you requested a retest as noted below. Please let me know if there is anything else you need from me. Thank you.


*Tina Huerta
Yates Petroleum Corporation
Regulatory Reporting Supervisor
tinah@yatespetroleum.com
575-748-4168*

Tina,

Bill Sonnamaker also looked at the MIT chart that the BLM approved for the Jackson Federal SWD #1, API # 30-025-28242 and stated it is the wrong chart. Yates needs to retest this well and use the correct chart. Chart & Spring should be 1000#, 1 hour clock, and a 35 min. test. Please let your field personal know this and to set up a re-test. Please let Bill know 24 hours before testing. Bill's number is (575) 393-6161 Ex 114.

Thanks Donna

AUG 18 2014



FOR RECORD ONLY

BS 8/8/2014