

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-09432
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. 96141
7. Lease Name or Unit Agreement Name George Etz
8. Well Number 3
9. OGRID Number 142624
10. Pool name or Wildcat 7 Rivers

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other ☐ Disposal well ☐

2. Name of Operator
Roca Production, Inc.

3. Address of Operator
P. O. Box 10139 Midland, Texas 79702

4. Well Location
Unit Letter N : 330 feet from the South line and 1650 feet from the West line
Section 27 Township 23S Range 36E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

E-PERMITTING
P&A NR P&A P&A R
INT TO P&A
CSNG CHG Loc
TA RBDMS CHART

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

7/11/14 POOH w/2 7/8" tbg & 5" pkr. Set 5" CIBP @ 3307' on WL. GIH w/tbg to 3307', circ 5" csg w/100 bbls 10# brine water w/25 sxs gel. Pump plug #1, 30 sxs Cl C cmt at 3307'. Pull 40 jts. WOC. Tag cmt plug at 2887'. Pull tbg to 1318'. Pump plug #2, 35 sxs Cl C cmt at 1318'. Pull 42 jts tbg. WOC. Tag cmt at 1035'. Ran 5" pkr. Found hole in csg from 65'-125'. Pull tbg & pkr. RIH w/tbg to 125'. Pump plug #3, 10 sxs Cl C cmt at 125'. Pull tbg. Hook onto 5" csg & squeeze 20 sxs Cl C cmt out 8 5/8" csg. Cut off wellhead. Cut off deadmen (anchors). Well P & A 7/15/14.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Steve Douglas TITLE Engineer DATE 8/14/14

Type or print name Steve Douglas E-mail address: steve@ogxresources.com PHONE: 432-685-1287

For State Use Only

APPROVED BY: Mary Brown TITLE Dist Supervisor DATE 8/18/2014

Conditions of Approval (if any)

AUG 18 2014