Form 3160-5 (March 2012)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

FORM APPROVED OMB No. 1004-0137

Expires: October 31, 2014

5. Lease Serial No. NM:66486

6. If Indian, Allottee or Tribe Name

abandoned well. Use Form 3160-3 (APD) for such propesa (SD)						
SUBMIT IN TRIPLICATE – Other instructions on page 2. 1. Type of Well AUG 2 5 2014				7. If Unit of CA/Agreement, Name and/or No. NM 82030 Bilberry 14 Fed Com		
1. Type of Well			2 5014			
Oil Well Gas W	AU	дос		8. Well Name and No. Bilberry 14 Fed Com #1		
2. Name of Operator Harvard Petroleum Company, LLC	•	REC	EIVED	9. API Well No. 30-041-20843	_	
3a. Address PO Box 936, Roswell, NM 88202-0936	3b. Phone No. (include area		10. Field and Pool or Exploratory Area			
575-623-1581					,	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 990' FNL & 990' FEL, Sec 14-T8S-R37E				11. County or Parish, State Roosevelt Co, New Mexico		
12. CHEC	CK THE APPROPRIATE BO	OX(ES) TO INDICATE NAT	URE OF NOTI	CE; REPORT OR OTH	ER DATA	
TYPE OF SUBMISSION TYPE OF AC				LION	· · · · · · · · · · · · · · · · · · ·	
Votice of Intent	Acidize Deepen Production (Start/Re		luction (Start/Resume)	Resume) Water Shut-Off		
Notice of Intent	Alter Casing	Fracture Treat	_	lamation	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Reco	omplete	Other	
Subsequent Report	Change Plans	✓ Plug and Abandon	Tem	porarily Abandon		_
Final Abandonment Notice	Convert to Injection	Plug Back	☐ Wat	er Disposal		
Attach the Bond under which the violation completion of the involve testing has been completed. Final determined that the site is ready for	ed operations. If the operation Abandonment Notices must	on results in a multiple comp	letion or recomp	pletion in a new interval	, a Form 3160-4 must be fi	led once
1. RU Pulling unit. Pull rods and pur	np, if any, and LD same.	to area of the second				
2. Install BOP. Pull and visual inspe	ct tubing.				A 6	
3. TIH w bit and scraper to 100' abo	ve the perfs (4452-4523').			4	EDIE	
4. TIH with CIBP and set same 90' a	above the perfs. TAG sam	e.				
5. Pull above the CIBP and circulate	hole with 10# gelled brine	e and spot 25 sxs cement	olug on top of	CIBP.		
6. If necessary, perf and squeeze 25	5 sxs cement at top of the	salt (circulation show cem	ent above salt	top). BLM directive ne	eded.	
7. Perf squeeze hole at base of 8 5/	'8" (365') and squeeze 35	sxs cement. WOC and TA	3 same.			
8. Set 10 sxs surface plug. Cut off w	rell head. Install DH marke	er. RD and cut off anchors.	Clean location	n to the satisfaction of	surface owner and BLM	l.
14. I hereby certify that the foregoing is to	rue and correct. Name (Printe	d/Typed)		,		
M.Y. Merchant		Title Ager	ıt		. Tr.	
Signature LACKAT	her I	Date 07/0	7/2014	DENIED: OF	SUBMIRAMS REDIAGRAMS	
and the second second second	THIŞ SPACE	FOR FEDERAL OR	<u></u>	IS REQUELLED	<u>.</u>	
Approved by Conditions of approval, if any, are attached that the applicant holds legal or equitable tentitle the applicant to conduct operations Title 18 U.S.C. Section 1001 and Title 43 firstitious or fraudulent statements or representations.	Assis Land	Date 07/0 FOR FEDERAL OR Can't Field Manage S Arich Internals s not warrant or certains t lease which would	OPERATOR	AFTER Mart	AUG Date	21 201
Conditions of approval, if any, are attached that the applicant holds legal or equitable tentitle the applicant to conduct operations	1.' Approval of this notice does itle to those rights in the subje- thereon.	s not warrant of certification between the second s	, -	Roswell	Field Office	
Title 18 U.S.C. Section 1001 and Title 43	U.S.C. Section 1212, make it a	a crime for any person kr.	aufully !	to make to any departmen	nt or agency of the United Sta	ates any false.

(Instructions on page 2)

MAB/02/8/25/8014

AUG 2 5 2014

f