Submit I Copy To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources		Form C-103 October 13, 2009	
District I 1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	15, 2007
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE STATE	
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
87505			11859	
(DO NOT USE THIS FORM FOR PROPOS	CES AND REPORTS ON WEL SALS TO DRILL OR TO DEEPEN OR	PLUG BAKKANDO A	7. Lease Name or Unit Agrees	ment Name
DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	CATION FOR PERMIT" (FORM C-101)	OBBENEH T	State SPX Charm	
	Gas Well 🔲 Other	2 4 301h	8. Well Number 4	
2. Name of Operator	•	SEP 19 LOW	9. OGRID Number	
Finley Resources Inc 3. Address of Operator			180387 10. Pool name or Wildcat	
1308 Lake Street Fort Wo	rth, TX 76102	RECEIVED		
4. Well Location				
Unit Letter G:		erth line and		st line
Section 33	Township 20S 11. Elevation (Show whether L	Range 36E		Lea /
	11. Dievation (Show whether L	N, KKD, KI, UK, etc.,		
12. Check A	Appropriate Box to Indicate	Nature of Notice,	Report or Other Data	
NOTICE OF IN	TENTION TO:	SUB	SEQUENT_REPORT OF	:
PERFORM REMEDIAL WORK	PLUG AND ABANDON D	REMEDIAL WOR	<u>—</u> -	=
TEMPORARILY ABANDON				
DOWNHOLE COMMINGLE	MOETH LE COMPL	CASING/CLIVILIN	1 300	
OTHER		OTHER		
OTHER: 13. Describe proposed or compl	eted operations. (Clearly state a	OTHER:	d give pertinent dates, including	estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.				
) Extered well to return to production and tournor cog lear				
DESteved well to return to production and found as leak Planto PAA 2) RU. Set CIBP @ 3780, spot 25 sxs cont, airc hole w/m				
2) (cd. 5) (cd				
1) Csg leak & 1,222. 392 mg 40 5x3 cmt, lag				
3) Csg leak @ 1,222! Sqz w/ 40 sxs cmt, tag at 1,122 (4) Perf + sqz @ 250' w/ 60sxs cmt + circ to surface. > SPOT 25 SXS CMT 1122! - 873'. WOC & TAG. (COVERS 1/2005) CSG LEAF)				
100 100 100 100 100 COVERS 2005				
→ 5HU 255XS	SCMI NEL	013.	C. C.	GLEAF)
Spud Date:	Rig Release	Date:		
I hereby certify that the information a	above is true and complete to the	best of my knowledge	e and belief.	
$\Lambda \cap \Lambda$	· Au		į	! ;
SIGNATURE / DULL	TITLE Reg	ulatory Analyst	DATE 9/	15/14
Type or print name April Wilker	rson E-mail addr	ess: awilkerson@finley	yresources.com PHONE: 817-2	31-8735
For State Use Quly				
APPROVED BY: Wally Down FITLE Dist Supervisor DATE 9/18/2014				
Conditions of Approval (if any):				


OIL CONSERVATION DIVISION - Hobbs office **Must Be Notified 24 hours prior** to the beginning of Plugging Operations.

SEP 1 9 2014

for

State SPX Charm - 4


API # 30 025 04389 Eumont Y7RQ Field 1650' FSL 1650' FEL Sec 33G Completion Date: 3/1956



TD: 3895'

State SPX Charm - 4

API # 30 025 04389 Eumont Y7RQ Field 1650' FSL 1650' FEL Sec 33G Completion Date: 3/1956



Finley Resources, Inc

State SPX Charm #4

Lea County, NM

API# 30-025-04389

Equipment and Design:

Finley's agent will use a "Closed Loop" system in the workover of this well. The following equipment will be on location: (1) 250 bbl Steel pit

Operations and Maintenance:

During each day of operation, the rig crew will inspect and monitor the fluids contained within the steel tank and visually monitor any release that may occur. Should a release, spill or leak occur, the NMOCD District 1 office in Hobbs, NM (575 393-6161) will be notified as required in NMOCD rule 19.15.29.8.

Closure:

After workover operations, fluids and solids will be hauled and disposed at New Mexico OCD approved disposal facility