Submit 1 Copy To Appropriate District State of New Mexico	Form C-103						
District 1 – (575) 393-6161 Energy, Minerals and Natural Resources	Revised August 1, 2011						
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	WELL API NO. 30-025-28265- 37409						
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease						
District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 1000 Rio Brazos Rd., Aztec, NM 87410	STATE S FEE						
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.						
87505							
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR BACK TO A	7. Lease Name or Unit Agreement Name						
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORMEDIP) FOR SUCH	North Hobbs G/SA						
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other SEP 17 2014	8. Well Number						
SEP I SEP I	29-635						
2. Name of Operator Occidental Permian Ltd.	9. OGRID Number: 157984						
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)						
HCR 1 Box 90 Denver City, TX 79323							
4. Well Location							
Unit Letter1_:1665feet from theSouth line and1240_							
Section 29 Township 18S Range 38							
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3659' KB							
した。****業大学を見た理想が発展をおかったができたがです。 フロフィーズン							
12. Check Appropriate Box to Indicate Nature of Notice	Report or Other Data						
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DE	RK						
	—						
OTHER: Coiled Tubing Cleanout OTHER:							
13. Describe proposed or completed operations. (Clearly state all pertinent details, and							
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.	ompletions: Attach wellbore diagram of						
proposed completion of recompletion.							
 Rig up Coiling Tubing Unit with Perf Clean Tool TIH to 4275' 							
 2) TIH to 4275' 3) Pull up with perf clean tool to 4050'' 							
4) Run perf clean tool with water across perforations 4091-4241'							
5) Close backside and repeat perf wash from 4091-4241' with 2500 gals 15% NEFE	HCL During this procedure and the						
6) Pump 10 bbls gel sweep to bring fines to the surface7) POOH with CT and RD Coil Tubing Unit	During this procedure we plan to use the closed-loop system with a steel						
8) Return well to injection	tank and haul contents to the required						
	disposal per ODC Rule 19.15.17						
Spud Date: Rig Release Date:	<u> </u>						
I hereby certify that the information above is true and complete to the best of my knowled	ge and belief.						
()							
SIGNATURE	DATE 9-15-14						
$\mathcal{T}^{$							
Type or print nameRobbie Underhill E-mail address: <u>Robert_Underhill@oxy.</u>	<u>,com</u> PHONE: <u>806-592-6287</u>						
	i alintaul						
APPROVED BY: Majer Drown BITLE Dist. Supervisor DATE 9/18/2014							
Conditions of Approval (if any):							
	SEP 19 2014						
	- 01						

C	E	P	1	9	- 9	N	1/
J	L.		_ 1	U	۲.	U	1.

M