Submit I Copy To Appropriate District Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resources	October 13, 2009
1625 N. French Dr., Hobbs, NM 88240 District II	HOBBS OCD	WELL API NO. 30-025-10550
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410 SEP 2 4 2014 Santa Fe, NM 87505 District IV		STATE FEE S
District IV	Ser 2 4 2014 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		307841
SUNDRY NOTICES AMBIREPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		7. Lease Name or Unit Agreement Name
PROPOSALS.)		SKELLY PENROSE B UNIT
1. Type of Well: Oil Well Gas Well Other TA'd Injection		8. Well Number 001
2. Name of Operator PROVIDENCE ENERGY SERVICES, INC. dba KELTON OPERATING		9. OGRID Number 012444
3. Address of Operator		10. Pool name or Wildcat
P.O. BOX 928, ANDREWS, TEX	AS 79714-0928	LANGLIE MATTIX (37240)
4. Well Location 1659		
Unit Letter B	: 990 feet from the NORTH line and 66	
Section 32	Township 22S Range 37E	NMPM LEA County
	11. Elevation (Show whether DR, RKB, RT, GR, etc.	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A		
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEME	NT JOB 🔲
DOWNHOLE COMMINGLE		
OTHER:	OTHER: Set C	IBP - TA
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
09/09/2014	T/A STATU	
	L	
 Moved in and rigged up pulling unit. Unset AD-1 packer and pull out of hole. NO CHART—		
2. Unset AD-1 packer and pull out of hole. — NO CHAKI — 3. Picked up and run 4 ½" CIBP and set at 3486'.		
4. Laid down tubing and remove from location, ND BOP, NU well head. Load hole. Will file paper work to P&A well.		
,		
STEP#	3 SETTING CIBP (@ 3486 &	
	0 3401	Accepted for Record Only
	@ 5406 E	MXB
		9/24/2014
Spud Date:	Rig Release Date:	7/24/2017
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE	TITLE PRESIDENT	DATE Sept. 22, 2014
Type or print name C. Dale Kelton E-mail address: providenceenergy@suddenlink.net PHONE: 432-661-1364		
Type or print name <u>C. Dale Kelton</u> E-mail address: <u>providenceenergy@suddenlink.net</u> PHONE: 432-661-1364 For State Use Only		
APPROVED BY: Conditions of Approval (if any):	TITLE	DATE
(Onditions of Approval (if any):		

Kelton Operating Corporation - WELL DIAGRAM

