

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-041-20809
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name STOLTENBERG
8. Well Number #1
9. OGRID Number 263940
10. Pool name or Wildcat TULE MONTOYA/PENN
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4394'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other Plug and Abandon

2. Name of Operator
SOVEREIGN EAGLE LLC

3. Address of Operator
PO BOX 1030 ROSWELL NM 88202

4. Well Location

Unit Letter F: 1650 feet from the NORTH line and 2310 feet from the WEST line
Section 26 Township 2S Range 29E NMPM ROOSEVELT County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4394'

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

PERF E-PERMITTING

TEMP P&A NR

PULL INT TO P&A

DOW CSNG

CLOS TA

OTHE

P&A R

COMP

CHG Loc

RBDMS CHART

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS ☐

CASING/CEMENT JOB ☐

ALTERING CASING ☐

P AND A ☒

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

10/13/2014 Re-entered well and drill out surface plugs and plug inside 8 5/8" casing shoe. Could not get past hole caving in at 2250'.

10/20/14 Plugged and abandoned by;

Set plug #1 with 100 sx across 8 5/8" casing shoe at 2128', end of tubing at 2169'.

Set plug #2 with 50 sx with end of tubing at 395' across the 13 3/8" casing shoe at 331'.

Set 10 sx plug at surface.

Clean location and fill cellar. Dry hole marker will be placed after Stoltenberg #2 is drilled and completed on same location.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Paul Ragsdale

TITLE Operations Manager

DATE 10/21/2014

Type or print name Paul Ragsdale

E-mail address: pragsdale@stratanm.com

PHONE: 575-626-7903

For State Use Only

APPROVED BY:

Bil Samamoh

TITLE Staff Manager

DATE 11/4/2014

Conditions of Approval (if any):

FOR RECORD ONLY

NOV 05 2014

Sonnamaker, William, EMNRD

From: Paul Ragsdale <pragsdale@stratanm.com>
Sent: Tuesday, October 21, 2014 9:22 AM
To: Sonnamaker, William, EMNRD
Subject: Stoltenberg P & A
Attachments: StoltenbergP&A.pdf

Bill, please find the C 103 for plugging the Stoltenberg attached. We will send a hard copy also.

We have decided since the re-entry was unsuccessful, that we will drill a new well on this same location by moving the drill hole 50' west of this well. I will be sending a new APD sometime this afternoon. Silver Oak has a rig available that can move as soon as we get the APD approved.

Thanks,
Paul

Paul Ragsdale
Strata Production Company
Operations Manager

(575) 622-1127 ext 18 Work
(575) 626-7903 Mobile
pragsdale@stratanm.com
PO Drawer 1030
Roswell NM 88202

Sonnemaker, William, EMNRD

From: Paul Ragsdale <pragsdale@stratanm.com>
Sent: Friday, October 17, 2014 1:06 PM
To: Sonnemaker, William, EMNRD
Subject: Stoltenberg P & A
Attachments: 10172014115609-DOC101714.pdf

Bill, attached is the C-103 for the abandonment of the Stoltenberg. I noticed that they set another plug at 1100' when the well was plugged previously. I did not include that plug but we can add it if it is required.

Tentative plans is to lay drill pipe down on Saturday and then pump cement of Sunday.

Thanks,

Paul

Paul Ragsdale
Strata Production Company
Operations Manager

(575) 622-1127 ext 18 Work
(575) 626-7903 Mobile
pragsdale@stratanm.com
PO Drawer 1030
Roswell NM 88202