Submit 3 Copies To Appropriate District	State of New Me			Form C-103
Office Ener	rgy, Minerals and Natu			June 19, 2008
1625 N. French Dr., Hobbs, NM 87240 District II	II. COMERNA ETON	HOBBS OCD	WELL API NO. 30-025-4	1551
1301 W. Grand Ave., Artesia, NM 88210	IL CONSERVATION		5 Indicate Type of I	
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fra Santa Fe, NM 8	ncis Prov 1 2 2014	STATE	FEE X
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	,	RECEIVED	6. State Oil & Gas Le	ease No.
SUNDRY NOTICES AN	ID REPORTS ON WEI		7. Lease Name or Un	it Agreement Name:
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				
1. Type of Well:			North Hobbs G/	
Oil Well X Gas Well Other			947	
2. Name of Operator Occidental Permian Ltd.			9. OGRID Number 157984	1
3. Address of Operator			10. Pool name or Wil	
P.O. Box 4294, Houston, TX 772	<u>110-4294</u>		Hobbs: Graybur	g-San Andres
1. Well Location				
Unit Letter A : 278	feet from theNor	th line and	feet from the	he <u>East</u> line
Section 19		Range 38-E		County Lea
11. E	Elevation (Show whether 3661	<i>DR, RKB, RT,  GR, et</i> L.6'  GR	c.)	
12. Check Appropr	riate Box to Indicate	Nature of Notice, l	Report, or Other Da	ta .
NOTICE OF INTENTION TO: SUB			SEQUENT REPO	ADT OE:
·			•	
ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			$\mathbf{X}$	ALTERING CASING
EMPORARILY ABANDON   CHAI	NGE PLANS	COMMENCE DRILLI	NG OPNS.	P AND A
ULL OR ALTER CASING	TIPLE COMPL	CASING/CEMENT J	ОВ 🗆	
OWNHOLE COMMINGLE				
)THER:		OTHER:		
13. Describe proposed or completed operat of starting any proposed work). SEE R or recompletion.	` .	, ,	•	· ·
		· <u>·</u> .		
MI x RU pulling unit. ND WH :				
tubing. RD line spooler. Laid down ESP x found lead cable splice was bad. RIH with workstring x $6-1/8$ " bit x tag at 4626'. Pull up above perfs. Kill well x wait on ESP equipment to be delivered.				
RU line spooler x RBIH w/Centrilift ESP equipment on 131 jts. 2-7/8" production tubing. Landed hanger x RD spooler. ND BOP x NU WH x test tree to 5000 psi. RD x MO x clean location.				
hanger x RD spooler. ND BOP	x NU WH x test tree	to 5000 psi. RD x	MO x clean location	1.
				•
10 (00 (14 (10)))		10.4	00 (4.4. (DDDU)	]
Spud Date: 10/23/14 (RUPU)	Rig Relea	ase Date: 107	29/14 (RDPU)	
hereby certify that the information above is	true and complete to the	best of my knowledg	e and belief.	
IGNATURE Mark Standard Compliance Analyst DATE 11/7/14				
ype or print name <u>Mark Stephens</u> E-mail address: <u>PHONE (713) 366-5158</u>				
for State Use Only \\\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \				
PPROVED BY Conditions of Approval (if any):	Hown TIT	rle Dest S	mpenió de DA	те <u>11/13/2014                                    </u>
V				