State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

David Martin

Cabinet Secretary

Brett F. Woods, Ph.D. Deputy Cabinet Secretary

Jami Bailey, Division Director
Oil Conservation Division



Response Required - Deadline Enclosed

Field Inspection Program
"Preserving the Integrity of Our Environment"

19-Nov-14

RAM ENERGY LLC 5100 EAST SKELLY DRIVE SUITE 600 TULSA OK 74135

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

NEW_MEXICO_A_STATE_No.001_ P-30-15S-33E--30-025-08332-00-00-Inspection *Significant Corrective Type Inspection Inspector Violation? Inspection No. Date Non-Compliance? Action Due By: . 11/18/2014 Routine/Periodic Mark Whitaker Yes No 12/31/2014 iMAW1432246509 Violations Absent Well Identification Signs (Rule 103) Comments on Inspection: Well sign incorrect (Rule 19.15.16.8). WELL SIGN SHOULD LIST CURRENT OPERATOR OF

RECORD. ALSO CHANGE EMERGENCY CONTACT PHONE NUMBER.

Rule 19.15.16.8 Sign should be legible from 50'

Rule 19.15.16.8 Sign should be legible from 50'

and each sign shall show operator's name, property
and each sign shall show operator's name, unit letter
name, well number, location by footage, unit letter
name, well number, and API number
section, township, range, and API number

NOV 2 5 2014

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Manufacture of Figure 1

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD OIL CONSERVATION DIVISION 1625 N FRENCH DRIVE HOBBS NM 88240



015H14150977 \$0.48 11/19/14 Mailed From 88240

RAM ENERGY LLC 5100 EAST SKELLY DRIVE SUITE 600 TULSA, OK 74135