Submit 1 Copy To Appropriate District Office	State of New		Form C-103
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and N	atural Resources	Revised July 18, 2013 WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	$\frac{1}{10} = (575) 748 - 1283 $		30-025-26976
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. F	rancis Dr.	5. Indicate Type of Lease
District IV - (505) 476-3460	Santa Fe, NM	87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		001420	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name NBR
ا مند J Gas Well Cher (مند الله الله الله الله الله الله الله الل			8. Well Number 1
2. Name of Operator OXY USA	Inc.	NOV 2 0 2014	9. OGRID Number 16696
3. Address of Operator			10. Pool name or Wildcat 96602
			Swo Bell Canyon Cherry Curryon
4. Well Location Unit Letter <u>J</u> : 1980 feet from the South line and 1980 feet from the enst line			
Unit Letter : Section 3	Township 225	Range 33E	NMPM County Lea
	11. Elevation (Show whether		
3631 GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK DIE PLUG AND ABANDON DIE REMEDIAL WORK DIE ALTERING CASING			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A			
DOWNHOLE COMMINGLE			
OTHER:			ent to Injection
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15 4 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
See Attached			
[···			
Spud Date:	Rig Release	e Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE			
Type or print name <u>David Stewart</u> E-mail address: <u>david_stewart@oxy.com</u> PHONE: <u>432-685-5717</u>			
For State Use Only			
Petroleum Engineer			
APPROVED BY:			
SWD-142D			

ų,

DEC 2 4 2014

NBR #1 - SWD


Date Remarks


6/27/13 MIRU PU, ND WH, NU BOP. Wait on WS Tbg.


6/28/13 PU Bit & Scraper, RIH w/ 2-7/8" L80 WS tbg & tag CIBP @ 9823'. TOH SB Tbg & LD Bit & Scraper.

- 7/2/13 Wait on trucks to arrive on Loc. Circ hole with 10# Brine. Spot 230 bbl kill mud. Getting ready to spot 30 sx cmt Class H Plug, got call from Rising Star they accidentally loaded Cl C cmt instead of Cl H, sent truck back.
- 7/3/13 RU to spot Cl H cmt plug. Checked water it was no good, they had checked day before it was good, someone dumped Brine in our Fresh water tank. Wait 5 hours for Fresh Water. M&P 30sx Cl H cmt on top of CIBP @ 9823'. PUH to 8668', M&P 30sx Cl H cmt. Calc TOC @ 8570', PUH, WOC 4 hrs. RIH & tag cmt @ 8565'. PUH w/ 1000' WS Tbg.
- 7/5/13 POOH w/ tbg, RU WL, RIH & set CIBP @ 6817', POOH w/ WL. RIH w/ tbg & tag CIBP @ 6817'. M&P 30sx CL C cmt, POOH w/ tbg. RIH w/ WL & set CBP @ 5250', POOH. RIH w/ WL & perf sqz hole @ 5220', POOH, RDWL.
- 7/8/13 RIH w/ pkr & set @ 5170', load & test csg & pkr to 1000#, held good. EIR @ 550# @ 1.6 BPM, started getting returns out 10-3/4", circ till fluid cleaned up, rel pkr & POOH.
- 7/9/13 RIH w/ CR & set @ 5170', sting out, sting back in, put 600psi on backside & sqz perf @ 5220' w/ 220sx Cl C cmt w/ returns out 10-3/4" while pumping cmt & flush. SD w/ 800psi on tbg & holding, sting out of ret & PUH, rev out any cmt left in tbg, TOH w/ tbg & LD Stinger.
- 7/12/13 RIH & drill on CR, fell thru & drill good cmt down to 5230', fell out of cmt. Tested sqz to 1000psi, held good. DO CIBP @ 5250', went down to 6775' (PBTD). PUH w/ bit above sqz perfs.
- 7/15/13 POOH w/ Tbg, LD DC & Bit. RIH w/ WL & tag @ 6634', Run CBL/GR/CCL, made 500' section with no pressure. Drop back down run Main pass with 1000psi F/ 6632' to surface, RD WL
- 7/16/13 POOH & LD tbg, ND BOP, NU WH, RDPU, Wait on orders.
- 8/23/13 RUPU, NDWH, NU BOP, RIH w/ Pkr & set @ 5157', test csg 1000# held solid for 15 min. Test down the tbg to 1000#, lost 600# in 5 min. Rel pkr, RIH PUH.
- 8/26/13 RIH w/ pkr to isolate leak. Isolated leak @ 5224-5289'.
- 8/27/13 Rel pkr & POOH w/ tbg, RDPU.
- 9/12/13 RIH w/ WL & perf @ 5030-5032, 5084-5087, 5267-5270, 5641-5643, 5750-5752, 5805-5807, 5952-5954' Total 32 holes, RD POOH.
- 9/16/13 RU BH, frac w/ 10000g FW + 10000g 15% HCl acid + 284339g gel fluid w/ 731100# sand.
- 9/26/13 RIH & tag fill @ 5984', start to circ to clean out, no circulation
- 9/27/13 MI RU, Foam unit & Nirtogen Membrane unit
- 9/30/13 RIH & tag fill @ 5960', break circ, clean out to 6020'.
- 10/1/13 RIH & tag @ 6020'. break circ, clean out to 6780', tagged hard, circ hole clean.
- 10/2/13 POOH w/ tbg, RIH w/ WL & perf @ 5960-5950, 5810-5800, 5650-5640, 5270-5260, 5090-5080, 5040-5030' Total 240 holes. POOH w/ WL.
- 10/3/13 RIH w/ Arrowset X- Pkr & 2-7/8" Composite lined tbg & set pkr @ 4981'
- 10/4/13 Circ hole w/ pkr fluid, test to 500#, held good.
- 10/7/13 ND BOP, NUWH; test to 560#, held good. RDPU
- 10/17/13 RU pump truck, run MIT, test to 550#, good test, witnessed by Mark Whitaker-NMOCD. (Original chart can't be found, copy of chart attached).

OXY USA Inc. - Current NBR #1 API No. 30-025-26976







h