40			
Submit One Copy To Appropriate District Office District I 1625 N. French Dr., Hobbs, NM 88240 District II	ico Forr	n C-103	
District I Energy, Minerals and Natur	al Resources Revised Novemb	er 3, 2011	
District I District II District II Bit S Einst St. Artesia NM 88210 2 2 2 2 2 2 2 2 2 2 2 2 2	WELL API NO. 30-025-10668		
811 S. First St., Artesia, NM 88210	SIVISION 5 Indicate Time of Lance		
District III 1000 Rio Brazos Rd., Aztec, NM 87410	cis Dr. $ $ STATE \square FEE \square	a	
District IV Santa Fe, NM 874	6. State Oil & Gas Lease No.	.	
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreemen	t Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU	G BACK TO A Skelly Penrose B Unit	t i tune	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FO PROPOSALS.)	L SUCH		
1. Type of Well: Oil Well Gas Well Other · INJECT	ON 8. Well Number 45		
2. Name of Operator	9. OGRID Number		
Providence Energy Services, Inc. dba Kelton Operating	012444		
3. Address of Operator	10. Pool name or Wildcat		
P.O. Box 928, Andrews, TX 79714-0928	Langlie Mattix (37240)		
4. Well Location			
Unit Letter <u>D</u> : <u>660</u> feet from the <u>NORTH</u>	_ line and feet from the <u>WEST</u> line		
Section 8 Township 23-S Range 37-E	NMPM County Lea		
11. Elevation (Show whether DR,	RKB, RT, GR, etc.)		
10. Check Americanista Denta Indiana Nature of Native De	Children D. A.		
12. Check Appropriate Box to Indicate Nature of Notice, Re	port or Other Data		
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:]	
PERFORM REMEDIAL WORK D PLUG AND ABANDON	REMEDIAL WORK	sing 🔲 ^I	
TEMPORARILY ABANDON			
PULL OR ALTER CASING 🔲 MULTIPLE COMPL 🔲	CASING/CEMENT JOB	/	
OTHER:	Location is ready for OCD inspection after P&A	<u> </u>	
 All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. 			
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR			
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR			
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to original groun	d contour and has been cleared of all junk trash flow	lines and	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.			
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from lease and well location.			
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)			
All other environmental concerns have been addressed as per OCD	rules.		
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-			
retrieved flow lines and pipelines.		non-	
If this is a one-well lease or last remaining well on lease: all electric			
location, except for utility's distribution infrastructure.	al service poles and lines have been removed from leas		
	al service poles and lines have been removed from leas		
When all work has been completed potent this form to the expression D	- Br		
When all work has been completed, return this form to the appropriate D	- Br		
When all work has been completed, return this form to the appropriate D SIGNATURE	strict office to schedule an inspection. $\mathcal{R}^{\mathcal{H}}$		
SIGNATURE CD-K	esidentDATE 12/27/2014	se and well	
SIGNATURE	strict office to schedule an inspection.	se and well	
SIGNATURE	strict office to schedule an inspection.	se and well	
SIGNATURE	strict office to schedule an inspection.	se and well	
SIGNATURE	strict office to schedule an inspection.	se and well	
SIGNATURE	esidentDATE 12/27/2014	se and well $\frac{1-1364}{5 / 2015}$	

、 ·