	B SUNDRY Do not use thi	UNITED STATES PARTMENT OF THE IN JREAU OF LAND MANAG NOTICES AND REPOI s form for proposals to I. Use form 3160-3 (APL	NTERIOR GEMENT RTS ON WE drill or to re-	ل LLS: enter an	-	SOCD 2 2015	OMB N	APPROVED IO. 1004-0135 July 31, 2010
	SUBMIT IN TRI	PLICATE - Other instruc	tions on rev	erse side.			7. If Unit or CA/Agre	ement, Name and/or No.
1. Type of Well Oil Well	🗖 Gas Well 🔲 Oth	er		······································			8. Well Name and No MARATHON RO	AD 15 PA FEDERAL 1H 🗸
2. Name of Oper MEWBOUF	rator RNE OIL COMPAN	Y E-Mail: jlathan@me	JACKIE LATHAN ewbourne.com				9. API Well No. 30-025-41575-00-S1	
3a. Address HOBBS, N	M 88241		3b. Phone No. (include area code) Ph: 575-393-5905				 Field and Pool, or Exploratory LEA 	
4. Location of W	/ell (Footage, Sec., T	., R., M., or Survey Description)	1				11. County or Parish,	and State
Sec 15 T20	0S R34E SESE 030 N Lat, 103.540099	0FSL 0330FEL					LEA COUNTY,	
	12. CHECK APPI	ROPRIATE BOX(ES) TC) INDICATE	NATURE	OF NC	TICE, RI	EPORT, OR OTHE	R DATA
TYPE OF	SUBMISSION			TYF	PE OF A	CTION		
🛛 Subseque	 □ Notice of Intent □ Acidize □ Alter Casing □ Casing Repair □ Final Abandonment Notice □ Convert to Injection 			□ Fracture Treat □ Reclam □ New Construction □ Recom			olete arily Abandon	 Water Shut-Off Well Integrity Other Well Spud
If the proposa Attach the Bo following con testing has be determined th 01/11/14 S sks Class (14.8 #/g w/ sks of cem Drilled out	I is to deepen direction: and under which the wo en completed. Final At at the site is ready for f pud 17 1/2" hole. R C w/additives. Mixe 1.34 vd. Tested BC	an 1670' of 13 3/8" 54.5 8 d @ 13.5 #/g w/1.75 yd. T DPE to 3000# & annular to 9:00 A.M. 01/16/14 tested	give subsurface the Bond No. on sults in a multiple ed only after all r & 48# H40 & ail w/200 sks > 1500#. Plug	locations and i file with BLN e completion of equirements, J55 ST&C of Class C w down @ 9:	measured M/BIA. I or recomp including csg. Ce /1% Ca :30 AM	and true ver Required sub pletion in a p reclamation mented w Cl2. Mixe 01/14/14.	rtical depths of all pertin bsequent reports shall be new interval, a Form 316 n, have been completed, ith 1150 d @	nent markers and zones. c filed within 30 days 60-4 shall be filed once
14. 1 hereby cert Name (Printer		#Electronic Submission For MEWBOU d to AFMSS for processing	JRNE OIL CO	IPÁNY, sen WEATHER	nt to the FORD o	Hobbs n 05/02/20	-	
Signature	(Electronic S	Submission)		Date 03	/05/201	A .		
		THIS SPACE FO	OR FEDERA				SE	
Approved By	ACCEPT	ED		JAME _{Title} SUPE	ES A AN ERVISC			Date 01/17/2015
certify that the app	roval, if any, are attache plicant holds legal or eq le the applicant to cond	d. Approval of this notice does uitable title to those rights in the uct operations thereon.	not warrant or subject lease	Office Hol	bbs			
		U.S.C. Section 1212, make it a statements or representations as				llfully to m	ake to any department o	r agency of the United
	** BLM REV	ISED ** BLM REVISE	D ** BLM RE	EVISED **	BLM	REVISE	D ** BLM REVISE	 D **

.

JAN 3 0 2015

M

Company Marbourne Date 1-15-14

Lease KIAAATHON BOAD"IS "PA FEO 1 H County La Co. NUL.

Drilling Contractor Paterion 4444 Plug & Drill Pipe Size 17 122 4 EF

MAN WELDING SERVICES, INC.

Accumulator Pressure: <u>300</u> Manifold Pressure: <u>1500</u> Annular Pressure: <u>1200</u>

Accumulator Function Test - OO&GO#2

To Check - USABLE FLUID IN THE NITROGEN BOTTLES (III.A.2.c.i. or ii or iii)

- Make sure all rams and annular are open and if applicable HCR is closed.
- Ensure accumulator is pumped up to working pressure! (Shut off all pumps)
 - 1. Open HCR Valve. (If applicable)
 - 2. Close annular.

Θ

- 3. Close all pipe rams.
- 4. Open one set of the pipe rams to simulate closing the blind ram.
- 5. For 3 ram stacks, open the annular to achieve the 50+ % safety factor. (5M and greater systems).
- 6. Record remaining pressure 13co psi. Test Fails if pressure is lower than required.
- a. {950 psi for a 1500 psi system} b. {1200 psi for a 2000 & 3000 psi system }
- 7. If annular is closed, open it at this time and close HCR.

To Check - PRECHARGE ON BOTTLES OR SPHERICAL (III.A.2.d.)

- Start with manifold pressure at, or above, maximum acceptable pre-charge pressure:
 a. {800 psi for a 1500 psi system}
 b. {1100 psi for 2000 and 3000 psi system}
 - 1. Open bleed line to the tank, slowly. (gauge needle will drop at the lowest bottle pressure)
 - 2. Close bleed line. Barely bump electric pump and see what pressure the needle jumps up to.
 - 3. Record pressure drop 1000 psi. Test fails if pressure drops below minimum.
- Minimum: a. {700 psi for a 1500 psi system } b. {900 psi for a 2000 & 3000 psi system}

To Check - THE CAPACITY OF THE ACCUMULATOR PUMPS (III.A.2.f.)

- Isolate the accumulator bottles or spherical from the pumps & manifold.
- Open the bleed off valve to the tank, {manifold psi should go to 0 psi} close bleed valve.
 - 1. Open the HCR valve, {if applicable}
 - 2. Close annular
 - 3. With pumps only, time how long it takes to regain the required manifold pressure.
 - 4. Record elapsed time 1415 425cc Test fails if it takes over 2 minutes.
 - **a**. {950 psi for a 1500 psi system} **b**. {1200 psi for a 2000 & 3000 psi system}

Ĩ		WELDING SERVICES		UP SERVIC	• BOP TEST E • BOP LIF IAS SEPARA A • 575-3	TS • TANDEM	Pg	_of _3_	
c	Company	. Menbourne		_ Date:	1-15	- 14	Invoice #	B60388	
τ, ι	ease: U	ARATHON RUAD "IF" P.	A FED 14	_ Drilling	Contractor	- Patterson	Rig # _	944	
F	lug Size.	&Type: 12" C22	Drill Pipe Siz	re 41	TF	Tester	Ma, Hhen	Davis	-
F	Required	BOP:		Instal	led BOP:		······		PT-1-10-1
•A	ppropriate (Casing Valve Must Be Open During BOP Test *				* Check Valv	e Must Be Open/Disable	d To Test Kill Line Va	alves *
H- 704		Annular #15 Pipe Rams #12 Jelind Rams #13 Hit II Hit II Casing	#26 #2 #4 #3 #1 #1 #25 Super Ch	N5 Le S Le S Le S Le S Le S Le S Le S Le S	#6 3 L 3 L 2 2 C	IBOP #17 Manual IBOP #16	fizz Fump Valve \$20	Dart Valve #19 Stand Pipe Valve #24 #23 TIW Valve #18	
	· · · · · · · · · · · · · · · · · · ·		- <u>1</u>						·
	TEST 0	ITEMS TESTED	TEST LENGTH	LOW PSI	HIGH PSI		REMARKS	* *	<u> </u>
	i setting a	17	10 uus	250	3000	Low Gorel	Sum 11 510	with an	
			·		· · · · ·	High Pin	receil bail	and the second secon	إس
				· · · · · · · · · · · · · · · · · · ·			tasiline !!	High Care	Ś.
						Goul Terr			
	2	16	10 min	236	300	Low Gerd	Samil Louis	e as High	<u>4</u>
						Prerracial	Beile up us	H.Y. Pre. r Yern	
	1					Ctub. 1. Te	C. Hart a	with Greet	Ice .
	3	16	Ionin	250	3000	Suall bla	ed eff on L	Sur Purt	unter .
							black off		
Ŭ,							t to work		
	4	16	10400	250	Jaco		d off as t	23	
							an Grand P		
4							2		
a (*							Ublack off a	/ 1	1
	-	15 9 7		200	1500	buck up in	· .		
ا ا ا س	<u>⊢⊃</u> ́		Duin	250	JARO	Į · · ·	Spall Ela		- L.
t,			1			Presiding 6			Merte
· ·	<u> </u>	12.9.7	10 hun	250	3000	NO Pressur			
;				ř.			Functions		times
, .* 	1 (₁₀	1/2, 4, 7		<u> </u>	D- Pair	Plosig red wy	seto Low, b	local off.	in tow
			/ 17 4	SALI IN	o- rai	7		· ·	



÷., • •

WELDING • BOP TESTING NIPPLE UP SERVICE • BOP LIFTS • TANDEM MUD AND GAS SEPARATORS Lovington, NM • 575-396-4540

_of __3 2 Pg.

...

TEST #	ITEMS TESTED	TEST LENGTH	LOW PSI	HIGH PSI	REMARKS
					Proceed back up . Black ett .
					again Record up to 1840 pt
			, i , i		to beals for Lowker, Leck at Batt.
					cide of Almed Ann door
8.	75.43	1041in	250	300	Provend up Shall Shed St
5. 8.165					in Law Processed back ye Susail
*					bland off again, black off to class
÷.,					Hus Fuld values Velve 486 wards
9	7,5,4,7	Durin	250		Sturbal to parison up but you
				-	cround comm on CHAR+ TO hold Type
					Shared CHISATI LAW Good, Samer Store
					off on High, Processed back upo
	· · · · · · · · · · · · · · · · · · ·	·			Shall Have OFF again, Then Prica
	· · · · · · · · · · · · · · · · · · ·				Drupped about the pri 4 best in
					Clarka Mian Ealer Flore to Aulich
					buches .
10	1797	10 min	_	3000	Prestated up to High to LARCH
					Lost in Plusten dour, Lonk
•	· · · ·				in Toma Spot; Lack Nor or fare
•••••		1			as before . Blint Rea duars no
	· · · · · · · · · · · · · · · · · · ·		•		Se open est.
l (75,43	10min	÷ .	3000	Haud Grouge Flings + 1966 tinil
					Prarmanel back up 13 High, Riperl
	· · · · · · · · · · · · · · · · · · ·				off on High Charles duitald For
	·····				Lealer, AD Leave Fund, Programmel.
•	· ·	· · · · · · · · · · · · · · · · · · ·			buck up, Small blesst che, Princessig
					buck up , General Tert
R	7, 6, 36, 2.1	1Davin	250	3000	Low Creel, Sauli Glace offer an
					High, Prenced up in High multiple
		ļ	·		riner with bleed off still; Blead
		ļ			off proment to work thin file
	· · · · · · · · · · · · · · · · · · ·				Valuer
13	7636,21	10hin	-	3000	Prestured back up to Hish
					(xeed Tost
14	7, 6, 30, 26, 25	Bump Tell	-	3000	Pressinul 110, Blod off, formel For
·····		HOMORE !!!!			CONTRACT CONTRACT CONTRACT



12,9.7

ITEMS TESTED

TEST #

15

. . .

WELDING - BOP TESTING NIPPLE UP SERVICE • BOP LIFTS • TANDEM MUD AND GAS SEPARATORS Levington, NM · 575-398-4540

Pg. <u>3</u> of <u>3</u>

104

Resard

Prican

o t


ć,


... REMARKS


Law Good


TEST LENGTH LOW PSI HIGH PSI 250 Durin 3000 Sarall blood off on h۵ 1

	· · · · · · · · · · · · · · · · · · ·		``		1416. Small Sleed off in High, Average
					back up , High bard , bread Torn
:16	12,10,8	10 min	250	3000	Same 11 block off on Low, Pressure
	·				back up , Sa all grout aft again
					Remain brok up again, Lue Cread
	·				Pressin the to High Aigh Com!
	· ·				found Tert
17	17, 10, 95, 5, 4, 3	10mil	250	3000	(resc.) Terre
	13.115.43	Ducin	250	1	George Test
	· · · · · · · · · · · · · · · · · · ·			ŀ	
	<u></u>	1		<u></u>	2.4
		1			
· · · · ·					······································
		1	<u>}</u>	<u> </u>	
				· ·	
		1	<u> </u>		
·					
		·	· · · ·		
		· . ·	· · · · · ·	·	
			·	. 	
			·		
	· · · · · · · · · · · · · · · · · · ·				
			<u> </u>		<u> </u>
		<u> </u>	<i>شر</i>	<u> </u>	
		+		[<u>·</u>	
<u></u>	· · · · · · · · · · · · · · · · · · ·	+] ^r 	ļ	
		<u> </u>	ļ	· .	
		ļ	ļ		
			ļ		
T					









344 C

