

CROSS TIMBERS ENERGY, LLC

Hydrogen Sulfide Drilling Plan Summary To be in place prior to drilling the Grayburg Formation

- A. All personnel shall have proper H2S training in accordance with Onshore Order 6 III.C.3.a. and carry their certification card.
- B. Briefing Area: two perpendicular areas will be designated by signs and readily accessible.
- C. Required Emergency Equipment:
 - ☐ Well control equipment
 - a. Flare line from wellhead to be ignited by flare gun.
 - b. Choke manifold with an adjustable choke.
 - Protective equipment for essential personnel.

Breathing Air Trailer:

- a. Rescue Packs (SCBA) 2 shall be stored in the safety trailer.
- b. Work/Escape packs —4 packs shall be stored on the rig floor with sufficient air hose so as not to restrict work activity.
- ☐ H2S detection and monitoring equipment:

The stationary detector with four wireless sensors will be placed in the upper dog house if equipped, set to visually alarm @ 10 ppm and audible @ 14 ppm. Calibrate a minimum of every 30 days or as needed. The sensors will be placed in the following places: Rig floor / Bell nipple / End of flow line or where well bore fluid is being discharged. (Gas sample tubes will be stored in the safety trailer)

- Visual warning systems.
 - a. One color code condition sign will be placed at the entrance to the site reflecting the possible conditions at the site.
 - b. A colored condition flag will be on display, reflecting the current condition at the site at the time.
 - c. Two wind socks will be placed in strategic locations, visible from all angles.
- Mud program:

The mud program has been designed to minimize the volume of H2S circulated to surface. The operator will have the necessary mud products to minimize hazards while drilling in H2S bearing zones.

- Metallurgy:
 - a. All drill strings, casings, tubing, wellhead, blowout preventer, drilling spool, kill lines, choke manifold and lines, and valves shall be suitable for H2S service.
 - b. All elastomers used for packing and seals shall be H2S trim.
- Communication: Communication will be via two way radio in emergency and company vehicles. Cell phones and land lines where available.

Hydrogen Sulfide Contingency Plan

Assumed 100 ppm ROE - 3,000'

100 ppm H2S concentration shall trigger activation of this plan

HOBBSOCD

FEB 2 3 2015

Emergency Procedures

RECEIVED

In the event of a release of gas containing H2S, the first responders must:

- Isolate the area and prevent entry by other persons into the 100 ppm ROE.
- Evacuate any public places encompassed by the 100 ppm ROE.
- Be equipped with H2S monitors and air packs in order to control the release.
- Use the "buddy system" to ensure no injuries occur during the response.
- Take precautions to avoid personal injury during this operation.
- Have received training in the:
 - o Detection of H2S
 - Measures for protection against H2S
 - o Equipment used for protection and emergency response

Ignition of Gas Source

Should control of the well be considered lost and ignition considered, take care to protect against exposure to Sulfur Dioxide (SO2). Intentional ignition must be coordinated with the NMOCD and the local officials. Additionally, the NM State Police may become involved. NM State Police shall be the Incident Command on scene of any major release. Take care to protect downwind whenever there is an ignition of the gas.

Characteristics of H2S and SO2

Common Name - Hydrogen Sulifide	Chemical	Specific	Threshold	Hazardous	Lethal
	Formula	Gravity	Limit	Limit	Concentration
	H2S	1.189 Air=1	10 ppm	100 ppm/hr	600 ppm
Sulfur Dioxide	SO2	2.210 Air=1	2 ppm	N/A	1000 ppm

Contacting Authorities

Cross Timber Energy, LLC's personnel must liaison with local and state agencies to ensure a proper response to a major release. Additionally, the OCD must be notified of the release as soon as possible but no later than 4 hours. Agencies will ask for information such as type and volume of release, wind direction, location of release, etc. Be prepared with all information available including directions to site. The following call list of essential and potential responders has been prepared for use during a release. Cross Timbers Energy, LLC's response must be in coordination with the State of New Mexico's "Hazardous Materials Emergency Response Plan (HMER).

Cross Timbers Energy LLC Buckeye Office in Lea County, NM:

From Hobbs, NM take Highway 62/180 West for approximately 10 miles to SH 529, turn right on SH 529 and go NW for 3 miles to Highway 238, turn North on Highway 238 and proceed North for approximately 8 miles to the Buckeye Field Office.

Cross Timbers Energy, LLC Personnel:

Buckeye Field Office Jerry Parker, Buckeye Production Foreman Gene Hudson, Lease Operator Al Lujan, Lease Operator Kevin Bennett, Lease Operator Jose Casas, Lease Operator James Embree, Lease Operator Kasey Guinn, Lease Operator Ian Peterson, Operations Engineer Bill Frey, Operations Manager George Ramsey, Drilling Engineer Robbie Grigg, Regulatory Compliance	575-396-0542 575-441-1628 575-441-1634 575-441-1638 575-513-8156 575-746-7220 575-704-2241 575-746-7212 432-634-4922 817-334-7709 903-253-5001 817-917-5341
Sheriff Departments:	911
Lea County Eddy County	575-396-3611 575-887-7551
New Mexico State Police	575-392-5588
Fire Departments:	911
Eunice Hobbs Jal Lovington Carlsbad	575-394-2111 575-397-9308 575-395-2221 575-396-2359 575-885-2111
Hospitals:	911
Eunice Medical Emergency Hobbs Medical Emergency Jal Medical Emergency Lovington Medical Emergency Carlsbad Medical Emergency	575-394-2112 575-397-9308 575-395-2221 575-396-2359 575-885-2111
Agency Notifications:	
Bureau of Land Management New Mexico Oil Conservation Division	575-393-3612 575-393-6161
Contractors:	
Windmill Weed Control – Light Towers/Trash Trailers Spur Services – Trucking/Forklift/Light Towers Catalyst Chemical Lucky Health & Safety Indian Health & Safety Watson - Dirt Contractor Sweatt – Dirt Contractor Cesar Trucking – Dirt Contractor/Backhoe	575-631-0969 575-942-9503 575-390-7782 575-492-7777 575-393-3093 575-391-0537 575-397-4541 575-605-1802