State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez Governor

David Martin Cabinet Secretary

Brett F. Woods, Ph.D. Deputy Cabinet Secretary David Catanach, Director Oil Conservation Division



Response Required - Deadline Enclosed

__Underground_Injection_Control_Program

"Protecting Our Underground Sources of Drinking Water"

23-Apr-15

ENERGEN RESOURCES CORPORATION

2010-AFTON-PLACE FARMINGTON NM 87401-2707

LETTER OF VIOLATION and SHUT-IN DIRECTIVE Failed Mechanical Integrity Test

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, <u>the well(s) must be shut-in</u> <u>immediately</u> until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or <u>probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the</u> Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION


LAMBIRTH A	No.006				30-041-20584-00-00
		Active Sa	lt Water Dispo	sal Well	J-30-5S-33E
Test Date:	4/20/2015	Permitted Injection	1.PSI:	Actual_PSI;	
Test Reason:	Annual IMIT	Test Result:	F	Repair Due:	7/24/2015
Test Type:	Bradenhead Test	FAIL TYPE:		FAIL CAUSE:	
Comments on MIT: BHT-FAILURE. CSG Pressure would not blow down.					

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Hobbs OCD District Office

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted-as-a-diagnosis-of-the-condition-of-the-wellbore: Additional-testing-should be conducted by the operator to accurately determine the nature of the actual failure. * Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas. EMNRD OIL CONSERVATION DIVISION 1625 N FRENCH DRIVE HOBBS NM 88240



ENERGEN RESOURCES CORPORATION 2010 AFTON PLACE FARMINGTON NM 87401-2707

.

•

.

.