Submit 1 Copy To Appropriate District Office State of New Mexico	Form C-103
District 1 – (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240	Revised July 18, 2013 WELL API NO.
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-041-20963
District III - (505) 334-6178 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410     1220 South St. 1 Hillors D1.       District IV - (505) 476-3460     Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	1
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Hard Days Night -
PROPOSALS.)	8. Well Number .
1. Type of Well: Oil Well Gas Well Other   2. Name of Operator - MAX 0 4 2015	l 9. OGRID Number
ARMSTRONG ENERGY CORPORATION	1092
5. Address of Operator	10. Pool name or Wildcat
P.O. Box 1973, Roswell, NM 88022-1973 <b>RECEIVED</b>	Wildcat: Fusselman
Unit Letter <u>N</u> : 475 feet from the <u>South</u> line and <u>1705</u>	feet from theWestline
Section 10 Township 6S Range 33E	NMPM Roosevelt County
11. Elevation (Show whether DR, RKB, RT, GR, e	
4400' GR	
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO:	TING <swd injection=""></swd>
PERFORM REMEDIAL WORK D PLUG AND ABANDON V R CONVERS	
TEMPORARILY ABANDON CHANGE PLANS	
PULL OR ALTER CASING DOWNHOLE COMMINGLE	CHG LOC
CLOSED-LOOP SYSTEM	P&A NRP&A R
OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated	
date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple C proposed completion or recompletion.	
VUNLTY CITT ON CHIST,	
1. RU completion unit, ND wellhead and install B.O.P. 2. TIH w/ tubing to 5200' and circulate the casing with 9.5 PPG 35 vis mud. <b>PRESSURE TEST CASING</b> .	
2. TIH w/ tubing to 5200' and circulate the casing with 9.5 PPG 35 vis mud.	
3. Spot a 100' plug from 3220'-3120', top of San Andres, with 25 sx Class "C" cement.	
4. Perf @ 2480' and establish circulation.	
5. Spot a 150' plug from 2480' to 2330', inside/outside casing, with 50 sx Class "C" cement.	
6. WOC for 4 hrs and tag plug @ 2330'.	The Oil Conservation Division
	AUST BE NOTIFIED 24 Hours
	ior to the beginning of operations
	10r to the beginning of operations
Spud Date: Rig Release Date:	
·	
I hereby certify that the information above is true and complete to the best of my knowledg	e and belief.
SIGNATURE TITLE Vice President – Operations/Engineering DATE04/29/15	
Type or print name Bruce A. Stubbs E-mail address:bastubbs@armstrongenergycorp.com_ PHONE:575-625-2222	
For State Use Only	
APPROVED BY: Maley Strown TITLE Dist. Supervisor DATE 5/4/2015	
Conditions of Approval (if any)	
<u> </u>	MAY 0 5 2015

fle
11

- 7. Perf @ 1750' and establish circulation.
- Spot a 100' plug from 1750'-1650', inside/outside casing, with 35 sx Class "C" cement. 8.

9. Perf @ 500' and establish circulation.

- 10. Spot a 150'plug from 500'-350', inside/outside casing, with 35 sx Class "C" cement.
- 11. Perf @ 100' and establish circulation.
- 12. Spot a 100' plug from 100' to surface, inside/outside casing, with 25 sx Class "C" cement.
- 13. Cut off wellhead, install Dry Hole marker, remove production equipment, cut off anchors and remove caliche.
- 14. Rehab location and reseed when soil moisture permits.

WOC & TAG-WOC & TAG-

