

WBDU #168 - 30-025-41548

Dickey, Sylvia, EMNRD

Sent: Wednesday, May 06, 2015 2:08 PM**To:** Fisher, Reesa [Reesa.Fisher@apachecorp.com]**Cc:** Goetze, Phillip, EMNRD; Sonnamaker, William, EMNRD

Hello Reesa;

I received the completion paperwork for the well above. After reviewing the order and completion data, it seems that the well is out of compliance with WFX-923.

If you have already submitted a request to amend this order, on the well above to Phillip, please let me know.

Please note that according to WFX-923 page one (1), bottom paragraph, the actual approved perforated injection depth is 5822-6594; After reviewing the C105, c103, there seems to be a little deviation from this approved area. After looking at the PTS grid report, it does however show the well is still in the Drinkard interval.

Please call me if you read otherwise, concur or have any questions.

Thank you,

SYLVIA A. DICKEY

Compliance Officer

Hobbs OCD District I Office

575-370-3188

575-393-6161 112

MAY 07 2015