Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form proposals to drill or to re-enter anco abandoned well. Use Form 3160-3 (APD) for such proposals.

OCD Hobbs

FORM APPROVED OMB No. 1004-0137

Expires: July 31, 2010

5. Lease Serial No. NMLC-060199A

SEE ATTACHED FOR

CONDITIONS OF APPROVAL

6. If Indian, Allottee or Tribe Name

| SUBMIT | IN TRIPLICATE - Other instr | uctions on page 2. | EP 1 7 2014 | 7. If Unit of CA/Agre | eement, Name and/or No. | |
|---|---|---|--|---|---|--|
| 1. Type of Well | | |)EF 3 | | | |
| - Oil Well Gas Well Other | | | | 8. Well Name and No Cutthroat Federal | | |
| 2, Name of Operator | RECEIVED | | 9. API Well No. | 9. API Well No. | | |
| Mack Ene | | | 30-025-41557 | | | |
| 3a. Address | | 3b. Phone No. (include area code) | | 10. Field and Pool or | 10. Field and Pool or Exploratory Area | |
| P.O. Box 960 Artesia, NM 88210-0960 | | (575) 748-1288 | | Yeso | | |
| 4. Location of Well (Footage, Sec., T,R,M, or Survey Description | | i) | | 11. Country or Parish | 11. Country or Parish, State | |
| 1650 FNL & 2310 FEL, Sec. 29 T17S R32E | | | | Lea, NM | Lea, NM | |
| 12. CHEC | K THE APPROPRIATE B | OX(ES) TO INDICATI | E NATURE OF N | OTICE, REPORT OR OTH | IER DATA | |
| TYPE OF SUBMISSION | TYPE OF ACT | | | ACTION | | |
| Notice of Intent | Acidize | Deepen | | Production (Start/Resume) | Water Shut-Off | |
| | Alter Casing | Fracture Tre | at 🔲 | Reclamation | Well Integrity | |
| Subsequent Report | Casing Repair | New Constr | uction | Recomplete | Other | |
| Subsequent Report | Change Plans . | Plug and Ab | andon | Temporarily Abandon | | |
| Final Abandonment Notice | Convert to Injection | Nlug Back | | Water Disposal | | |
| 13. Describe Proposed or Completed C the proposal is to deepen directi Attach the Bond under which the v following completion of the involv testing has been completed. Final A determined that the site is ready fo | onally or recomplete horiz work will be performed or p yed operations. If the operat bandonment Notices must | contally, give subsurface le rovide the Bond No. on ion results in a multiple | ocations and measur file with BLM/BI completion or rec | ed and true vertical depths of A. Required subsequent rep ompletion in a new interval | of all pertinent markers and zones. Forts must be filed within 30 days The a Form 3160-4 must be filed once | |
| Mack Energy Corporation as opera 429-7300' acidize and frac the Cu | | | gback and mov | e uphole and perforat | e the Yeso formation from | |
| . MIRU PU | | | | | | |
| . POH w/rods stand back 118-1" | & 160-7/8" laydown 7 | '2-7/8" rods & 14 F | K- Bars. K-Bars | s will be run back in h | ole. | |
| . POH wrods stand back 118-1". NU 3K BOP & RU Lucky Well. POH w/tbg. Standback 230 jts & | service safety equip. | Kill well if needed | to hold H2S do | own, | | |
| . POH w/tbg. Standback 230 jts & | k laydown bottom 50 j | its. See Cor | TAOI MO | mai ping | | |
| RU wireline & set CIBP @ 892 | | | | | | |
| . RIH w/wireline & set CIBP @ | 25 5x | . Cover 1 op of Abo | 5 W 1414. CA | | | |

Jerry W. Sherrell

Title Production Clerk

Date 8-29-2014

This Space For Federal or State Office Septical View (And States any false, fictitious or fraudulent statements or representations as to any matter within its introducing of the production Clerk

Title Seption (Printed Typed)

(Instructions on page 2)

9. Swab & evaluate

8. RIH w/Packer PPI Perfs & pump acid ball job.

10. If zone looks productive proceed w/slickwater frac.

Mack Energy Corporation

Cutthroat Federal #5 Sec. 29 T17S R32E 30-025-41557

Before

13 3/8 @ 867' w/725sx, circ. 8 5/8 @ 2258' w/1290sx, circ. Perfs from 5429-7300 Yeso Formation CIBP @ 7464' w/35' cap Top Abo @ 7474' CIBP @ 8921' w/35' cap Perfs from 9021-9129' Top cmt @ 9284' CIBP @ 9520' w/25sx cap Perfs from 9556-9587' Squeezed w/75sx CIBP @ 9640' w/ 35' cap Perfs from 9672-9693 Cmt retainer @ 9650' Squeezed w/100sx H 5 1/2 @ 9800' w/1900sx, circ.

TD 9800'

Cmt retainer @ 9530'

Mack Energy Corporation

Cutthroat Federal #5 Sec. 29 T17S R32E 30-025-41557

After

STATE AND THE PROPERTY OF THE

13 3/8 @ 867' w/725sx, circ.

8 5/8 @ 2258' w/1290sx, circ.

Perfs from 5429-7300 Yeso Formation

CIBP @ 7464' w/35' cap

Top Abo @ 7474'

CIBP @ 8921' w/35' cap

Perfs from 9021-9129'

Top cmt @ 9284'

CIBP @ 9520' w/25sx cap Cmt retainer @ 9530'

Perfs from 9556-9587' Squeezed w/75sx

CIBP @ 9640' w/ 35' cap Cmt retainer @ 9650'

Perfs from 9672-9693 Squeezed w/100sx H

5 1/2 @ 9800' w/1900sx, circ.

TD 9800'

Cutthroat Federal 5 30-025-41557 Mack Energy Corporation September 10, 2014 Conditions of Approval

Notify BLM at 575-393-3612 a minimum of 24 hours prior to commencing work.

- 1. Prior to setting CIBP at 8921' the operator shall place a minimum of 25 sx Class H Cement on top of the CIBP at 9,520' to seal the top of the Wolfcamp formation (Top of Wolfcamp at 9346'). WOC and tag at approximately 9,296'.
- 2. Operator shall set CIBP at 7574' and place a minimum of 25 sx Class H Cement on top of the CIBP to seal the top of the Abo formation. (Top of Abo at 7474')
- 3. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 4. Surface disturbance beyond the originally approved pad must have prior approval.
- 5. Closed loop system required.
- 6. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 7. Operator to have H2S monitoring equipment on location.
- 8. A minimum of a **3000 (3M)** BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram.
- 9. Subsequent sundry required detailing work done, a C-102 form, and completion report for the new formations. Operator to include well bore schematic of current well condition when work is complete.
- 10. See attached for general requirements.

CRW 091014

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Production Zone Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from this approval.

If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat Class "C"**, for up to 7,500 feet of depth or **Neat Class "H"**, for deeper than 7,500 feet plugs.

- 6. <u>Subsequent Plug back Reporting:</u> Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed.</u>
- 7. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.