Submit 1 Copy To Appropriate District Office State of New Mexico <u>District I</u> – (575) 393-6161 Energy, Minerals and Natural Resources	Form C-103 Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	WELL API NO.
811 S. First St., Artesia, NM 88210       OIL CONSERVATION DIVISION	30-041-20959 5. Indicate Type of Lease
District III - (505) 334-6178         1220 South St. Francis Dr.           1000 Rio Brazos Rd., Aztec, NM 87410         Santa Fe, NM 87505	STATE     FEE       6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU <b>HOBBSOCD</b> DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	<ol> <li>Lease Name or Unit Agreement Name</li> <li>Pep 36 State</li> </ol>
PROPOSALS.) 1. Type of Well: Oil Well  Gas Well  Other  APR 1 0 2015	8. Well Number
2. Name of Operator	9. OGRID Number
ARMSTRONG ENERGY CORPORATION RECEIVED	1092 10. Pool name or Wildcat
P.O. Box 1973, Roswell, NM 88022-1973	Wildcat: Wolfcamp
4. Well Location	
Unit LetterM990feet from theSouthline and430feet from theWestlineSection36Township5SRange33ENMPMRooseveltCounty	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK 🔲 PLUG AND ABANDON 🔲 REMEDIAL WORK 🔅 ALTERING CASING 🗌	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A OPULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB	
OTHER:       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, ar	Perf & Acidize Complete Acidize
date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
03-31-15 RU Crain Acidizing, spot 250 gals 15% NEFE acid @ 7306', RD, POH w/ tbg. RU Cased Hole Solutions, perf	
7283'-7292' and 7297'-7306', 2 JSPF, 120° phasing, total 38 shots. RD Cased Hole Solutions, TIH w/ 5-1/2" pkr, on-off tool and tbg, reverse acid into tbg, set packer pressure annulus to 500 psi, pump down tbg @ .5 BPM, formation broke @	
3615 psi, 2900-3150-3400 psi, increase rate to 1.9 BPM @ 3400 psi, displace acid. ISIP 3100 psi, 5 min 2201 psi, 10 min 1776 psi, 15 min 1503 psi. RD Crain Acidizing, RU swab, blow down and RIH w/ swab. Rec'd 45 BLW, swabbed down	
to SN, show of gas on last run.	
04-01-15 Made 2 swab runs, rec'd 9 BW, no show. RU Crain Acidizing, pump 80 BBLS (3360 gals) and 80 ball sealers, rate 4.1	
BPM, 3250-3500 psi, balls on, 4200 psi, broke back to 3600 psi, problem 5 min 2800 psi, 10 min 2700 psi, 15 min 2600 psi, 128 BLW plus 16 BLV	
back, RU swab, made 10 runs, rec'd 78 BLW, show of gas and 1% oil cut. FL @ 4500', 14 runs with 96 BLW back, 5	
BBLS/run, 10% oil cut, gas show, FL @ 6000', swabbing from SN. Rec'd 104 BLW, 25% oil cut, show of gas, 300' of fluid per run, 40 BLTR.	
(Continued – Pg 2)	
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE	
Type or print name <u>Bruce A. Stubbs</u> E-mail address: <u>bastubbs@armstrongenergycorp.com</u> PHONE: <u>575-625-2222</u>	
For State Use Only	
APPROVED BY:	
Conditions of Approval (if any):	MAY 2 6 2015

## API #30-041-20959 Pep 36 State #3 C-103 – Perf & Acidize Page 2

Crain Acidizing has agreed to re-acidize the well at their cost due to malfunction with ball drops on the initial treatment.

04-03-15 RU Crain Acidizing, pump 80 BBLS (3360 gals) 15% NEFE acid with 80 ball sealers, 4.7 BPM @ 3000-3400 psi, balled out with 65 balls on, max pressure 7200 psi, released balls and displaced acid. ISIP 2800 psi, 5 min 2226 psi, 10 min 1685 psi, 15 min 1216 psi, flowed back. RU swab, 132 BLTR, swabbed 102 BLW, final run had 1% oil cut, 30 BLTR.