Submit 3 Copies To Appropriate District State of New Mexico	
Unice	Form C-103
1625 N. French Dr., Hobbs, NM 88240	WELL API NO. May 27, 2004
District II 1301 W. Grand Ave. Artesia NM 88210 - OHCONSERVATION DIVISIO	
1301 W. Grand Ave., Artesia, NM 88210 District III 1000 BBS CONSERVATION DIVISIO 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV 27 2015 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM MAY 27 2015 Santa Fe, NM 87505 87505	E-1582
SUNDRY NOTICESTANDEREPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROFOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	A ARCO 28 STATE
PROPOSALS.)	8. Well Number
1. Type of Well: Oil Well       Gas Well       Other Inj         2. Name of Operator	9. OGRID Number
SUNDOWN ENERGY LP	232611
3. Address of Operator	10. Pool name or Wildcat
13455 NOEL RD, STE. 2000, DALLAS, TX 75240	REEVES (QUEEN)
4. Well Location	
Unit Letter <u>B</u> : <u>330</u> feet from the <u>NORTH</u> line and <u>1650</u> fee Section 28 Township 18S Range 35E NMPM	t from the <u>EAST line</u> County LEA
11. Elevation (Show whether DR, RKB, RT,	
3913.8' GR	
Pit or Below-grade Tank Application or Closure	
Pit typeDepth to GroundwaterDistance from nearest fresh water well	
	bbls; Construction Material
12. Check Appropriate Box to Indicate Nature of N	lotice, Report or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
	AL WORK 🛛 ALTERING CASING 🗌
PULL OR ALTER CASING DIMULTIPLE COMPL CASING/	
	Convert P&A well to inj well
13. Describe proposed or completed operations. (Clearly state all pertinent de	tails and give pertinent dates including estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Complete	ions: Attach wellbore diagram of proposed completion
12/12/14	
10/27/19 - 12/10/11	
or recompletion. 10/27/14 - 12/18/14 1- Dig out old cellar- weld on 8 5/8" and 4 %" stubs: nipple up well he	ead & BOP
1- Dig out old cellar- weld on 8 5/8" and 4 ½" stubs; nipple up well he	
<ol> <li>Dig out old cellar- weld on 8 5/8" and 4 ½" stubs; nipple up well he</li> <li>Pick up 3 ¾" bit and tubing; Clean out cement plugs ( 0-147' and 1</li> </ol>	
<ol> <li>Dig out old cellar- weld on 8 5/8" and 4 ½" stubs; nipple up well he</li> <li>Pick up 3 ¾" bit and tubing; Clean out cement plugs (0-147' and 1 Continue to PBTD at 4500'.</li> </ol>	.620'-1760'), cement and CIBP at 4400'.
<ol> <li>Dig out old cellar- weld on 8 5/8" and 4 ½" stubs; nipple up well he</li> <li>Pick up 3 ¼" bit and tubing; Clean out cement plugs (0-147' and 1 Continue to PBTD at 4500'.</li> <li>Run 4 1/2" internally coated packer &amp; 2 3/8" Internally coated tu</li> </ol>	.620'-1760'), cement and CIBP at 4400'. bing to
<ol> <li>Dig out old cellar- weld on 8 5/8" and 4 ½" stubs; nipple up well he</li> <li>Pick up 3 ¼" bit and tubing; Clean out cement plugs (0-147' and 1 Continue to PBTD at 4500'.</li> <li>Run 4 1/2" internally coated packer &amp; 2 3/8" Internally coated tu 4430' (PERFS : 4480'- 4483')- test for injectivity. 1/6/2015Test ann</li> </ol>	620'-1760'), cement and CIBP at 4400'. bing to Julus as required by State of New Mexico,
<ol> <li>Dig out old cellar- weld on 8 5/8" and 4 ½" stubs; nipple up well he</li> <li>Pick up 3 ¾" bit and tubing; Clean out cement plugs (0-147' and 1 Continue to PBTD at 4500'.</li> <li>Run 4 1/2" internally coated packer &amp; 2 3/8" Internally coated tu 4430' (PERFS : 4480'- 4483')- test for injectivity. 1/6/2015Test ann Witnessed by NM OCD</li> </ol>	620'-1760'), cement and CIBP at 4400'. bing to Julus as required by State of New Mexico,
<ol> <li>Dig out old cellar- weld on 8 5/8" and 4 ½" stubs; nipple up well he</li> <li>Pick up 3 ½" bit and tubing; Clean out cement plugs (0-147' and 1 Continue to PBTD at 4500'.</li> <li>Run 4 1/2" internally coated packer &amp; 2 3/8" Internally coated tu 4430' (PERFS : 4480'- 4483')- test for injectivity. 1/6/2015Test ann Witnessed by NM OCD</li> <li>Install injection line and place well in service.</li> </ol>	.620'-1760'), cement and CIBP at 4400'. bing to Julus as required by State of New Mexico,
<ol> <li>Dig out old cellar- weld on 8 5/8" and 4 ½" stubs; nipple up well he</li> <li>Pick up 3 ¼" bit and tubing; Clean out cement plugs (0-147' and 1 Continue to PBTD at 4500'.</li> <li>Run 4 1/2" internally coated packer &amp; 2 3/8" Internally coated tu 4430' (PERFS : 4480'- 4483')- test for injectivity. 1/6/2015Test ann Witnessed by NM OCD MITCHART #/6/2015</li> <li>Install injection line and place well in service. Note: This well will be known as the Reeves-Queen Waterflood I</li> </ol>	.620'-1760'), cement and CIBP at 4400'. bing to Julus as required by State of New Mexico, Unit #2 (Order # R-13785, Case # 15048)
<ol> <li>Dig out old cellar- weld on 8 5/8" and 4 ½" stubs; nipple up well he</li> <li>Pick up 3 ½" bit and tubing; Clean out cement plugs (0-147' and 1 Continue to PBTD at 4500'.</li> <li>Run 4 1/2" internally coated packer &amp; 2 3/8" Internally coated tu 4430' (PERFS : 4480'- 4483')- test for injectivity. 1/6/2015Test ann Witnessed by NM OCD MITCHART #/6/2015</li> <li>Install injection line and place well in service. Note: This well will be known as the Reeves-Queen Waterflood II L hereby certify that the information above is true and complete to the best of my k</li> </ol>	.620'-1760'), cement and CIBP at 4400'. bing to sulus as required by State of New Mexico, <b>Unit #2 (Order # R-13785, Case # 15048)</b> mowledge and belief. I further certify that any pit or below-
<ol> <li>Dig out old cellar- weld on 8 5/8" and 4 ½" stubs; nipple up well he</li> <li>Pick up 3 ½" bit and tubing; Clean out cement plugs (0-147' and 1 Continue to PBTD at 4500'.</li> <li>Run 4 1/2" internally coated packer &amp; 2 3/8" Internally coated tu 4430' (PERFS : 4480'- 4483')- test for injectivity. 1/6/2015Test ann Witnessed by NM OCD</li> <li>Install injection line and place well in service. Note: This well will be known as the Reeves-Queen Waterflood II I hereby certify that the information above is true and complete to the best of my k grade tank has been/will be constructed or closed according to NMOCD guidelines [], a general</li> </ol>	.620'-1760'), cement and CIBP at 4400'. bing to sulus as required by State of New Mexico, <b>Unit #2 (Order # R-13785, Case # 15048)</b> mowledge and belief. I further certify that any pit or below- permit [] or an (attached) alternative OCD-approved plan [].
<ol> <li>Dig out old cellar- weld on 8 5/8" and 4 ½" stubs; nipple up well he</li> <li>Pick up 3 ½" bit and tubing; Clean out cement plugs (0-147' and 1 Continue to PBTD at 4500'.</li> <li>Run 4 1/2" internally coated packer &amp; 2 3/8" Internally coated tu 4430' (PERFS : 4480'- 4483')- test for injectivity. 1/6/2015Test ann Witnessed by NM OCD WITT Charle 1/6/2015Test ann Witnessed by NM OCD WITT Charle 1/6/2015Test</li> <li>Install injection line and place well in service. Note: This well will be known as the Reeves-Queen Waterflood I I hereby certify that the information above is true and complete to the best of my k grade tank has been/will be constructed or closed according to NMOCD guidelines [], a general SIGNATURE</li> </ol>	.620'-1760'), cement and CIBP at 4400'. bing to ulus as required by State of New Mexico, Unit #2 (Order # R-13785, Case # 15048) mowledge and belief. I further certify that any pit or below- permit [] or an (attached) alternative OCD-approved plan []. ASST. DATE 2/18/2015
<ul> <li>1- Dig out old cellar- weld on 8 5/8" and 4 ½" stubs; nipple up well he</li> <li>2- Pick up 3 ½" bit and tubing; Clean out cement plugs (0-147' and 1 Continue to PBTD at 4500'.</li> <li>3- Run 4 1/2" internally coated packer &amp; 2 3/8" Internally coated tu 4430' (PERFS : 4480'- 4483')- test for injectivity. 1/6/2015Test ann Witnessed by NM OCD PTTChard 1/6/2015Test ann Witnessed by NM OCD PTTChard 1/6/2015Test</li> <li>4- Install injection line and place well in service. Note: This well will be known as the Reeves-Queen Waterflood I I hereby certify that the information above is true and complete to the best of my k grade tank has been/will be constructed or closed according to NMOCD guidelines ], a general SIGNATURE</li></ul>	.620'-1760'), cement and CIBP at 4400'. bing to sulus as required by State of New Mexico, <b>Unit #2 (Order # R-13785, Case # 15048)</b> mowledge and belief. I further certify that any pit or below- permit [] or an (attached) alternative OCD-approved plan [].
<ol> <li>Dig out old cellar- weld on 8 5/8" and 4 %" stubs; nipple up well he</li> <li>Pick up 3 %" bit and tubing; Clean out cement plugs (0-147' and 1 Continue to PBTD at 4500'.</li> <li>Run 4 1/2" internally coated packer &amp; 2 3/8" Internally coated tu 4430' (PERFS : 4480'- 4483')- test for injectivity. 1/6/2015Test ann Witnessed by NM OCD WITTELE 1/6/2015Test ann Witnessed by NM OCD WITTELE 1/6/2015</li> <li>Install injection line and place well in service. Note: This well will be known as the Reeves-Queen Waterflood I I hereby certify that the information above is true and complete to the best of my k grade tank has been/will be constructed or closed according to NMOCD guidelines [], a general SIGNATURE</li></ol>	.620'-1760'), cement and CIBP at 4400'. bing to ulus as required by State of New Mexico, Unit #2 (Order # R-13785, Case # 15048) mowledge and belief. I further certify that any pit or below- permit
<ol> <li>Dig out old cellar- weld on 8 5/8" and 4 ½" stubs; nipple up well he</li> <li>Pick up 3 ½" bit and tubing; Clean out cement plugs (0-147' and 1 Continue to PBTD at 4500'.</li> <li>Run 4 1/2" internally coated packer &amp; 2 3/8" Internally coated tu 4430' (PERFS : 4480'- 4483')- test for injectivity. 1/6/2015Test ann Witnessed by NM OCD FOLT Charlet 1/6/2015</li> <li>Install injection line and place well in service. Note: This well will be known as the Reeves-Queen Waterflood I I hereby certify that the information above is true and complete to the best of my k grade tank has bega/will be constructed or closed according to NMOCD guidelines ], a general SIGNATURE BELINDA BRADLEY E-mail address: bbradley@sunde For State Use Only APPROVED BY: Mit Market State Stat</li></ol>	.620'-1760'), cement and CIBP at 4400'. bing to ulus as required by State of New Mexico, Unit #2 (Order # R-13785, Case # 15048) mowledge and belief. I further certify that any pit or below- permit
<ol> <li>Dig out old cellar- weld on 8 5/8" and 4 ½" stubs; nipple up well he</li> <li>Pick up 3 ¾" bit and tubing; Clean out cement plugs (0-147' and 1 Continue to PBTD at 4500'.</li> <li>Run 4 1/2" internally coated packer &amp; 2 3/8" Internally coated tu 4430' (PERFS : 4480'- 4483')- test for injectivity. 1/6/2015Test ann Witnessed by NM OCD MITCHERED 1/6/2015</li> <li>Install injection line and place well in service. Note: This well will be known as the Reeves-Queen Waterflood II I hereby certify that the information above is true and complete to the best of my k grade tank has been/will be constructed or classed according to NMOCD guidelines ], a general SIGNATURE</li></ol>	.620'-1760'), cement and CIBP at 4400'.         bing to         nulus as required by State of New Mexico,         Unit #2 (Order # R-13785, Case # 15048)         unowledge and belief. I further certify that any pit or below-permit □ or an (attached) alternative OCD-approved plan □.         ASST.       DATE 2/18/2015         ownenergy.com Telephone No. 432-943-8770         Y       Mauage         DATE       State S
<ol> <li>Dig out old cellar- weld on 8 5/8" and 4 %" stubs; nipple up well he</li> <li>Pick up 3 %" bit and tubing; Clean out cement plugs (0-147' and 1 Continue to PBTD at 4500'.</li> <li>Run 4 1/2" internally coated packer &amp; 2 3/8" Internally coated tu 4430' (PERFS : 4480'- 4483')- test for injectivity. 1/6/2015Test ann Witnessed by NM OCD POINT Chart 8/6/2015</li> <li>Install injection line and place well in service. Note: This well will be known as the Reeves-Queen Waterflood I I hereby certify that the information above is true and complete to the best of my k grade tank has been/will be constructed or closed according to NMOCD guidelines ], a general SIGNATURE TITLE ADMIN. TITLE ADMIN. A Type or print name BELINDA BRADLEY E-mail address: bbradley@sunde For State Use Only APPROVED BY:</li></ol>	.620'-1760'), cement and CIBP at 4400'. bing to sulus as required by State of New Mexico, Unit #2 (Order # R-13785, Case # 15048) mowledge and belief. I further certify that any pit or below- permit □ or an (attached) alternative OCD-approved plan □. ASSTDATE2/18/2015 pwmenergy.com Telephone No. 432-943-8770 PERMITTING_ <swdinjection≥< td=""></swdinjection≥<>
<ol> <li>Dig out old cellar- weld on 8 5/8" and 4 %" stubs; nipple up well he</li> <li>Pick up 3 %" bit and tubing; Clean out cement plugs (0-147' and 1 Continue to PBTD at 4500'.</li> <li>Run 4 1/2" internally coated packer &amp; 2 3/8" Internally coated tu 4430' (PERFS : 4480'- 4483')- test for injectivity. 1/6/2015Test ann Witnessed by NM OCD POST Chart 1/6/2015Test ann BELINDA BRADLEY E-mail address: bbradley@sund For State Use Only APPROVED BY:</li></ol>	.620'-1760'), cement and CIBP at 4400'. bing to sulus as required by State of New Mexico, Unit #2 (Order # R-13785, Case # 15048) snowledge and belief. I further certify that any pit or below- permit □ or an (attached) alternative OCD-approved plan □. ASSTDATE2/18/2015 ownenergy.com Telephone No. 432-943-8770 PERMITTING <swd injection=""> DNVERSION QMARBDMS,</swd>
<ol> <li>Dig out old cellar- weld on 8 5/8" and 4 %" stubs; nipple up well he</li> <li>Pick up 3 %" bit and tubing; Clean out cement plugs (0-147' and 1 Continue to PBTD at 4500'.</li> <li>Run 4 1/2" internally coated packer &amp; 2 3/8" Internally coated tu 4430' (PERFS : 4480'- 4483')- test for injectivity. 1/6/2015Test ann Witnessed by NM OCD POST Crearl 8/6/2015</li> <li>Install injection line and place well in service. Note: This well will be known as the Reeves-Queen Waterflood I I hereby certify that the information above is true and complete to the best of my k grade tank has been/will be constructed or classed according to NMOCD guidelines ], a general SIGNATURE BELINDA BRADLEY E-mail address: bbradley@sunde For State Use Only</li> <li>APPROVED BY: Mit Decomposed (if any):</li> </ol>	.620'-1760'), cement and CIBP at 4400'. bing to sulus as required by State of New Mexico, Unit #2 (Order # R-13785, Case # 15048) mowledge and belief. I further certify that any pit or below- permit □ or an (attached) alternative OCD-approved plan □. ASSTDATE2/18/2015 pwmenergy.com Telephone No. 432-943-8770 PERMITTING_ <swdinjection≥< td=""></swdinjection≥<>

.

۰.

,	_			
	MAY	2	8	JŲ€

^			WELL DA	TA SHEET			
LEASE:	REEVES-QUEEN WATERFLO		.: 2	_	FIELD:	REEVES (QUEEN	<u>N)</u>
LOC: STATUS: TD: PBTD: COTD:	330' FNL & 1650' FEL Injection 4560' 4500	UNIT B SEC: CO: ST:	28 T: LEA NM	18S R: 36E	SURVEY: API NO: LEASE #	30-025-29526	
Spud Date: Comp.Date: GL: DF: KB:				Csg Detail: Hole Size: <u>8-5/8</u> Csg set @ Circ? YES	475' w/	_#/ft, grade	K-55
				Hole Size: 4-1/2"OI csg set @ In Stage 1 circ? Stage 2 circ?	7-7/8 ), 4559' w/ stages w/D TOC TOC	V tool @ By	K-55
		X	et se	ter to developed to	£75 ( €5		
		X	×		IPC tbg set in set pkr @ 4410		
				Queen Peri PBTD 4500 <b>TD 4560'</b>	's 4480' - 4483 )'	bb 2/16/15	
		Z	7				-

· 1+

: