Submit 1 Copy To Appropriate District State of New Mexico Form C-103 Office Revised August 1, 2011 Energy, Minerals and Natural Resources District I - (575) 393-6161 WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283 30-025-23941 OIL CONSERVATION DIVISION 811 S. First St., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III - (505) 334-6178 STATE FEE 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Hill A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well Number 008 1. Type of Well: Oil Well X Gas Well Other 2. Name of Operator 9. OGRID Number Mar Oil & Gas Corporation 151228 3. Address of Operator 10. Pool name or Wildcat PO Box 5155 Santa Fe, NM 87502 Eumont; Yates, 7Rvrs, Queen 4. Well Location : 3630 South-- line and \_\_\_ Unit Letter feet from the 877 feet from the- West line Township **21S** Range 37E **NMPM** County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING □ **TEMPORARILY ABANDON** CHANGE PLANS COMMENCE DRILLING OPNS. P AND A XX PULL OR ALTER CASING MULTIPLE COMPL П CASING/CEMENT JOB  $\Box$ DOWNHOLE COMMINGLE OTHER: Location is ready for OCD inspection after P&A All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. | Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OUARTER/OUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from nonretrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to schedule an inspection. I hereby certify that the information above is true and complete to the best of my knowledge and belief. **TITLE Field Supervisor SIGNATURE** Type or print name Billy E. Prichard E-mail address: billy@pwllc.net PHONE: 432-934-7680 For State Use Only

.015 Y