Submit I Copy To Appropriate District Office	State of New Mexico	Form C-103			
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural R	Revised July 18, 2013 WELL API NO.			
<u>District II</u> – (575) 748-1283	OIL CONSERVATION DIV	30-025-23868			
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	1220 South St. Francis I	5. Indicate Type of Lease			
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505		STATE 6. State Oil & Gas	FEE 🔯	
1220 S. St. Francis Dr., Santa Fe, NM 87505	Sunta 1 0, 1 1.1.1 0 / 3 0 3		309574	Bouse 110.	
(DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.) 1. Type of Well: Oil Well 2. Name of Operator	Gas Well Other INJECTOR	HOBBS OCI	LANGLIE JAL 8. Well Number 79. OGRID Number	49 /	
3. Address of Operator	SERVES OPERATING LP		10. Pool name or V	510271	
	8, MIDLAND, TX 79702	RECEIVED			
4. Well Location					
Unit Letter <u>H</u> : Section 6	1980 feet from the <u>NORTH</u> Township 25S Ra	line and nge 37E	510feet from the NMPM	he <u>EAST</u> line County LEA	
Section 0	11. Elevation (Show whether DR, RKB			County LEA	
	3229' GR				
12. Check A	appropriate Box to Indicate Nature	e of Notice,	Report or Other D	D ata	
NOTICE OF IN	· · · · · · · · · · · · · · · · · · ·	E-PERI	MITTING <swd< td=""><td>INJECTION></td></swd<>	INJECTION>	
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON ☑ REM CHANGE PLANS ☐ COM	ONVE	RSION	RBDMS	
PULL OR ALTER CASING	MULTIPLE COMPL CAS	KEIUK	RN TO	TA	
DOWNHOLE COMMINGLE		CSNG_ INT TO	A DRANG	CHG LOC	
CLOSED-LOOP SYSTEM OTHER:	П ОТЬ	lek:	PA PA NE	RP&A R	
13. Describe proposed or compl	eted operations. (Clearly state all pertine	ent details, and			
of starting any proposed wo proposed completion or reco	rk). SEE RULE 19.15.7.14 NMAC. For	r Multiple Coi	mpletions: Attach we	Ilbore diagram of	
proposed compression of reco	Ang terroin.				
SEE ATTACHED P&A PR	OCEDURE ALONG WITH CURRENT	& PROPOSE	ED WELLBORE DIA	GRAMS	
	•			,	
		7	The Oil Conservati	ion Division	
			UST BE NOTIFI		
		Prio	or to the begi <mark>nnin</mark> g	g of operations	
Spud Date:	Rig Release Date:			7	
Spud Date.	Trig release Suite.		<u>.</u>		
I hereby certify that the information a	above is true and complete to the best of	my knowledg	e and belief.		
Laura for To					
SIGNATURE WWW VV9	TITLEREGU	JLATORY TI	ECH ,DATI	E_ <u>07/01/2015</u>	
Type or print nameLAURA PIN	E-mail address:lpina	a@legacylp.co	omPHO	NE: <u>432-689-5200</u>	
For State Use Only	٧٠ ١٠		•	-1.1-	
APPROVED BY: Conditions of Approval (If ary):	lown TITLE DIST	Duper	WUOU DAT	E 7/7/2015	

PROCEDURE TO PLUG AND ABANDON

Langlie Jal Unit #49
Langlie Mattix (7-Rivers, & Queen) Field
Lea County, New Mexico
6/19/15
AFE# 615030

GENERAL WELL DATA


- GL 3229'
- 8-5/8" 30# surface csg @ 824' w/475 sxs. TOC @ surface
- 4-1/2" 9.5# or 10.5# prod. csg @ 3575' w/1200 sxs. TOC @ surface
- TD @ 3600'
- PBTD @ 3572'
- Queen Perfs: 3318'-3551'

OBJECTIVE: Plug and Abandon Well.


PROCEDURE

- 1. Hold Safety Meeting. High concentrations of H2S may be present. MIRU plugging equipment.
- 2. Dig out cellar. Kill well if necessary and ND WH, remove any tubing joints, and NU BOP.
- 3. PU work string and RIH to PBTD @ 3076'.
- 4. Circulate well with mud.
- 5. Set 350' cmt plug (2726'-3076') w/ 27 sxs.
- 6. PU to 1400' and set 300' cmt plug (1100'-1400') w/23 sxs. WOC and tag.
- 7. PU to 874' and set 100' cmt plug (774'-874') w/ 10 sxs. WOC and tag.
- 8. PU to 350' and set 350' cmt plug to surface w/ 27 sxs.
- 9. RDMO plugging equipment.
- 10. ND BOP
- 11. Cut off wellhead and weld on marker.

PREPARED BY:	_R Peña Jr	DATE:6-19-15			
APPROVED BY:	•	DATE:			



LEASE:	LJU	RESERVOIRS	PERFOR	ATIONS	CASING			SPUD DATE: 10/2/1971		
WELL	49	ANHYDRITE	TOP	BTM	SIZE	WT	GRD	CSA	COMP DATE: 4/4/1972	
API #:	30-025-23868	SALT	1		ELEVATION		ONS			
		YATES	ľ				see below		KB:	
FIELD:	Langlie Mattix	SEVEN RIVERS	see below						GL:	3229
LOCATION	:	QUEEN							DF:	
•	Sec 6 35S 37E					TU	JBING		UPDATED: 1	/1/2009
	LEA COUNTY, NM								BY: K	AS .
Directions to Location :		TOP OF PAY	ł				see below			
1980 N, 510 E										



PBTD: 3572 TD: 3600