Submit 3 Copies To Appropriate DistrictState of New MexicoOfficeEnergy, Minerals and Natural ResourcesDistrict 11625 N. French Dr., Hobbs, NM 87240		Form C-103 June 19, 2008
		WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATIO	N DIVISION	30-025-41551
District III 1220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM District IV	87505	STATE FEE X
1220 S. St. Francis Dr., Santa Fe, NM 87505		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUGH PROPOSALS.)		7. Lease Name or Unit Agreement Name:
		North Hobbs G/SA Unit
1. Type of Well:		8. Well Number
Oil Well Image: Constraint of Constraints 2. Name of Operator	<u>FJUL 1 5 2015</u>	947 / 9. OGRID Number
Occidental Permian Ltd.		157984
3. Address of Operator	RECEIVED	10. Pool name or Wildcat
P.O. Box 4294, Houston, TX 77210-4294		Hobbs: Grayburg-San Andres
4. Well Location		
Unit Letter <u>A : 278</u> feet from the <u>No</u>	orth line and	<u>1123</u> feet from the <u>East</u> line
Section 19 Township 18-S Range 38-E NMPM County Lea		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3661.6' GR		
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data		
NOTICE OF INTENTION TO: SUBSE		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A		
)THER:	OTHER:	
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 		
MI x RU pulling unit. Circ. well w/130 bbls. 10# brine. ND WH x NU BOP. RU spooler x POOH w/ESP		
equipment x production tubing. Found pump and gas separator locked w/scale. RD spooler x RIH w/6-1/8"		
bit x 7" scraper. Worked scraper from 4200'-4595'. POOH w/bit x scraper and RIH w/7" packer x set at		
4303'. Pump scale squeeze of 213 gal. EC6490A mixed w/130 bbls FW x flush w/144 bbls FW. POOH with packer. PU x RIH w/Centrilift 400 ESP equipment on 130 jts. 2-7/8" production tubing (S/N @ 4240').		
ND BOP x NU WH. Test tree to 5000 psi. Install surface equipment x hook up flowline. RD x MO x clean		
location.		
· · · · · · · · · · · · · · · · · · ·		
Spud Date: RUPU - 6/12/15 Rig Rela	ease Date: RDF	PU - 6/17/15
hereby certify that the information above is true and complete to the	ie best of my knowledg	e and belief.
IGNATURE		
ype or print name <u>Mark Stephens</u> E-	mail address:	
For State Use Only		
APPROVED BY		
Conditions of Approval (if any)		

JUL 2 1 2015

M