State of New Mexico Energy, Minerals & Natural Resources

rorm C-101 June 16, 2008

HOBBS OCD

Oil Conservation Divsiion 1220 S. St. Francis Dr. JUL 1 7 2015 Submit to appropriate District Office

istrict IV

625 N. French Dr., Hobbs, NM 88240

000 Rio Brazos Rd., Aztec, NM 87410

301 W. Grand Avenue, Artesia, NM 88210

District 1

District III

20 S. St. Francis Dr., Santa Fe, NM 87505				Santa Fe, NN			☐ AME	INDED REPORT		
APPLICA PLUGBA(TION F CK, OR	OR ADI	PERN D A Z	MIT TO ONE	DRILI	L, RE-ENTEI	R, DEEPEN _{RE}	Cenned		
			¹ Opera	tor Name and	l Address				² OGRID Numbe 157984	r
Occidental	${\tt Permian}$	Ltd.								
P.O. Box 42	294, Hous	ston,	TX 7	7210-429	4			30- 025	3 API Number	97
⁴ Proper 195	-	•			So	⁵ Property Nam uth Hobbs G/SA		⁶ Well No. 259		
Hobb	os; Grayl		posed Po - San	oll Andres (31920)			¹⁰ Proposed P	ool 2	
Surface Lo	cation									
UL or lot no.	Section	Tow	nship	Range	Lot. Idn	Feet from the	North/South Line	Feet from the	East/West line	County
I	4	1	9-S	38-E		2018	South	557	East	Lea
Proposed E	Bottom F	Iole I	Locati	on If Dif	ferent l	From Surface				
UL or lot no.	Section	Tow	nship	Range	Lot. Idn	Feet from the	North/South Line	Feet from the	East/West line	County
L	3	1	9-5	38-E		1384	South	1191	West	Lea
dditional V	Vell Loc	ation	1							
II Work Type Code N			12 Well Type Code		13 Cable/Rotary	y ¹⁴ Lea	14 Lease Type Code D		Ground Level Elevation 3612.0'	
16 Multiple		17 [17 Proposed Depth		18 Formation	19	19 Contractor		20 Spud Date	
No			4550'TVD/5080' MD		San Andre		H&P 340		12/7/15	
Proposed (Casing a	nd C	ement	Progran	n					

Hole Size	Casing Size	Casing weight/foot	Setting Depth	Sacks of Cement	Estimated TOC
12-1/4	9-5/8	36	1700	640	Surface
8-3/4	7	26	5080	830	Surface

² Describe the proposed program. If this application is to DEEPEN or PLUG BACK, give the data on the present productive zone and proposed new productive zone. Describe the blowout prevention program, if any. Use additional sheets if necessary.

See attached for BOP program.

Oxy will use a closed-loop system with steel tanks and haul contents to the required disposal facility per OCD Rule 19.15.17 (closed-loop system schematic is also attached).

I hereby certify of my knowledge	that the information given above is true and complete to the best and belief.	OIL CONSERVATION DIVISION		
ignature:	MarkStephen	Approved by:		
rinted name:	Mark Stephens	Title: Petroleum Engineer		
`itle:	Regulatory Compliance Analyst	Approval Date: 07/21/15 Expiration Date: 07/21/17		
-mail Address:	Mark_Stephens@oxy.com	///		
Date: 7/15/15	Phone: (713) 366-5158	Conditions of Approval Attached		

CONDITIONS OF APPROVAL

API#	Operator	Well name & Number
30-025-42697	Occidental Permian LTD	South Hobbs G/SA Unit # 259

Applicable conditions of approval marked with XXXXXX

Administrative Orders Required

XXXXXXX	If within City Limits No Pits – Must use close loop		
XXXXXXX	Will require administrative order for injection or disposal prior to injection or disposal		

Other wells

Drilling

XXXXXXX	Once the well is spud, to prevent ground water contamination through whole or partial conduits from the surface,
	the operator shall drill without interruption through the fresh water zone or zones and shall immediately set in
	cement the water protection string

Casing

XXXXXXX	SURFACE CASING - Cement must circulate to surface
XXXXXX	PRODUCTION CASING - Cement must circulate to surface
XXXXXXX	If cement does not circulate to surface, must run temperature survey or other log to determine top of cement
	South Area
XXXXXXX	Surface casing must be set 25' below top of Rustler Anhydrite in order to seal off protectable water

Completion & Production

XXXXXX	Must notify Hobbs OCD office prior to conducting MIT (575) 393-6161 ext. 114		
XXXXXX	Must conduct & pass MIT prior to any injection		

Lost Circulation

XXXXXXX	Must notify OCD Hobbs Office if lost circulation is encountered at 575-370-3186

Stage Tool

XXXXXX	Must notify OCD Hobbs Office prior to running Stage Tool at 575-370-3186
XXXXXXX	If using Stage Tool on Surface casing, Stage Tool must be greater than 350' and a minimum 200 feet above surface shoe.
XXXXXXX	When using a Stage Tool on Intermediate or Production Casing Stage must be a minimum of 50 feet below previous casing shoe.