

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD Hopps

FORM APPROVED OMB NO. 1004-0135-Expires: July 31, 2010

5. Lease Serial No. NMNM27506

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

				INIVINIVI27506
				6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on revers			JL 2 1 20	7. If Unit or CA/Agreement, Name and/or No. NMNM134673
Type of Well		RECEIVED	8. Well Name and No. MOOSES TOOTH 29 26 33 FED COM 1H	
Name of Operator CHEVRON USA INCORPORA	DY H MURILLO JRILLO@CHEVRON.COM		9. API Well No. 30-025-42168-00-S1	
3a. Address 15 SMITH ROAD MIDLAND, TX 79705	Phone No. (include area code): 575-263-0431: 575-263-0445		10. Field and Pool, or Exploratory WC-025 G-07 S263329D	
4. Location of Well (Footage, Sec., T			11. County or Parish, and State	
Sec 29 T26S R33E NWNW 20 32.021087 N Lat, 103.601275			LEA COUNTY, NM	
12. CHECK APPI	ROPRIATE BOX(ES) TO IN	DICATE NATURE OF I	NOTICE, RI	EPORT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION				
Notice of Intent	☐ Acidize	□ Deepen	☐ Product	ion (Start/Resume)
	☐ Alter Casing	☐ Fracture Treat	□ Reclama	ation .
☐ Subsequent Report	Casing Repair .	■ New Construction	□ Recomp	olete ' Other '
☐ Final Abandonment Notice	□ Change Plans	Plug and Abandon	□ Tempor	arily Abandon
	□ Convert to Injection	□ Plug Back	■ Water D	Disposal
If the proposal is to deepen directional Attach the Bond under which the work following completion of the involved	ally or recomplete horizontally, give rk will be performed or provide the E operations. If the operation results i condoment Notices shall be filed on inal inspection.) It to perform a cement job Brack 5/8" casing riser. Ensure that 5K valve to 250 PSI low and 3 SI. and pump as per the following ead (or combination flush/wate essary). Use dispersants. surface centrifugal). Stay at the max active and correct.	subsurface locations and measure and No. on file with BLM/BLA in a multiple completion or receip after all requirements, included the casing riser and valve the casing riser and valve on the set pump of schedule: g schedule: er), establish injection rate than the blender in first 10 blender to the suction side chieved injection rate.	and true ve Required sub impletion in a r ing reclamation above well. es are rated Kickout to 13 es/pressures os if of one pump	350 S
Со	Electronic Submission #2877 For CHEVRON USA mmitted to AFMSS for process	INCORPORATED, sent to ing by LINDA JIMENEZ on	the Hobbs 04/13/2015 (1	15LJ0909SE)
Name(Printed/Typed) CINDY H MURILLO		. Title PERMI	TTING SPEC	JIALIST
Signature (Electronic S	Submission)	Date 01/13/2	015	
	THIS SPACE FOR F	EDERAL OR STATE	OFFICE US	SE W
Approved By CHRISTOPHER WA Conditions of approval, if any, are attache certify that the applicant holds legal or equ which would entitle the applicant to condu	varrant or ect lease Office Hobbs	UM ENGINE	EER Date 07/15/2015	
which would entitle the applicant to condu	Office Hopps			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.







Additional data for EC transaction #287760 that would not fit on the form

32. Additional remarks, continued

c. Pump 5 bbls water spacer.(Stay at the mas achieved injection rate).

d. Pump 13.0 ppg Cement as follows: Actual
e. Pump volume to shoe (225 bbls) at 3 bpm or max injection rate

f. Slow rate down to 0.5-1 bpm and pump 16 bbls to estimated TOC @ 5190'.

- g. Shut down for 5 minutes and monitor pressure. If well goes on vacuum then shut down for 30 minutes and allow cement to fall/start to gel up.

 h. Pump slowly until catch pressure and for last 15 bbls, pump 5 bbls and shut down for 5 min
- monitor pressure.
- i. If pressure reaches initial injection pressure, wash up and attempt to pump1 bbls down riser to clear. If well is still on vacuum at end of job do not fill up, but allow to fall and find a level.
- 4. SI the well and wash up lines. RDMO cement equipment. Well to be SI for 24 hrs allowing cement to build desired compressive strength.
- 5. After 24 hrs WODC. MOB and kill truck and pressure test intermediate-production casing annulus to 1,000 PSI (250 PSI steps). Hold and chart test for 30 minutes. If could not hold pressure, consult the CE before moving to the Run RCBL/CCL/GR/Log.

 ******Chevron has contacted Chris Walls on 01/09/2015 and Chris has given verbal approved for the
- bardenhead squeeze****

If you have any questions, please contact Said Daher at 713-372-0233