		BSOC
Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103
Office District I – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240	001	WELL API NO.
District II - (575) 748-1283	OIL CONCEDUATION DIVISION	30-025-31653
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	EVED STATE STATE
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE
District IV – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		
87505		19207
SUNDRY NO	TICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
	ICATION FOR PERMIT" (FORM C-101) FOR SUCH	Dagger Lake 5 State
PROPOSALS.)	Gas Wall Cother	8. Well Number
1. Type of Well: Oil Well	Gas Well Other	o. Well Humber
		a contrav
2. Name of Operator		9. OGRID Number
	Amtex Energy, Inc.	000785
Address of Operator		10. Pool name or Wildcat
	P.O. Box 3418, Midland, TX 79702	Dagger Lake Delaware
4. Well Location		
	feet from the South line and 1980	0 feet from the East line
Section 5	Township 22S Range 33E NMPM	Lea County
	11. Elevation (Show whether DR, RKB, RT, GR, etc.	
	KB 3661'	是一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个
		The state of the
12 Charle	Appropriate Box to Indicate Nature of Notice	Panart or Other Data
12. CHeck	Appropriate Box to Indicate Nature of Notice,	, Report of Other Data
NOTICE OF I	NTENTION TO: SUE	SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		
TEMPORARILY ABANDON		RILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEMEN	IT JOB
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM		
CLOSED-LOOP SYSTEM OTHER:		orarily Abandon
OTHER:	☐ OTHER: Temp	orarily Abandon
OTHER: 13. Describe proposed or com	D OTHER: Temporal pleted operations. (Clearly state all pertinent details, and	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed v	pleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com	pleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re	OTHER: Tempor pleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion.	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 1. MIRU TFH Renta	OTHER: Tempor pleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion.	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 1. MIRU TFH Renta	OTHER: Tempor pleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion.	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or come of starting any proposed we proposed completion or result. 1. MIRU TFH Rentation 2. Load Casing w/ we will be supposed to the completion of the complete of the complet	oTHER: Temper pleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Contended in the completion. In Tools 10/20/2015 water and pressure tested to 570-560 psi, respectively.	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or come of starting any proposed we proposed completion or result. 1. MIRU TFH Renta 2. Load Casing w/ we more than 30 minst	OTHER: Tempor pleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion. all Tools 10/20/2015 water and pressure tested to 570-560 psi, respectively.	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or come of starting any proposed we proposed completion or results. 1. MIRU TFH Renta 2. Load Casing w/ we more than 30 mins 3. Attached record of	OTHER: Temper pleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Coecompletion. If Tools 10/20/2015 water and pressure tested to 570-560 psi, respectively. If the property of the p	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or come of starting any proposed we proposed completion or results. 1. MIRU TFH Renta 2. Load Casing w/ we more than 30 mins 3. Attached record of 4. CIBP @ 4,910' we	orher: Tempor pleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion. all Tools 10/20/2015 rater and pressure tested to 570-560 psi, respectively. The original Chart Recorder. 7 35' cmt. on top.	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or come of starting any proposed we proposed completion or results. 1. MIRU TFH Renta 2. Load Casing w/ we more than 30 mins 3. Attached record of	orher: Tempor pleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion. all Tools 10/20/2015 rater and pressure tested to 570-560 psi, respectively. The original Chart Recorder. 7 35' cmt. on top.	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or come of starting any proposed we proposed completion or results. 1. MIRU TFH Renta 2. Load Casing w/ we more than 30 mins 3. Attached record of 4. CIBP @ 4,910' we	orher: Tempor pleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion. all Tools 10/20/2015 rater and pressure tested to 570-560 psi, respectively. The original Chart Recorder. 7 35' cmt. on top.	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or come of starting any proposed we proposed completion or results. 1. MIRU TFH Renta 2. Load Casing w/ we more than 30 mins 3. Attached record of 4. CIBP @ 4,910' we 5. Perfs @ 4,951'- 4	OTHER: Tempor pleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion. If Tools 10/20/2015 water and pressure tested to 570-560 psi, respectively. The properties of the properties	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or come of starting any proposed we proposed completion or results. 1. MIRU TFH Renta 2. Load Casing w/ we more than 30 mins 3. Attached record of 4. CIBP @ 4,910' we	OTHER: Tempor pleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion. If Tools 10/20/2015 water and pressure tested to 570-560 psi, respectively. The properties of the properties	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or come of starting any proposed we proposed completion or results. 1. MIRU TFH Renta 2. Load Casing w/ we more than 30 mins 3. Attached record of 4. CIBP @ 4,910' we 5. Perfs @ 4,951'- 4	OTHER: Tempor pleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion. If Tools 10/20/2015 water and pressure tested to 570-560 psi, respectively. The properties of the properties	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
oTHER: 13. Describe proposed or come of starting any proposed we proposed completion or results. 1. MIRU TFH Renta 2. Load Casing w/ we more than 30 mins 3. Attached record of 4. CIBP @ 4,910' we 5. Perfs @ 4,951'- 4. CIBP within 100' of proposed or come of starting any proposed within 100' of proposed or come of starting any proposed within 100' of proposed or come of starting any proposed or come of starting any proposed within 100' of proposed or come of starting any proposed within 100' of proposed within 100' of proposed or completion or research within 100' of proposed or completion or research within 100' of proposed within 100' of prop	OTHER: Tempor pleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion. All Tools 10/20/2015 rater and pressure tested to 570-560 psi, respectively. The properties of the properties	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or come of starting any proposed we proposed completion or results. 1. MIRU TFH Renta 2. Load Casing w/ we more than 30 mins 3. Attached record of 4. CIBP @ 4,910' we 5. Perfs @ 4,951'- 4	OTHER: Tempor pleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion. If Tools 10/20/2015 water and pressure tested to 570-560 psi, respectively. The properties of the properties	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
oTHER: 13. Describe proposed or come of starting any proposed we proposed completion or results. 1. MIRU TFH Renta 2. Load Casing w/ we more than 30 mins 3. Attached record of 4. CIBP @ 4,910' we 5. Perfs @ 4,951'- 4. CIBP within 100' of proposed or come of starting any proposed within 100' of proposed or come of starting any proposed within 100' of proposed or come of starting any proposed or come of starting any proposed within 100' of proposed or come of starting any proposed within 100' of proposed within 100' of proposed or completion or research within 100' of proposed or completion or research within 100' of proposed within 100' of prop	OTHER: Tempor pleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion. All Tools 10/20/2015 rater and pressure tested to 570-560 psi, respectively. The properties of the properties	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
oTHER: 13. Describe proposed or come of starting any proposed we proposed completion or results. 1. MIRU TFH Renta 2. Load Casing w/ we more than 30 mins 3. Attached record of 4. CIBP @ 4,910' we 5. Perfs @ 4,951'- 4. CIBP within 100' of proposed or come of starting any proposed within 100' of proposed or come of starting any proposed within 100' of proposed or come of starting any proposed or come of starting any proposed within 100' of proposed or come of starting any proposed within 100' of proposed within 100' of proposed or completion or research within 100' of proposed or completion or research within 100' of proposed within 100' of prop	OTHER: Tempor pleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion. All Tools 10/20/2015 rater and pressure tested to 570-560 psi, respectively. The properties of the properties	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or come of starting any proposed was proposed completion or results. 1. MIRU TFH Renta 2. Load Casing w/w more than 30 mins 3. Attached record of 4. CIBP @ 4,910' w 5. Perfs @ 4,951'- 4. CIBP within 100' of pure Spud Date:	DOTHER: Tempor pleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion. All Tools 10/20/2015 rater and pressure tested to 570-560 psi, ress. In Original Chart Recorder. All 35' cmt. on top. All 35' cmt. on top. Belease Date:	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of cord on chart recorder for
OTHER: 13. Describe proposed or come of starting any proposed was proposed completion or results. 1. MIRU TFH Renta 2. Load Casing w/w more than 30 mins 3. Attached record of 4. CIBP @ 4,910' w 5. Perfs @ 4,951'- 4. CIBP within 100' of pure Spud Date:	OTHER: Tempor pleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion. All Tools 10/20/2015 rater and pressure tested to 570-560 psi, respectively. The properties of the properties	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of cord on chart recorder for
OTHER: 13. Describe proposed or come of starting any proposed was proposed completion or results. 1. MIRU TFH Renta 2. Load Casing w/w more than 30 mins 3. Attached record of 4. CIBP @ 4,910' w 5. Perfs @ 4,951'- 4. CIBP within 100' of pure Spud Date:	DOTHER: Tempor pleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion. All Tools 10/20/2015 rater and pressure tested to 570-560 psi, ress. In Original Chart Recorder. All 35' cmt. on top. All 35' cmt. on top. Belease Date:	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of cord on chart recorder for
OTHER: 13. Describe proposed or come of starting any proposed we proposed completion or results. 1. MIRU TFH Renta 2. Load Casing w/ we more than 30 mins 3. Attached record of 4. CIBP @ 4,910' we 5. Perfs @ 4,951'- 4. CIBP within 100' of pure Spud Date: I hereby certify that the information of the starting of the	OTHER: Temporpleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion. All Tools 10/20/2015 water and pressure tested to 570-560 psi, rest. on Original Chart Recorder. (7.35° cmt. on top. 1.985°) Deerfs Rig Release Date:	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of a cord on chart recorder for a ge and belief.
OTHER: 13. Describe proposed or come of starting any proposed was proposed completion or results. 1. MIRU TFH Renta 2. Load Casing w/w more than 30 mins 3. Attached record of 4. CIBP @ 4,910' w 5. Perfs @ 4,951'- 4. CIBP within 100' of pure Spud Date:	DOTHER: Tempor pleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion. All Tools 10/20/2015 rater and pressure tested to 570-560 psi, ress. In Original Chart Recorder. All 35' cmt. on top. All 35' cmt. on top. Belease Date:	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of cord on chart recorder for
OTHER: 13. Describe proposed or come of starting any proposed we proposed completion or results. 1. MIRU TFH Rentance 2. Load Casing w/w more than 30 mins 3. Attached record of 4. CIBP @ 4,910' w 5. Perfs @ 4,951'-4 CIBP within 100' of proposed or completion or results. I hereby certify that the information of the start of t	DOTHER: Temporpleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion. If Tools 10/20/2015 rater and pressure tested to 570-560 psi, respectively. The president of the pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion. If Tools 10/20/2015 rater and pressure tested to 570-560 psi, respectively. The president of the pertinent details, and work). The president of the pertinent details, and work details are president of the pertinent details, and work details are president of the pertinent details, and work details are president of the pertinent details, and work details are president of the pertinent details, and work details are president of the pertinent details, and work details are president details. The president details are president details are president details, and work details are president details. The president details are president details, and work details are president details. The president details are president	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of cord on chart recorder for cord and belief. DATE 10/20/2015
OTHER: 13. Describe proposed or come of starting any proposed we proposed completion or results. 1. MIRU TFH Rentance 2. Load Casing w/w more than 30 mins 3. Attached record of 4. CIBP @ 4,910' w 5. Perfs @ 4,951'-4 CIBP within 100' of proposed or completion or results. I hereby certify that the information of the start of t	OTHER: Temporpleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion. All Tools 10/20/2015 water and pressure tested to 570-560 psi, rest. on Original Chart Recorder. (7.35° cmt. on top. 1.985°) Deerfs Rig Release Date:	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of cord on chart recorder for cord and belief. DATE 10/20/2015
OTHER: 13. Describe proposed or come of starting any proposed we proposed completion or results. 1. MIRU TFH Rentance 2. Load Casing w/ we more than 30 minsters 3. Attached record of 4. CIBP @ 4,910' we 5. Perfs @ 4,951'- 4. CIBP within 100' of pure Spud Date: I hereby certify that the information of pure starting the pure starting that the information of pure starting that the information of pure starting that the information of pure starting	DOTHER: Temporpleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion. If Tools 10/20/2015 rater and pressure tested to 570-560 psi, respectively. The president of the pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion. If Tools 10/20/2015 rater and pressure tested to 570-560 psi, respectively. The president of the pertinent details, and work). The president of the pertinent details, and work details are president of the pertinent details, and work details are president of the pertinent details, and work details are president of the pertinent details, and work details are president of the pertinent details, and work details are president of the pertinent details, and work details are president details. The president details are president details are president details, and work details are president details. The president details are president details, and work details are president details. The president details are president	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of cord on chart recorder for cord and belief. DATE 10/20/2015
OTHER: 13. Describe proposed or come of starting any proposed we proposed completion or results. 1. MIRU TFH Rentance 2. Load Casing w/w more than 30 mins 3. Attached record of 4. CIBP @ 4,910' w 5. Perfs @ 4,951'-4 CIBP within 100' of proposed or completion or results. I hereby certify that the information of the start of t	DOTHER: Temporpleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion. If Tools 10/20/2015 after and pressure tested to 570-560 psi, respectively. The president of the pertinent details, and work). See RULE 19.15.7.14 NMAC. For Multiple Concompletion. If Tools 10/20/2015 psi, respectively. The president of the pertinent details, and work). The president of the pertinent details, and work d	ge and belief. DATE 10/20/2015 DATE 10/20/2015 Deergy.com PHONE: (432) 686-0824
OTHER: 13. Describe proposed or come of starting any proposed we proposed completion or results. 1. MIRU TFH Rentance 2. Load Casing w/ we more than 30 minsters 3. Attached record of 4. CIBP @ 4,910' we 5. Perfs @ 4,951'- 4. CIBP within 100' of pure Spud Date: I hereby certify that the information of pure starting the pure starting that the information of pure starting that the information of pure starting that the information of pure starting	DOTHER: Temporpleted operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion. If Tools 10/20/2015 rater and pressure tested to 570-560 psi, respectively. The president of the pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion. If Tools 10/20/2015 rater and pressure tested to 570-560 psi, respectively. The president of the pertinent details, and work). The president of the pertinent details, and work details are president of the pertinent details, and work details are president of the pertinent details, and work details are president of the pertinent details, and work details are president of the pertinent details, and work details are president of the pertinent details, and work details are president details. The president details are president details are president details, and work details are president details. The president details are president details, and work details are president details. The president details are president	ge and belief. DATE 10/20/2015 DATE 10/20/2015 Deergy.com PHONE: (432) 686-0824

