			OCD-HOBBS				
	UNITED STATES DEPARTMENT OF THE INTE BUREAU OF LAND MANAGEN	PARTMENT OF THE INTERIOR		FORM A OMB NO Expires: J	FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010		
SUNDRY	NOTICES AND REPORTS	S ON WELLS		5. Lease Serial No. NMNM33955			
Do not use th	his form for proposals to drill ell. Use form 3160-3 (APD) fo	Il or to re-enter an		6. If Indian, Allottee or	r Tribe Name		
SUBMIT IN TR	RIPLICATE - Other instruction	ns on reverse side.		7. If Unit or CA/Agree	ement, Name and/or	No.	
1. Type of Well Gas Well 🖸 Otl				8. Well Name and No. HALFWAY SWD 1	1		
2. Name of Operator R360 PERMIAN BASIN	Contact: CHF E-Mail: chrisr@wastecc	RIS R RUANE		9. API Well No. 30-025-42545	-		
3a. Address 3 WATERWAY SQUARE PLA THE WOODLANDS, TX 7738	ACE, SUITE 110 Ph	b. Phone No. (include area code h: 832-442-2200		10. Field and Pool, or E BLUE BIRD DRI	RILL ISLAND		
4. Location of Well <i>(Footage, Sec., 7</i>		NUVU	2 2015	11. County or Parish, a	and State		
Sec 22 T20S R32E SWSW 84	45FSL 1030FWL	RECI	EIVED	LEA COUNTY, N	NM		
12. CHECK APP	PROPRIATE BOX(ES) TO IN			REPORT, OR OTHER	R DATA		
TYPE OF SUBMISSION			OF ACTION				
□ Notice of Intent	Acidize	Deepen		ction (Start/Resume)	Water Shut-C	Off	
Sector 1 at 1	Alter Casing	Fracture Treat	C Reclam	mation	Well Integrity		
Subsequent Report	Casing Repair	New Construction	Recom		Other	1	
Final Abandonment Notice	Change Plans	<ul> <li>Plug and Abandon</li> <li>Plug Back</li> </ul>	Tempo Water I	orarily Abandon			
ran 7?35# HCL80 f/155?- 0?. 9/21/2015 Hold salfety meeting with Halli Pump Cement as follows: 530 Lift Psi 17750 psi, Displace wi Drop 1st stage ball open and t	an with BLM approval. 27 Ran 7? 35# HCL80 f/ 14,636?- DVT at 5178? and 10,456?. 7 Illiburton, Schlumberger, Weir a 0 sxs Lead (13.5 pg / 1.3 cf/sx) vith 150 bbl FW & 383 bbls muc I pump thru Stage #1 DV tool, c IV Tool #1, Set up pump Stage (14,635)	7? float collar at 14,579. and Precision drilling. c) Tail w/ 105 sxs (16.4 pp id, floats held, circ 125 sxs cmt					
14. I hereby certify that the foregoing is	Electronic Submission #32067	73 verified by the BLM We	ell Informatio	on System		_	
Name (Printed/Typed) JEREMY (		Hobbs		111			
N 18 16	Submission)		2015 ACC	EPTED FOR	RFCORD		
		FEDERAL OR STATE					
Approved By		Title		OCT 2 0 2015	5 Date		
Conditions of approval, if any, are attached. Approval of this notice does n vertify that the applicant holds legal or equitable title to those rights in the s which would entitle the applicant to conduct operations thereon.		warrant or	0	PRSwar	A		
itle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s			d willfully to m	CARLSBAD FIELD U	geney of the United		
	TOR-SUBMITTED ** OPER		and the second second		. 12		
WE have a	OR-SUBMITTED OF LI	ATOK-SUDMITTEE	* UPENS.	OK-SUDMITTEE	KZ		
					11.2	1	
a 1. S. M. S.			N	OV 1 0 2015		an	
in the here where			135	01 10 2013		0011	

## Additional data for EC transaction #320673 that would not fit on the form

## 32. Additional remarks, continued

TOPS: Yates - 2,969 Capitan - 3,300' Delaware MTN - 5,129 Bone springs - 7,738' 1st Bone springs - 8,815' 2nd Bone springs carb - 9,160" 2nd Bone springs sand - 9,410' 3rd Bone spirngs carb - 10,040' 3rd Bone springs sand - 10,498' Wolfcamp - 10,754' Strawn - 11,714' Atoka - 12,216' Marrow - 12,793' Marrow Sand - 13,042 Lower Morrow - 13,379' Barnett -13,752 Mississipian Lime - 13,884' Woodford shale, 14,409 Devonian, 14,623'

## 9/22/2015

Circulate 1st stage DVT and hold safety meeting for 2nd stage cmt job. Change lines from rig back to Shlumberger, Pump 2nd stage 7" cement job as follows: 10 bbls of FW W/dye, 40 bbls of CW-100 spacer, 40 bbls of gelled spacer pumped @ 5 bbls min @ 600 psi, 2nd stage Lead: 567 sx of TXI cement, Blended with 75 lb sx WTSK 0.2% BWOB, 10%BWOB, 0.8% BWOB, 0.1% BWOB, 2 lb/sx WTSK, 0.25% BWOB, 0.2% BWOB, 2% BWOB, Pumped @ 5 bbls min @ 800 psi for a 240 bbls slurry, mixed @ 11.5 lb/gal, 2.38 cuft/sx, 13.88 gal fw/sx. 2nd stage Tail: 103 sx of class H cement, mixed @16.4 lb/gal, 1.09 cutf/sx, 4.45 gal fw/sx, blended with, 94 lb/sx WTSK, 0.4% BWOB, 0.25% BWOB, 2% BWOB, Pumped @ 5 bbls min @500 psi, 20 bbl slurry, Shut down and drop plug, Wash up on top of plug, displace 7" casing with 200 bbls FW, swaping to drilling mud for 187 bbls pumped @ 5 bbls min @ 850 psi, slowing the last 10 bbls to 2 bbls min @ 950 psi, bwrmei a construction of the start of the bumping plug @ 2,900 psi, check floats, floats held, drop Halliburton bomb, wait 25 min, pressure up to 1,100 psi and open 3rd stage DVT, circulate cement off DVT with pump truck, circulated off 235 sx or 100 bbls of cement. Turn back over to rig pumps, Service rig and topdrive, circulate 3rd stage DVT for 6 hrs. Cement 3rd stage as follows: Lead cement: 364 sx of TXI, mixed @ 11.5 lb/gal, 2.16 cuft/sx, 12.66 gal fw/sx, Blended with, 75 lb/sx of WTSK, 1.5% BWOB, 5% BWOB, 1% BWOB, 0.2% BWOB, 0.2% BWOB, pumped @ 5 bbls min @ 550 psi for a 140 bbls slurry, Tail cement: 95 sx of class C, mixed @ 14.8 ppg, 1.36 cuft/sx, 6.44 gal fw/sx, blended with 94 lb/sx WTSK, 0.1% BWOB, 0.2% BWOB, 0.3% BWOB, 0.2% BWOB, 2% BWOB, pumped @ 5 bbls min @ 350 psi, for a 23 bbls slurry, Shut down, drop plug, wash up on top of plug, displace with 191 bbls of fesh water slowing the last 10 bbsl to 2 bbls min @ 1100 psi, bumping plug @ 2700 psi, hold pressure for 5 min, bleed off pressure DVT closed, Circulated 30 bbls or 77 sx of cement to 1/2 round. Close

in cementing head on 7' csg.

Wash up pump trucks and wash out BOP's, flow lines and well head, rig down Schlumberger and start cleaning pits.

Wait on cement 4 hrs, back out landing it, make up and install well head pack off from Weir well heads, trash is on top of landing ring We will have to nipple down to set the packoff on the casing. We will wait the 24 hrs on cement

then nipple down install packoff, install

DSA then nipple up and test BOP's.

Pat with BLM was notified about the cement job. He did not come out due to other pressing jobs.