

10/13/2015

RE: C-102 - updated Rojo B 7811 JV-P #1H 30-025-42897

Attached please find one original of Form C-102 for the referenced well location.

The surveyor found a corner that had not been previously located. This made the coordinates for the surface hole slightly different, but more accurate.

Please give a shout with any questions. 432-682-3753.

Pam Inskeep Regulatory Administrator BTA Oil Producers LLC 432-682-3753 pinskeep@btaoil.com