Submit 1 Copy To Appropriate District Office HOBBS OCD State of New Mexico District I – (575) 393-6161 Energy, Minerals and Natural Resources	Form C-103 Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 <u>District II - (575) 748-128 NOV 1 6 2015</u> OIL CONSERVATION DIVISION	WELL API NO. 30-025-42290
811 S. First St., Artesia, NM 88210	5. Indicate Type of Lease
District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	STATE X FEE
District IV - (505) 476-3460 RECEIVED Santa Fe, NM 8/505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name Altbeir 10 State
PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other	8. Well Number 1H
2. Name of Operator	9. OGRID Number
Devon Energy Production Company, L.P.	3167
3. Address of Operator	10. Pool name or Wildcat
333 West Sheridan, Oklahoma City, OK 73102	WC-025 G-06 S183608B; Bone Spring
4. Well Location	
Unit Letter N : 230 feet from the South line and 1980 feet from the West line	
Section 10 Township 18S Range 36E 11. Elevation (Show whether DR, RKB, RT, GR, etc	NMPM County Lea
11. Elevation (Show whether DR, RRB, R1, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WO	RK ALTERING CASING RILLING OPNS. P AND A
OTHER: OTHER:	
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 	
Devon Energy Production Company, LP respectfully requests to run and MIT on the referenced well with the following procedures:	
1. MIRU WSU.	
 MIRU WSU. ND Wellhead. NU BOPE & test. 	
 POOH W/ESP assembly and 2-7/8" production tubing from ~8,736'. 	
 Make gauge ring/junk basket run to ~6,720'. RU W/L. Set CIBP @ 6,700'. Dump bail 35' cement on top. RD W/L. SET CIBP@ 8258 	
 TIH w/2-7/8" tubing to ~6,600". Load and circulate hole w/2% KCl w/corrosion inhibitor. 	
 Pressure test casing to 500 psi for 30 minutes. Chart test and have NMOCD witness. Bleed off pressure. ND BOPE. NU wellhead. 	
9. RDMO WSU.	
TA'ing will bring well into OCD compliance until well can be evaluated. Attached: Current and Proposed Wellbore Schematics.	
Devon Energy respectfully requests a 5 year TA status for the Altbeir 10-1H. Condition of Approval: notify	
	OCD Hobbs office 24 hours
Parla -	incous office 24 hours
I hereby certify that the information above is true and complete to the best of my knowled	ge and belief.
SIGNATURE CONCENTITLE Regulatory Analyst	DATE 11/10/2015
Type or print name <u>Rebecca Deal</u> E-mail address: rebecca.deal@dvn.com PHONE: 405-228-8429	
For State Use Oniv	
APPROVED BY: Malen HOWN TITLE Dist Supervise DATE 11/30/2015 Conditions of Approval (if any):	
v	

NOV 3 0 2015



