			MUBBS	OCD				
	UNITED STATE DEPARTMENT OF THE UREAU OF LAND MAN	INTERIOR	DEC 01			FORM APPROVE OMB No. 1004-0 Expires: October 31	137	_
Do not use th	Y NOTICES AND REP(is form for proposals II. Use Form 3160-3 (A	to drill or to re	e-enter an/E	D	6. If Indian, Allottee	or Tribe Name		_
SUE	MIT IN TRIPLICATE - Other	r instructions on p	age 2.		7. If Unit of CA/Ag	eement, Name and	l/or No.	
	as Well Dther	1			8. Well Name and N SOUTH JUSTIS	o. 3 UNIT F #20		
2. Name of Operator LEGACY RI	SERVES OPERATING LP	/			9. API.Well No. 30-025-22742			~
3a. Address PO BOX 10848 MIDLAND, TX 79702		 Phone No. (include area code) 432-689-5200 			10. Field and Pool o JUSTIS;BLINE	r Exploratory Area BRY-TUBB-DRK		V
4. Vocation of Well (Footage, Sec. 1795 FNL & 1795 FWL, SENW, SEC.		J			E-PERMIT CONVERSIC RETURN			/
12. CI	HECK THE APPROPRIATE BO	DX(ES) TO INDICA	ATE NATURE O	FN	CONVERSIC RETURN TO	ING SSIA		
TYPE OF SUBMISSION			TYPE	0	RETURN TO	DNN		-
Notice of Intent	Acidize	Deepen Fracture	Treat	11	CSNG NT TO PA	ENVIRO	IA DW	CTION>
Subsequent Report	Casing Repair Change Plans	New Con Plug and	1	Keco	porarily Abandon	P&ANR	CHG LOC	
Final Abandonment Notice	Convert to Injection	Plug Bac	:k [Wate	er Disposal		· «AR	
13. Describe Proposed or Complete	d Operation: Clearly state all per							

1200-

the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

8/27-28/15 RU wireline. RIH w/ 5 ½" CIBP on wireline and set at 4915'. Make 2 wireline dump bailer runs and place 4 sxs Class H cmt (+/-40') on top of plug. Load csg with pkr fluid and test csg to 500# for 30 min for company test.

10/30/15 RU wireline. RIH and tag top of cmt plug at 4870', 45' cmt on top of plug. Make wireline dump baller run and place 2 sxs Class H cmt on top of current cement plug and bridge plug. Estimate 60-65' of cmt now on top of CIBP. Job witnessed by Steven Balley (BLM).


Note: The tubing was pulled previously on 8/27/12 following an unsuccessful fishing tubing fishing job.

10/30/15 Run MIT. RU pump truck and chart recorder. Perform MIT at 602# for 30 min. OK. Chart attached Along with current wellbore diagram. Well is now TA'd.

After (12 moths from the well must be online	
or plans to P & A must be submitted.	


14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)						
LAURA PINA	COMPLIANCE COORDINATOR					
Signature Laura ma Dat	Date 11/30/2015					
THIS SPACE FOR FEDERA	L OR STATE	AUGEPSED FOR RECORD				
Approved by		PETROLEUM ENGINEER				
	Title	Date				
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	Kenneth Rennick				
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person fictitious or fraudulent statements or representations as to any matter within its jurisdiction.	knowingly and willfu	It to BUTTEALD BEDATOD MANAGEMENT United States any false CARLSBAD FIELD OFFICE				
(Instructions on page 2)						


MUB/OCD 12/1/2015 DEC 09 2015 BB1 2/8/15



0x gross 12/4/15

WELLBORE SCHEMATIC





PBD @ 7900'

7-7/8" hole. 5-1/2" 15.5,17# J-55 csg @ 7911'.

11/25/2015 8:23 AM