Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103	
<u>District 1</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and	Natural Resources	WELL API NO.	Revised July 18, 2013
District II - (575) 748-1283	OIL CONSERVA	OIL CONSERVATION DIVISION		
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of Lea	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		6. State Oil & Gas Leas	FEE 🗸
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Suma re, :		o. State Off & Gas Leas	se No.
	TICES AND REPORTS ON W	/ELLS	7. Lease Name or Unit	Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Northeast Drinkard Unit (NEDU) / 22503 /	
PROPOSALS.)  1. Type of Well: Oil Well  Gas Well  Other			8. Well Number 133	
2. Name of Operator	NOV 2 3 2015		9. OGRID Number 873	
Apache Corporation NOV 2 3 2010  3. Address of Operator		10. Pool name or Wildcat		
303 Veterans Airpark Lane, Suite	1000 Midland, TX 79705	RECEIVED	Eunice; B-T-D, North (2	
4. Well Location	4 344 55			
Unit Letter D / Lot 5	: 1458 feet from the Nor	th line and 10	98feet from the	Westline
Section 2	Township 21S	Range 37E		nty Lea
	11. Elevation (Show wheth		:.)	
	3502'	GL		
12. Check	Appropriate Box to Indic	ate Nature of Notice	, Report or Other Data	
NOTICE OF	NITENTION TO	l cur	CECUENT DEDOD	T OF:
PERFORM REMEDIAL WORK	INTENTION TO:  PLUG AND ABANDON		BSEQUENT REPOR	ERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	The second secon	RILLING OPNS. P AN	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	NT JOB	
DOWNHOLE COMMINGLE	]			
CLOSED-LOOP SYSTEM [ OTHER: REACTIVA	 TE WELL F.	OTHER:		П
O ITILITY.	npleted operations. (Clearly sta		nd give pertinent dates, inc	luding estimated date
	work). SEE RULE 19.15.7.14	NMAC. For Multiple Co	ompletions: Attach wellbo	re diagram of
proposed completion or r				
Apache proposes to reactivate this Day 1/2: MIRU, NU BOPs, PU and I		drill collars and 4 3/4" hit	to +/-5655' DO cement an	d CIRP Continue in
hole to +/- 6045'. Circulate	clean and POOH w/ 2-7/8" L-80	work string. LD drill coll	ars and bit.	
Day 3: PU and RIH w/treating pac	ker and RBP on 2-7/8" work stri	ing. Pressure test tubing	to 3,500 psia. Set packer (	@ +/- 6030'.
	or to ensure integrity. PU and results w/5,000 gals 15% HCl and ro		aximum pressure 3,500 ps	ia). Release packer and
wash salt. POOH laying do	wn w/ 2-7/8" work string and pa			
Day 4: RIH w/ 2-7/8" production tul Day 5: RIH w/ 1-3/4" pump and roo		OMO		
Post 1 Week: Pump acrolein and cir	culate for 6 hours. Shut in well	for 48 hours.		
Pump corrosion inhibite Place well on producti	tor with biocide in flush. Circulat	te for 6 hours.		
Note: Depending on production test		uction (casing squeeze)		
Spud Date: 6/12/1999	Rig Rele	ase Date: 6/24/1999		
I hereby certify that the information	on above is true and complete to	the hest of my knowled	ge and helief	
Thereby certify that the information	and complete to	the best of my knowled	ge and benefit	
SIGNATURE ROSA T	TITLE!	Sr. Staff Reg Analyst	DATE 1	1/20/2015
SIGNATURE DODG A	-			112012010
Type or print name Reesa Fisher	E-mail a	address: Reesa.Fisher@ap	pachecorp.com PHONE:	(432) 818-1062
For State Use Only				
APPROVED BY:	TITLE	Petroleum Engin	DATE	12/13/15
Conditions of Approval (if any):				1111