District I 625 N. French D	r., Hobbs, NM	88240			State of N	ew Mexico			Form C-1	
Phoae: (575) 393-6161 Fax: (575) 393-0720 <u>District II</u> 811 S. First St., Artesia, NM 88210			Energy	Energy Minerals and Natural Resources				Revised July 18, 20		
							<b>OBBS OCE</b>			
hone: (575) 748- istrict III	1283 Fax: (575	5) 748-9720		(	Oil Conservation Division 1220 South St. Francis Dr.				AMENDED REPOR	
000 Rio Brazos I hone: (505) 334-				1				EC 30 201	5	
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3460 Fax: (505) 476-3462					Santa Fe, NM 87505			RECEIVED		
APPLI	CATIC	ON FOR	PERMIT T	O DRILL,	RE-ENTE	R, DEEPEN,	PLUGBAC	K, OR AD		
		T	ENDURANCE RES					270329	lber	
		1	203 West Suite 10 Midland, TX	Wall 000			30-0	23-4:	298	
* Prop	erty Code	5	Ivitaliand, 125	э.	Property Name aster Bass 36 St	ate		0.1	Vell No. 1H	
11	110				rface Locatio					
UL - Lot	Section	Township	Range	Lot Idn	Feet from	N/S Line	Feet From	E/W Line	County	
D	36	24 S	34 E		330	N	425	w	LEA	
		1.0		* Propose	d Bottom Ho	le Location				
UL - Lot M	Section 36	Township 24 S	Range 34 E	Lot Idn	Feet from 330	N/S Line S	Feet From 660	E/W Line W	County LEA	
-				<u><u></u></u>	-11-6					
					ol Informatio	n				
				Pool N Red Hills: Bon	e Spring East 1	IDATH			Pool Code 96434	
	- P.								30434	
11 117	1.77		12	Additiona	<sup>13</sup> Cable/Rotary		4	15 0	1. 1	
	well		<sup>12</sup> Well Type Oil		R R		<sup>4</sup> Lease Type State	Gr	ound Level Elevation	
<sup>16.</sup> Multiple <sup>17.</sup> Proposed Dep		17. Proposed Depth	<sup>18</sup> Formation				20. Spud Date			
	N		13,850' MD	В	Bone Spring/Avalon		NorAm 23		05/01/16	
epth to Grou	ind water: 0	-400'	Dista	nce from nearest fi	resh water well		Distance	to nearest surfac	e water	
We will b	e using a o	closed-loop	p system in lieu o 21.	f lined pits Proposed Cas	sing and Cem	ent Program				
Туре	Hole	e Size	Casing Size	Casing Wei		Setting Depth	Sacks of	Cement	Estimated TOC	
Surf	12	2.25	9.625	40		1000	44	0	Surface	
Intl		.75	7	29		9900	77		Surface	
Prod		125	4.5	13.5		13850	25		8700	

# Casing/Cement Program: Additional Comments Plan to drill a 12-1/4" hole to 1000' with Fresh Water. Run 9-5/8", 40#, J-55 csg and cement to surface. Drill 8-3/4" vertical and curve on 10\*/100' to 9,900' with oil based

mud, and run 7", 29#, HCP-110 csg and cement to surface. Drill a 6-1/8" hole (~3950' lateral) to TD of ~13,850'. Run 4-1/2", 13.5#, HCP-110 csg and cement to 8700'.

### <sup>22.</sup> Proposed Blowout Prevention Program

Туре	Working Pressure	Test Pressure	Manufacturer
Double Ram	5000	5000	Cameron

best of my knowledge and be		OIL CONSERVATION DIVISION		
I further certify that I have 19.15.14.9 (B) MAC , it Signature	complied with 19.15.14.9 (A) NMAC 🔀 and/or applicable.	Approved By:		
Printed name: Ms. Tinlee Til	ion	Title: Petroleum Engineer		
Title: Engineer		Approved Date: 12/31/15 Expiration Date: 12/31/17		
E-mail Address: tinlee@endu	ranceresourcesllc.com			
Date: 12/21/2015	Phone: 432-242-4693	Conditions of Approval Attached		
VI STATE STATE		JAN 0 4 2010 115/11		

#### CONDITIONS OF APPROVAL

API #	Operator	Well name & Number	
30-025-42990	ENDURANCE RESOURCES LLC	TTELECASTER BASS STATE # 001H	

Applicable conditions of approval marked with XXXXXX

# Administrative Orders Required

Other wells	

Drilling

XXXXXXX	Once the well is spud, to prevent ground water contamination through whole or partial conduits from the surface, the operator shall drill without interruption through the fresh water zone or zones and shall immediately set in cement the water protection string

# Casing

XXXXXXX	SURFACE & INTERNEMIATE(1) CASING - Cement must circulate to surface
XXXXXXX	PRODUCTION CASING - Cement must tie back into intermediate casing
	If cement does not circulate to surface, must run temperature survey or other log to determine top of cement
XXXXXXX	Surface casing must be set 25' below top of Rustler Anhydrite in order to seal off protectable water

#### Lost Circulation

X Must notify OCD Hobbs Office if lost circulation is encountered at 575-370-3186	XXXXXXX
	Sec. 1

#### Stage Tool

XXXXXXX	Must notify OCD Hobbs Office prior to running Stage Tool at 575-370-3186
XXXXXXXX	If using Stage Tool on Surface casing, Stage Tool must be greater than 350' and a minimum 200 feet above surface shoe.
XXXXXXX	When using a Stage Tool on Intermediate or Production Casing Stage must be a minimum of 50 feet below previous casing shoe.

Pits

XXXXXXX	If using a pit for drilling and completions, must have an approved pit form prior to spudding the well	
		_

## **Completion & Production**

XXXXXXX	Will require a directional survey with the C-104