Submit 1 Copy To Appropriate District	Form C-103
District I Energy, Minerals and Natural Resources	October 13, 2009 WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210	30-025-38317
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV RECEIVES anta Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	o. olate on te olas lease no.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	North Monument G/SA Unit Blk. 10
PROPOSALS.) 1. Type of Well: Oil Well Gas Well	8. Well Number 363
2. Name of Operator	9. OGRID Number 873
Apache Corp.	
3. Address of Operator	10. Pool name or Wildcat
P O box Drawer D Monument NM 88265	Eunice Monument G/SA
4. Well Location Unit LetterI2630feet from theS line and _	120 fact from the
E line	_130leet from the
Section 30 Township 19S Range 37E	NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc	
	T
12. Check Appropriate Box to Indicate Nature of Notice	, Report or Other Data
NOTICE OF INTENTION TO: SUI	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORKPLUG AND ABANDON REMEDIAL WO	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEME	
	_
OTHER: OTHER: OTHER:	nd give pertinent dates including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, a	
 Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co proposed completion or recompletion. 	
 Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Complete Action 2010. 	
 Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co proposed completion or recompletion. 	ompletions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Perfs 3668-3948 	ompletions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Perfs 3668-3948 	ompletions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Perfs 3668-3948 	ompletions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Perfs 3668-3948 	ompletions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Perfs 3668-3948 	ompletions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Perfs 3668-3948 	ompletions: Attach wellbore diagram of
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Perfs 3668-3948 Plan to move in a pulling unit. Set a CIBP +- 3600 with 35' of cement on top. Will test to 	ompletions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Perfs 3668-3948 	ompletions: Attach wellbore diagram of
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Perfs 3668-3948 Plan to move in a pulling unit. Set a CIBP +- 3600 with 35' of cement on top. Will test to 	ompletions: Attach wellbore diagram of
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Perfs 3668-3948 Plan to move in a pulling unit. Set a CIBP +- 3600 with 35' of cement on top. Will test to Spud Date: 	500 psi for 30 minutes & chart the results.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Perfs 3668-3948 Plan to move in a pulling unit. Set a CIBP +- 3600 with 35' of cement on top. Will test to 	500 psi for 30 minutes & chart the results.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Perfs 3668-3948 Plan to move in a pulling unit. Set a CIBP +- 3600 with 35' of cement on top. Will test to Spud Date:	500 psi for 30 minutes & chart the results.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Perfs 3668-3948 Plan to move in a pulling unit. Set a CIBP +- 3600 with 35' of cement on top. Will test to Spud Date: 	500 psi for 30 minutes & chart the results.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Perfs 3668-3948 Plan to move in a pulling unit. Set a CIBP +- 3600 with 35' of cement on top. Will test to Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE Mathematical Additional Addi	500 psi for 30 minutes & chart the results.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Perfs 3668-3948 Plan to move in a pulling unit. Set a CIBP +- 3600 with 35' of cement on top. Will test to Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE TITLE	500 psi for 30 minutes & chart the results. 500 psi for 30 minutes & chart the results. ge and belief. DATE _//-5-/5 Dacheccorp.com_ PHONE: _575-441-7734_
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Perfs 3668-3948 Plan to move in a pulling unit. Set a CIBP +- 3600 with 35' of cement on top. Will test to Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE TITLE	500 psi for 30 minutes & chart the results. 500 psi for 30 minutes & chart the results. ge and belief. DATE _//-5-/5 Dacheccorp.com_ PHONE: _575-441-7734_
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Perfs 3668-3948 Plan to move in a pulling unit. Set a CIBP +- 3600 with 35' of cement on top. Will test to Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE TITLE	500 psi for 30 minutes & chart the results. 500 psi for 30 minutes & chart the results. ge and belief. DATE _//-5-/5 Dacheccorp.com_ PHONE: _575-441-7734_
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Perfs 3668-3948 Plan to move in a pulling unit. Set a CIBP +- 3600 with 35' of cement on top. Will test to Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE TITLE	500 psi for 30 minutes & chart the results. 500 psi for 30 minutes & chart the results. ge and belief. DATE _//-5-/5 Dacheccorp.com_ PHONE: _575-441-7734_
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Perfs 3668-3948 Plan to move in a pulling unit. Set a CIBP +- 3600 with 35' of cement on top. Will test to Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE TITLEInstrument Tech Type or print name Jim Ellison E-mail address: _JD.Ellison@aj APPROVED BY: Staff addressed address	500 psi for 30 minutes & chart the results. 500 psi for 30 minutes & chart the results. ge and belief. DATE _//-5-/5 Dacheccorp.com_ PHONE: _575-441-7734_