Submit i Copy To Appropriate District	State of New M			rm C-103
District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Nat	WELL	API NO. 5-00312	uly 18, 2013
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATIO	N DIVISION 5 India	cate Type of Lease	
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE FEE	
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 8	6. State	e Oil & Gas Lease No.	
SUNDRY NOTIO (DO NOT USE THIS FORM FOR PROPOS		LUG BACK TO A	e Name or Unit Agreeme	nt Name
DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other	ROC OGE KUL	CK QUEEN UNIT	
2. Name of Operator	SERVES OPERATING LP	AN 2 5 2016 9. OGF	RID Number 240974	
3. Address of Operator	8, MIDLAND, TX 79702		ol name or Wildcat ROCK; QUEEN	
4. Well Location	6, MIDLAND, 1X 77702	CAF	ROCK, QUEEN	/
Unit Letter <u>E</u> :	1980 feet from the NOR		_feet from theWEST_	line
Section <u>30</u>	Township 13S 11. Elevation <i>(Show whether D.</i>	Range 32E	NMPM County	LEA
and the second of the second	4388' KB	R, KKB, KI, GR, eIc.)	and the second second	
12. Check A	ppropriate Box to Indicate	Nature of Notice, Report	or Other Data	
NOTICE OF IN	TENTION TO:	SUBSEQUE	ENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OF	PNS. PANDA	
	MULTIPLE COMPL	CASING/CEMENT JOB		
DOWNHOLE COMMINGLE				
OTHER:		OTHER: STIMULATE & RU	IN ESP	\boxtimes
 Describe proposed or complete of starting any proposed work proposed completion or record 	k). SEE RULE 19.15.7.14 NMA			
SEE ATTACHED PROC	EDURE			
te:	Rig Release I	Date:		
			0	
'v that the information a	bove is true and complete to the	best of my knowledge and beli	et.	
				The state
SIGNA'	TITLE	REGULATORY TECH	DATE_01/22/2010	
Type or print name LAURA P For State Use Only	INA E-mail address	:lpina@legacylp.com	PHONE: <u>432-689</u>	0-5200
APPROVED BY: Conditions of Approval (if any):	TITLE	Petroleum Engineer	DATE 01/5	19/16
			JAN 28	2016

Legacy Reserves

DAILY OPERATIONS REPORT - (Selected Days)

7/1/2015 thru 1/22/2016

	Printed 1/22/2016 Page 1	
ROCK QUEEN UNIT #71 Zone: QUEEN Field: CAPROCK	LEA Co., NM	BOLO ID: 300680.36.71
AFE # 215043		
Convert from CO2 gas lifting to	artificial lift ESP and acidize	
Jul 31, 2015 Friday	(Day 1)	e e
		tubing. Tubing bled down to . Set p[ipe racks with 100jnts
Daily Cost: \$1,650 Cum. Cost: \$1,650 AFE Amount:		
SICP- 000#. SITP- < 40#. Moved in, rigged up Basic R out of hole spooling CT lin Only 1-2 bands per stand. P joints 2 3/8" J-55 IPC tubi layed down subs. Very litt 2340'. Did not notice any 3/8" Fiberglass tubing. FG	es to reels. Vac truck on ann ulled out of hole with 4- 4'x ng and packer bottom hole asse le paraffin noticed in tubing damage to IPC in tubing. Lay d Tubing looked good, no paraff ith 4.25" Bit and 98 joints 2	olers. Released packer and pull ulus due to swabbing with pkr. 2 3/8", 2- 6' x 2 3/8" subs, 90 mbly. Stood back IPC Tubing and and not until a depth of own 3 joints and about 9' of 2 in or build up.
Daily Cost: \$11,375 Cum. Cost: \$13,025 AFE Amount:		
picked up Arrowset-1X treat annulus. Test annulus and about 425'. Moved in rigge job. Test lines to 4000#.	(Day 3) nished pulling out of hole wit ing packer and run in hole to packer to 500# for 1 hour, no d up Crain Acidizing. Held saf Pumped 20bbls fresh water @ 8b f Acid/Xylene and 25bbls fresh	2950', set packer and loaded bleed off. Fluid level at ety meeting and began acid pm, 1050#, went to acid.

Max PSI- 2153#, Minimum PSI- 350#, Average PSI- 1517#. Max rate- 10bpm, Average Rate-9.5bpm.

ISIP- 350#, 5 minute- 135#, 10 minute- 126#, 15 minute- 92#.

Rigged Down Moved Out Crain. Opened flow line to tank. Flowed back about 20bbls fluid. Began getting nothing but CO2 after that. Flowed CO2 for about 3 hours, 1 hour very strong, slowing down to just a slight amount coming back. Total fluid recovered 20bbls.

Daily Cost: \$14,900 Cum. Cost: \$27,925 AFE Amount:

Legacy Reserves

DAILY OPERATIONS REPORT - (Selected Days)

7/1/2015 thru 1/22/2016

Printed 1/22/2016 Page 2

		Fillited 1/22/2010		
ROCK QUEEN Zone: QUEEN Fie		LEA Co., NM		BOLO ID: 300680.36.71
Aug 5, 2015 We SITP- 40#. B 1300'. well s minutes and s would not stop Released pack 4.25" bit and	ednesday led pressure o started gassin tarted getting p gassing, pum er, pulled out tagged @ 3090 spool above We	g hard at the end of acid/fluid back. F ped 18bbls produced of hole and layed pa ', no fill. Pulled	b. Made 2 swab runs second swab run. Ga lowed back for a tota water @ .5bpm, well w acker down. Picked w out of hole laying do with new well head.	ased for about 45 al of 147bbls. well went on vacuum. up ran in hole with own tubing and bit.
Daily Cost: Cum. Cost: AFE Amount:	\$11,750 \$39,675			
SICP- 000#. produced wate C.T. Lines. I 4' x 2 3/8" J IPC tubing su motor to surfa assembly at the Ran ESP to de problem down	r to keep well Moved in rigge -55 IPC tubing bs and 1- join ace, banded wi he base of fir pth and pulled hole. Baker T tubing, added	hole and lay down rea from gassing. Move d up Baker Spooler at sub, 87 joints 2 3/3 t 2 3/8" J-55 IPC tu th cable (2 bands pe st joint of tubing. up hole to make up ech believes it to b	mainder of tubing. T d in rigged up Tripp nd ESP. Run in hole 8" J-55 IPC tubing, 2 bing. Ran 3/8" cap s r joint). Ran check w bottom side pig tail e cable and not pump BOP. Will pull wel	le RD Spoolers for with Baker ESP, 1- 2- 10' x 2 3/8" J-55 string from base of valve above ESP . Have a ground . Banded C.T. Line
Found approxim bottom 25' of about 18" above	ITP- 000#. Pu mately 5 missi C.T. line and ve bottom cone ll have needed	ng bands from surfac bands were missing. ction. Lay down ESP	h tubing, ESP, cable e to 25' above the en Noted a damaged spo and sent seal in ordo ocation to run ESP in	nd of ESP BHA. The ot in the motor lead er to have it
Daily Cost: Cum. Cost: AFE Amount:	\$8,850 \$62,175			

Aug 10, 2015 Monday (Day 7)

SICP- 000#. Moved in rigged up Baker Spooler and Tripple RD Spooler. (Baker Tech advised a ground was found about 18" from end of motor lead on Friday). Replaced Seal in ESP assembly. Run in hole with ESP, cable and C.T. line. C.T. installed at top of

Legacy Reserves DAILY OPERATIONS REPORT - (Selected Days)

7/1/2015 thru 1/22/2016

Printed 1/22/2016 Page 3

ROCK QUEEN UNIT #71		LEA Co., NM	BOLO ID: 3006	BOLO ID: 300680.36.71	
IPC sub, 88 joint J-55 IPC sub & 1	valve 12' higher s 2 3/8" J-55 IP joint 2 3/8" J-5 Nippled Down BOP to production.	c tubing, 1- 8' x 2 3	ESP assembly, 1- 4' x 2 3/8" J 8/8" J-55 IPC sub, 1- 10' x 2 F BHA 2964.09'. Made up pig 1.	3/8"	
	9,670 1,845				
Aug 11,2015 Tuesd Rig Down Move Out		8)			
	\$600 2,445				
Aug 12, 2015 Wedn	esday (Day	9)			
	\$600 3,045				