

State of New Mexico  
Energy, Minerals and Natural Resources Department

Susana Martinez  
Governor

David Martin  
Cabinet Secretary

Brett F. Woods, Ph.D.  
Deputy Cabinet Secretary

David Catanach, Director  
Oil Conservation Division



**\*Response Required - Deadline Enclosed\***

*Field Inspection Program*  
*"Preserving the Integrity of Our Environment"*

09-Feb-16

OXY USA WTP LIMITED PARTNERSHIP  
PO BOX 4294  
HOUSTON TX 77210

**LETTER OF VIOLATION - Inspection**

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

**INSPECTION DETAIL SECTION**

MYERS LANGLIE MATTIX UNIT				No.031	L-30-23S-37E	30-025-10888-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.	
02/09/2016	Routine/Periodic	Mark Whitaker	Yes	No	3/10/2016	iMAW1604047104	
Violations							
Surface Damage/Restoration							
Comments on Inspection:		DO NOT RELEASE BOND. Wrong API number on P&A marker. Power disconnect box and pole laying on ground north of location. NEED TO CORRECT P&A MARKER AND REMOVE DISCONNECT BOX AND POLE FROM LOCATION.					
MYERS LANGLIE MATTIX UNIT No.097					K-31-23S-37E	30-025-10909-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.	
02/09/2016	Routine/Periodic	Mark Whitaker	Yes	No	3/10/2016	iMAW1604060206	
Violations							
Surface Damage/Restoration							
Comments on Inspection:		DO NOT RELEASE BOND. Well signs on north edge of location. Gas meter base on northwest corner. NEED TO REMOVE WELL SIGNS AND CONTACT GAS PURCHASER TO REMOVE EQUIPMENT. PLEASE FURNISH OCD A COPY OF CORRESPONDENCE TO GAS PURCHASER.					

FEB 10 2016

**MYERS LANGLIE MATTIX UNIT No.235**

I-7-24S-37E

**30-025-11039-00-00**

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
02/09/2016	Routine/Periodic	Mark Whitaker	Yes	No	3/10/2016	iMAW1604050447
<b>Violations</b> Surface Damage/Restoration						
<b>Comments on Inspection:</b> DO NOT RELEASE BOND. Well sign, wellhead and piping piled next to road just north of location. NEED TO REMOVE SIGN, WELLHEAD, PIPING AND OTHER DEBRIS.						

**MYERS LANGLIE MATTIX UNIT No.060**

B-31-23S-37E

**30-025-25945-00-00**

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
02/09/2016	Routine/Periodic	Mark Whitaker	Yes	No	3/10/2016	iMAW1604048571
<b>Violations</b> Surface Damage/Restoration						
<b>Comments on Inspection:</b> DO NOT RELEASE BOND. Power pole with disconnect box on west edge of location. Transformers on primary pole. NEED TO REMOVE SECONDARY POWER POLE FROM EDGE OF LOCATION. NEED TO REMOVE TRANSFORMERS FROM PRIMARY POLE.						

**MYERS LANGLIE MATTIX UNIT****No.259**


F-31-23S-37E

**30-025-32534-00-00**

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
02/09/2016	Routine/Periodic	Mark Whitaker	Yes	No	3/10/2016	iMAW1604046290
<b>Violations</b> Surface Damage/Restoration						
<b>Comments on Inspection:</b> DO NOT RELEASE BOND. No API number or Unit Letter and wrong section number on P&A marker. Transformers, power disconnect, and 2 poles east of location. NEED TO CORRECT P&A MARKER AND REMOVE POWER POLES.						

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

  
Petroleum Engr. Specialist

Hobbs OCD District Office

**Note:** Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD  
OIL CONSERVATION DIVISION  
1625 N FRENCH DRIVE  
HOBBS NM 88240



HASLER

FIRST-CLASS MAIL

**\$000.48<sup>5</sup>**

02/09/2016 ZIP 88240  
012E14642224

US POSTAGE

OXY USA WTP LIMITED PARTNERSHIP  
PO BOX 4294  
HOUSTON, TX 77210-4294