Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		Revised August 1, 2011 WELL API NO.
<u>District II</u> – (575) 748-1283	OIL CONSERVATION DI	VISION	30-025-28347
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	1220 South St. Francis		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE FEE 6. State Oil & Gas Lease No.
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505			0. State Off & Gas Lease NO.
	TICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
	OSALS TO DRILL OR TO DEEPEN OR PLUG BA		South Hobbs (G/SA) Unit
PROPOSALS.)	ICATION FOR PERMIT" (FORM C-101) FOR SU	CH	Section 3
1. Type of Well: Oil Well	Gas Well 🗌 Other:	, Our	8. Well Number: 144
2. Name of Operator Occidental Permian Ltd.	HODE	2016	9. OGRID Number: 157984
3. Address of Operator	FEB 1	1 60.	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 7	9323	-NED	
4. Well Location	DEC	EIVED	
	580' feet from the South line and	d 755	feet from the
Section 3			NMPM Lea County
Section 3 Township 19S Range 38E NMPM Lea Countý 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RK			
	3624.3' (KB)	, ni, on, cic.)	
		de ser e	
12 Check	Appropriate Box to Indicate Natur	e of Notice	Report or Other Data
12. Check	appropriate Box to indicate i tatal	e of frotice,	Report of Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A			
PULL OR ALTER CASING	MULTIPLE COMPL	SING/CEMENT	ТЈОВ 🗌
DOWNHOLE COMMINGLE			
OTHER:		HER:	
			d give pertinent dates including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or re-		in manipie cor	inpretions. Traten wendore diagram of
1. MIRU PU		During this	procedure we plan to use
2. POOH w/ Prod Equipment		burning this	loon system with a steel
2. POOR w/ Prod Equipment 3. Set CIBP @ 4240' and cap with 35' of CMT 4. Install TA wellhead the closed-loop system with a steel tank and haul contents to the required			
Install TA wellhead tank and haul contents to the required RDMO PU disposal per ODC Rule 19.15.17			aur contents to the required
5. RDMO PU disposal per ODC Rule 19.15.17			
Condition of	Approval: notify		
OCD Hobh	s office 24 hours		
Spud Date:	Rig Release Date:		
prior of runnin	g MIT Test & Chart		
en en la Astronomia de la composición d		CONT ST	
I hereby certify that the information	above is true and complete to the best of	f my knowledge	e and belief.
A chai	1 Pegulator	1	1 1
SIGNATURE Savelle X	DO TITLE (predinato	CDATE .	211/0/110
SIGNATURE			a file file
Type or print name April Hou	E-mail address		IONE: 713-366-5771
For State Use Only			113.000 - 3771
Mal	ARIAN Dist	5 000	1.101 2/22/2011
APPROVED BY:	A MOUTATLE MAL	Super	DATE 2 22 2016
Conditions of Approval (if any):		Sec. Sec.	· · ·
	v		D
			fur

FEB 2 3 2016