Form 3160-5 (August 2007)						FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No. NMNM90161		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.						6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.						7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well Gas Well Other injustion						8. Well Name and No. West Blinebry Drinkard		
2. Name of Operator APACHE CORPORATION Contact: ISABEL HUDSON E-Mail: Isabel.Hudson@apachecorp.com						9. API Well No. 30-025-06434-00-C1		
3a. Address 303 VETERA MIDLAND, TX	NS AIRPARK LA X 79705	NE SUITE 3000	 b. Phone No. (h: 432.818.) S OCE	10. Field and Pool, or MultipleSee At	Exploratory tached	
		R., M., or Survey Description)		11000		11. County or Parish, and State		
	R37E NESE 1980 Lat, 103.178698			MAR 1	1 2016	LEA COUNTY, I	MM	
12	2. CHECK APPR	OPRIATE BOX(ES) TO IN	NDICATE N	IATREG	TOTER	EPORT, OR OTHER	R DATA	
TYPE OF SU	JBMISSION			TYPE O	F ACTION			
🛛 Notice of In	itent	□ Acidize	Deepe		_	ion (Start/Resume)	U Water	
□ Subsequent	Report	 Alter Casing Casing Repair 	Fractu	re Treat Construction	Reclama		□ Well Ir	itegrity
	donment Notice	Change Plans	_	nd Abandon		arily Abandon	U Oulei	
-		Convert to Injection	Plug E		U Water D			
		ecompletion as per attached						
14. I hereby certify	that the foregoing is	Electronic Submission #326	CORPORATIO	ON, sent to the	Hobbs			
Name (Printed/1					ATORY AN			1 19
Signature	(Electronic S	ubmission)	1	Date 12/17/2	2015	÷		
		THIS SPACE FOR	FEDERAL	OR STATE	OFFICE U	SE	14	
Approved By PA	LIL SWARTZ			TitleTECHNIC		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Date	02/01/2016
Conditions of approv	Approval of this notice does not itable title to those rights in the sub	warrant or	Office Hobbs		Va	Duc	0210112010	
Title 18 U.S.C. Section	on 1001 and Title 43 U	J.S.C. Section 1212, make it a crin tatements or representations as to a		on knowingly and		ake to any department or a	agency of the	United
		SED ** BLM REVISED **				D ** BLM REVISED MAR 1 4 2016		N

Additional data for EC transaction #326627 that would not fit on the form

10. Field and Pool, continued EUNICE

Revisions to Operator-Submitted EC Data for Sundry Notice #326627

	Operator Submitted	BLM Revised (AFMSS)
Sundry Type:	RCMPL NOI	RCMPL NOI
Lease:	NMLC031741A	NMNM90161
Agreement:		
Operator:	APACHE CORP 303 VETERANS AIRPARK LANE SUITE 1000 MIDLAND, TX 79705 Ph: 432-818-1000	APACHE CORPORATION 303 VETERANS AIRPARK LANE SUITE 3000 MIDLAND, TX 79705 Ph: 432.818.1000 Fx: 432-818-1190
Admin Contact:	ISABEL HUDSON REGULATORY ANALYST E-Mail: Isabel.Hudson@apachecorp.com	ISABEL HUDSON REGULATORY ANALYST E-Mail: Isabel.Hudson@apachecorp.com
	Ph: 432-818-1142	Ph: 432.818.1142
Tech Contact:	ISABEL HUDSON REGULATORY ANALYST E-Mail: Isabel.Hudson@apachecorp.com	ISABEL HUDSON REGULATORY ANALYST E-Mail: Isabel.Hudson@apachecorp.com
	Ph: 432-818-1142	Ph: 432.818.1142
Location: State: County:	NM LEA	NM LEA
Field/Pool:	EUNICE; BLI-TU-DR, NORTH	BLINEBRY OIL & GAS DRINKARD EUNICE
Well/Facility:	WEST BLINEBRY DRINKARD UNIT 041 Sec 8 T21S R37E 1980FSL 660FEL	HAWK B-1 11 Sec 8 T21S R37E NESE 1980FSL 660FEL

L 32.491597 N Lat, 103.178698 W Lon

WBDU 41W (API: 30-25-06434) Proposed Procedure - December 7, 2015

Deepen Well, Run Liner, and recomplete in the Drinkard Formation

- Day 1: MIRU. Release packer and POOH w/ 2-3/8" tubing, on/off tool, and packer. PU & RIH w/ 6-1/8" bit on 2-7/8" work string.
- Day 2: Continue in hole and drill out well to new TD @ +/- 6870'.
- Day 3: Continue to drill out well to TD @ +/- 6870'.
- Day 4: Continue to drill out well to TD @ +/- 6870'. Circulate wellbore clean and POOH and LD 2-7/8" work string.
- **Day 5:** RU casing crew and equipment and RIH with 4-1/2" 11.6 lb/ft LTC 8 RD J-55 casing with DV tool w/packer (set at +/- 5500'), float collar, and float shoe to +/- 6870'. Perform two stage cement job to surface as follows:
 - Pump first stage consisting of 10 bbl fresh water flush, 40 bbl seal bond LCM spacer, and 231 sacks of 50:50 Fly Ash (Pozzolan):Class C cement + additives (weight 14.2 ppg, yield 1.31 cf/sack, volume 54 bbls, 100% excess slurry)
 - b. Drop plug, displace with 106 bbl fresh water (confirm volumes) and bump plug. Drop dart. Open DV tool and set packer to isolate first stage cement.
 - c. Pump second cement stage consisting of 20 bbl fresh water flush, lead slurry of 228 sacks 35:65 Fly Ash (Pozzolan):Class C cement + additives (weight 12.5 ppg, yield 2.13 cf/sack, 86.3 bbl, 20% excess slurry), tail slurry of 240 sacks of class C cement + additives (weight 14.8 ppg, yield 1.33 cf/sack, 57.8 bbl, 20% excess slurry)
 - d. Drop DV tool plug, displace with 85 bbl fresh water (confirm volumes)
- Day 6: WOC
- **Day 7:** RIH w/ 3-1/4" bit on 2-3/8" work string. Drill out DV tool, float collar and cement to +/- 6855'. Circulate clean. POOH
- Day 8: MIRU WL and RIH w/ GR/CBL/CCL, log well from TD to surface, POOH

PU and RIH w/ 3-1/8" TAGs loaded with SDP charges and perforate the Drinkard @ 4 SPF, 90 deg phasing (estimated 70', 280 shots), POOH

PU and RIH w/ treating packer on 2-3/8" work string

Day 9: Cont. RIH w/ treating packer on 2-3/8" work string. Set packer @ +/-6500'

MIRU crew. Acidize the Drinkard w/10,000 gals 15% HCl and rock salt in 3 equal stages @ +/- 10 BPM. Release packer. Wash out salt. POOH


- Day 10: PU and RIH with 4-1/2" injection packer with 2-3/8" IPC tubing subs, upper and lower profile nipples, and on/off tool on 2-3/8" work string. Set packer @ +/-6500'. Release on/off tool and pressure test casing to 500 psi. POOH and LD 2-3/8" work string
- Day 11: PU & RIH w/2-3/8" IPC injection tubing and on/off tool. Circulate packer fluid and latch onto packer with on/off tool. ND BOPs and NU WH. Pressure test casing to 500 psi. RDMO.

Day 12: Perform MIT test for NM OCD. Place well on injection

HOBBS OCD

Current Wellbore Diagram

MAR 1 1 2016



Proposed Wellbore Diagram

