Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

HOBBS OCD

FORM APPROVED OMB NO. 1004-0135

Expires: July 31, 2010 5. Lease Serial No.

SUNDRY	NMLC062486					
abandoned we	3. If Indian, Allottee or Tribe Name					
SUBMIT IN TRI	7. If Unit or CA/Agreement, Name and/or No.					
Type of Well	8. Well Name and No. DRICKEY QUEEN SAND UNIT 822					
Name of Operator LEGACY RESERVES OPERA	9. API Well No. 30-005-00987					
3a. Address PO BOX 10848 MIDLAND, TX 79702	3b. Phone No. (include area code) Ph: 432-689-5200 Ext: 5273		10. Field and Pool, or Exploratory CAPROCK; QUEEN			
4. Location of Well (Footage, Sec., T	11. County or Parish, and State					
Sec 4 T14S R31E NESW 198	CHAVES COUNTY, NM					
	300 00 000	•				
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
TYPE OF SUBMISSION	TYPE OF ACTION					
□ Notice of Intent	☐ Acidize	□ Deepen	☐ Production (Start/Resume)		☐ Water Shut-Off	
	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation		□ Well Integrity	
		■ New Construction	☐ Recomplete		☐ Other	
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	☐ Temporarily Abandon			
	☐ Convert to Injection	☐ Plug Back	☐ Water D	isposal		
13. Describe Proposed or Completed Ope If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for fi Delinquent paperwork not filed (10-07-Workover: POH w/rods and repaired wellhead as nece Set cmt retainer @ 442'. Stung	Illy or recomplete horizontally, k will be performed or provide operations. If the operation reandonment Notices shall be file nal inspection.) I from previous operator. and fished 2 7/8" producessary. Located and isola	give subsurface locations and meast the Bond No. on file with BLM/BIA sults in a multiple completion or reco ed only after all requirements, includ- tion tubing and BHA. Set RBI ted casing leaks from 127'-14	ured and true ve A. Required sub completion in a r ding reclamation P @ 2518'. F O' and 474'-	rtical depths of all pertir sequent reports shall be lew interval, a Form 316 t, have been completed, Replaced	ent markers and zones. filed within 30 days 0-4 shall be filed once	

Set cmt retainer @ 442'. Stung workstring into cmt retainer @ 442' and pumped 100 sx Class C cmt w/2% CaCl and displaced w/0.75 BFW leaving 6 sx in tbg and 2 sx in csg. POH w/workstring and cmt ret stinger. Pump 50 sx Class C cmt w/2% CaCl to squeeze cmt holes from 127'-140'. Displaced cmt to 100'. Circ 12 sx cmt to pit, leaving 2 sx in 4 1/2" casing. DO cmt to top of cmt retainer @ 442'. Pressure tested casing and started taking fluid @ 1 BPM @ 120 psi. Located and isolated additional casing leaks from 126'-158' and 252'-311'. Pumped down casing 75 sx Class C cmt w/2% CaCl. Displaced cmt to 100'. DO cmt to 158'. From 158'-495' apparently drilled outside of the casing because of the redbed and formation returns and never found the cmt retainer @ 442'. POH

14. I hereby certify that the foregoing is true and correct. Electronic Submission #336103 verified by the BLM Well Information System For LEGACY RESERVES OPERATING LP, sent to the Roswell							
Name (Printed/Typed) LAURA PINA		Title	COMPLIANCE COORDINATOR				
Signature (Electronic Submission)		Date	04/08/2016				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved By Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Title Office	Kar	Date			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #336103 that would not fit on the form

32. Additional remarks, continued

w/workstring and bit. Shut well in. RDMO WSU.

LEGACY RESERVES LP

FIELD:

495'

Caprock

DATE:

17-Jan-14

New Mexico

T-Anhy @ 1060'-est

LEASE/UNIT:

DQSU #822 (formerly Trigg Federal #22)

BY:

MWM

COUNTY:

Chaves

WELL: STATE: 822

Location: 1980' FSL & 1980' FWL, Sec 4K, T14S, R31E

KB = 4160'


SPUD: 12/06/55 COMP: 05/10/59

GL = 4153.4'

CURRENT STATUS: Inactive Producer

API = 30-005-00987

Original Well Name: J. H. Trigg Federal #22-4



8-5/8" 24# J-55 @ 113' w/50 sx; circ'd


Casing Leaks: 127'-140', 126'-158', 252'-311', and 474'-504'

CR @ 442' pumped 100 sx cmt with 6 sx left above through csg lk @ 474'-504'

Pumped down csg into csg lk 127'-140' w\ 50sx cmt circ 12sx to surf

DO cmt to CR. Find new csg lk's.

Pumped down csg into csg lk 126'-311' w\ 75sx cmt displaced to 100' DO cmt to 158'. Start getting iron and red beds back in returns, DO to 495' Did not find CR @ 442'. Suspect bit is outside csg. Stopped work.



Calc'd TOC @ 2406' w/enlargement = 15%; yld = 1.26 ft3/sk

Set RBP @ 2518 to repair csg leaks RBP @ 2518'

Top of Queen

Queen: 2762' - 2768' (? spf) (05-59)

2755' - 2762' (? spf) (08-59)

4-1/2" @ 2780' w/100 sx, wght & grd unk

T-Salt @ 1210'-est
B-Salt @ 1830'-est
T-Yates @ 2000'-est

PBTD - 2780' TD - 2780' Well History: DQSU #822 (formerly Trigg Federal #22)

(12-55) - D&A: This well was drilled to 2776' and then plugged and abandoned.

(05-59) - Initial Compl: Re-entered D&A'd well. Perforated 2762' - 2768'. Fractured w/18,500 gals L-O

and 30,000# 20-40 sand @ 23.5 BPM and 2300 - 2850 psi STP. Put well on

production, IP at 11 BOPD/0 BWPD.

(02-95) - C-O-O: To: Circle Ridge Production, Inc.

Fr: Larue & Muncy (operators since atleast 6/72),

(2-96) - C-O-O: To: Northland Operating Co.

Fr: Circle Ridge Production Inc.

(8-01) - C-O-O: To: American Inland Resources Co. LLC.

Fr: Northland Operating Co.

(2-06) - C-O-O: To: Palisades Asset holding Co. LLC

Fr: Caprock Exploration Inc.

(2-07) - C-O-O: To: Celero Energy II LP

(10-07) - Workover: POH w/ rods and fished 2 7/8" production tubing and BHA. Set RBP @ 2518'. Replaced and repaired wellhead as necessary. Located and isolated casing leaks from 127' - 140' and 474' - 504'. Set cmt retainer @ 442'. Stung workstring into cmt retainer @ 442' and pumped 100 sx Class C cment w/ 2% CaCl and displaced w/ 0.75 BFW leaving 6 sx in tbg and 2 sx in csg. POH w/ workstring and cmt ret stinger. Pump 50 sx Class C cement w/ 2% CaCl to squeeze cement holes from 127' - 140'. Displaced cmt to 100'. Circ 12 sx cmt to pit, leaving 2 sx in 4 1/2" casing. DO cement to top of cmt retainer @ 442'. Pressure tested casing and started taking fluid @ 1 BPM at 120 psi. Located and isolated additional casing leaks from 126' - 158' and 252' - 311'. Pumped down casing 75 sx Class C cement w/ 2% CaCl. Displaced cmt to 100'. DO cement to 158'. From 158' - 495' apparently drilled outside of the casing because of the redbed and formation returns and never found the cement retainer @ 442'. POH w/ workstring and bit. Shut well in. RDMO WSU.