UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

-	R.	ien.	41		
- 6	3 CS-4	Dυi	ati-	(844)	lac

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5. Lease Serial No. NMLC059001

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

6 If Indian Allottee or Tribe Nam

abandoned well	6. If Indian, Allottee or Tribe Name									
SUBMIT IN TRI	7. If Unit or CA/Agreement, Name and/or No. 8920003410									
1. Type of Well	8. Well Name and No. MCA UNIT 223									
Oil Well Gas Well Oth Name of Operator	9. API Well No.									
CONOCOPHILLIPS COMPAN	30-025-00800-00-S1									
3a. Address		. (include area code 3-3355)	10. Field and Pool, or Exploratory MALJAMAR						
MIDLAND, TX 79710		LODI	20 00	IVIALUAI	VICTO					
4. Location of Well (Footage, Sec., T	, R., M., or Survey Description)		HODI	55 00	11. County	or Parish, and Sta	te			
Sec 33 T17S R32E NWNE 66	0FNL 1980FEL /		ΔPR	1 8 2016	LEA CC	OUNTY, NM				
			AL IV	1 0 2010						
12. CHECK APPE	ROPRIATE BOX(ES) TO	INDICATE	NATURE OF	Notice, R	PORT, OR	OTHER DA	TA			
TYPE OF SUBMISSION	ТҮРЕ О	TYPE OF ACTION								
Notice of Intent	☐ Acidize	☐ Dee	□ Deepen		☐ Production (Start/P		INT TO PA TOWN X			
	☐ Alter Casing	☐ Frac	☐ Fracture Treat		☐ Reclamation		INT TO PA A. 🛪			
☐ Subsequent Report	☐ Casing Repair		■ New Construction		☐ Recomplete		P&A R			
☐ Final Abandonment Notice	☐ Change Plans		☑ Plug and Abandon		☐ Temporarily Aban					
13. Describe Proposed or Completed Ope	☐ Convert to Injection		☐ Plug Back		☐ Water Disposal					
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 1) MIRU, NDWH, NUBOP. POOH w/ Prod Equip 2) Set PKR @ 3300' - Sqz 20sx cmt - disp TOC to 3500'. WOC-Tag 3) Set 4-1/2" CIBP @ 3450' 4) Tbg @ 3450' - circ hole w/ MLF. Spot 25sx cmt @ 3450'-3200'. WOC-Tag 5) Perf @ 2150' - Sqz 40sx cmt to 2050'. WOC-Tag 2030'. 6) Perf @ 1225' - Sqz 40sx cmt to 1725'. WOC-Tag 2030'. 7) Perf @ 300' - Circ 40sx cmt to surface 8) Top off well. RDMO. Cut off WH & anchors. Install dryhole marker RECLAMATION PROCEDURE										
AT	TACHED P	airie (hicken (POAS 1	Affact	ud				
14. I hereby certify that the foregoing is true and correct. Electronic Submission #335326 verified by the BLM Well Information System For CONOCOPHILLIPS COMPANY, sent to the Hobbs Committed to AFMSS for processing by PRISCILLA PEREZ on 04/04/2016 (16PP0521SE)										
Name (Printed/Typed) GREG BR	YANT		Title AGEN	Γ						
-1										
Signature (Electronic S										
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE US	SE					
Approved By W	Title En	3			Date 4/7/16					
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu-	itable title to those rights in the		Office CF	-0						
Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s					ke to any depa	artment or agency	of the United			

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **





WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

RKB @ 3938 DF @ 3928 Subarea Maljamar Lease & Well No No. 223 660 FNL & 1980 FEL. Sec 33, T-17S, R-32E Legal Description 10" Hole County State New Mexico Lea 8" 32# SS @ 29' Field Maljamar (Grayburg-San Andres) Cmt 15 sx. Circ Date Spudded 1/23/1941 Rig Released. TOC @ Surface API Number 30-025-00800 Status Active Service Well Drilled as Pearsall #5A OGRID# 005073 Lease # LC-059001 Stimulation History: TOC 5 1/2" @ 290" (EST) Lbs. Max Max Interval Date Sand Press ISIP Rate Туре Gals Down 3891-4051 2/23/1941 Nitro Glycerin 320 Qts 1/7/1946 Deepen to 4137 4056-4137 1/7/1946 Nitro Glycerin 210 PB fr 4148-4077 w/ 40 sxs cmt 210 Qts 4/10/1947 4/13/1947 Ran 5' Plastic Plug; PB to 4072 Top Salt @ 1175 8/15/1955 LC 10.000 15,000 2/29/1968 CO fr 4050-4072 2/29/1968 Placed on Injection Set CIBP @ 3862' w/ sand on top TOS @ 3850 Run 4 1/2" 11.35# K-55 @ 3842; cmt w/ 200 sxs; TOC @ 3000' 7/3/1975 7/3/1975 7/3/1975 DO & Push BP to 4135 Fill wellbore fr 4135-3982 w/ pea gravel Set CMRT @ 3730' Sqz/d 3730-3982 w/ 130 sxs cmt 9/18/1987 9/18/1987 9/18/1987 9/18/1987 DO to 4135 9/18/1987 Ran 3" Fiberglass Liner N-80 to 4135'; cmt'd w/ 150 sxs; TOL @ 3523' 9/18/1987 CO to 4135' 9/18/1987 2% KCL Base Salt @ 2100 Perf 3900-3990, 4030-4050 & 4056-4072 w/ 1 SPF 9/18/1987 5/2/1988 Re-Perl 3900-4002, 4010-4020, 4040-4045, 4052-4074, 4083-4085, 4091-4093, 4097-4108, 4115-4120 w/ 1 SPF 3900-4120 5/2/1988 15% HCL 10/18/2005 Tag Fill @ 4098 TOC 4 1/2" @ 3000 TOL 3" @ 3523" 7-7/8" Hole 5-1/2" 14# SS @ 3558' Cmt 250 sxs. TOC @ 290' (est) Sqz'd 3730-3982 w/ 130 sxs cmt 4 1/2" 11.35# K-55 @ 3842" Cmt 200 sxs TOC @ 3000 3900-3990 4030-4093 Formation Tops: Rustler 4097-4120 Salado Tag Fill @ 4098 Tansill Yates 3" FG Liner N-80 @ 4135" Seven Rivers Cmt 150 sxs Queen TOL @ 3523 Grayburg San Andres PBTD @ 4072 TD @ 4051' NTD @ 4137'

Date March 29, 2016

WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

Date March 29, 2016 RKB @ 3938 DF @ GL @ 3928 Maljamar No. 223 Lease & Well No. MCA Unit 660 FNL & 1980 FEL, Sec. 33, T-17S, R-32E Legal Description 10" Hole County Lea State : New Mexico Maljamar (Grayburg-San Andres) 8" 32# SS @ 29' Field Cmt 15 sx, Circ Date Spudded 1/23/1941 Rig Released: TOC @ Surface API Number 30-025-00800 Status Active Service Well P&S 40sx cmt @ 300'-3' Drilled as Pearsall #5A OGRID# 005073 LC-059001 Lease # Stimulation History: TOC 5 1/2" @ 290' (EST) Lbs. Max Max Interval Date Gals Press ISIP Rate Type Sand Down 3891-4051 2/23/1941 Nitro Glycenn 320 Ots 1/7/1946 Deepen to 4137 4056-4137 1/7/1946 Nitro Glycerin 210 Ots 4/10/1947 PB fr 4148-4077 w/ 40 sxs cmt 4/13/1947 Ran 5' Plastic Plug; PB to 4072 1115 Top Salt @ 1175 8/15/1955 LC 10,000 15,000 P&S 40sx cmt @ 1225'-1125' . Tag 2/29/1968 CO fr 4050-4072 2/29/1968 Placed on Injection min 110' 7/3/1975 Set CIBP @ 3862' w/ sand on top; TOS @ 3850' 7/3/1975 Run 4 1/2" 11.35# K-55 @ 3842; cmt w/ 200 sxs; TOC @ 3000' 7/3/1975 DO & Push BP to 4135' 9/18/1987 Fill wellbore fr 4135-3982 w/ pea gravel Set CMRT @ 3730' 9/18/1987 9/18/1987 Sqz'd 3730-3982 w/ 130 sxs cmt DO to 4135' 9/18/1987 9/18/1987 Ran 3" Fiberglass Liner N-80 to 4135'; cmt'd w/ 150 sxs; TOL @ 3523' 9/18/1987 CO to 4135 2630 9/18/1987 2% KCL 3150 Base Salt @ 2100" 9/18/1987 Perf 3900-3990, 4030-4050 & 4056-4072 w/ 1 SPF P&S 40sx cmt @ 2150'-2056' - Tag 5/2/1988 Re-Perf 3900-4002, 4010-4020, 4040-4045, 4052-4074, 4083-4085, 4091-4093, 4097-4108, min. 120 4115-4120 w/ 1 SPF 3900-4120 5/2/1988 15% HCL 10/18/2005 Tag Fill @ 4098" TOC 4 1/2" @ 3000 Spot 25sx cmt @ 3450'-3200' - Tag T Set CIBP @ 3450' 3475 TOL 3" @ 3523" Sqz 20sx cmt under PKR - disp TOC to 3500 - Tag 7-7/8" Hole 5-1/2" 14# SS @ 3558" Cmt 250 sxs; TOC @ 290' (est) Sqz'd 3730-3982 w/ 130 sxs cmt 4 1/2" 11.35# K-55 @ 3842" Cmt 200 sxs TOC @ 3000 3900-3990 4030-4093 Formation Tops; Rustler 4097-4120 Salado Tag Fill @ 4098 Tansill Yates 3" FG Liner N-80 @ 4135' Seven Rivers Cmt 150 sxs; Queen TOL @ 3523' Grayburg San Andres PBTD @ 4072 TD @ 4051'

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

HOBBS OCD

APR 1 8 2016

Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

RECEIVED

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:</u>
From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
 Operations must include adequate measures for stabilization and reclamation of disturbed lands.
 Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
 process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.

- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.
- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Linda Denniston Environmental Protection Specialist 575-234-5974

Henryetta Price Environmental Protection Specialist 575-234-5951

Dara Glass Environmental Protection Specialist 575-234-5924

Shelly Tucker Environmental Protection Specialist 575-234-5979