Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103	
District I – (575) 393-6161 Energy, Minerals and Natural Resources		Revised July 18, 2013 WELL API NO.		
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283		30-025-00350	
811 S. First St., Artesia, NM 88210	11 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of	Lease
1000 Rio Brazos Rd., Aztec, NM 87410	istrict III – (505) 334-6178 1220 South St. Francis Dr.		STATE 🖂	FEE 🗆 🖊
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505		6. State Oil & Gas I	Lease No.
87505				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or U	Init Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			STATE BH	1
PROPOSALS.)			0 777 11 37 1	J
1. Type of Well: Oil Well	Gas Well Other-SWD	OBBS OC	1	,
2. Name of Operator	/		9. OGRID Number	1
Devon Energy Production Compar	ny, LP	APR 2 5 2016	6137	,
 Address of Operator W. Sheridan Avenue, Oklahor 	Pool name or W SWD; SAN ANDRE			
4. Well Location	ma City, OK 75102	RECEIVED	SWD, SAN ANDRI	2.5
The state of the s	000 fact from the South	line and 220	feet from the Ea	act lime
Section 32	:990_feet from theSouth Township 15S	line and330 Range 32E		astline Lea County, NM
Section 32	11. Elevation (Show whether DE			Lea County, NM
4322' KB; 4309' GL; 13' KB to GL				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO				
NOTICE OF INTENTION TO: SUBSEQUENT REI PERFORM REMEDIAL WORK □ PLUG AND ABANDON ☒ REMEDIAL WORK □ INT TO PA ▷				
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRI			P&A NR	
PULL OR ALTER CASING		CASING/CEMENT		P&A R
DOWNHOLE COMMINGLE	The second secon		_	FOAR
CLOSED-LOOP SYSTEM □	<u>_</u>			
OTHER:		OTHER:	1 -11 1	. 1 1: 1 1 .
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.				
/ to 40ZO' WOC + TAG				
1. MIRU. Release 4-1/2" AD-1 Packer @ 4,012'. POOH w/packer & 2-3/8" injection tubing				
2. Set CIBP @ 4,000'. Tag plug. Spot 25 sx (360') Cl C @ 4,000' - 3,640'. 3. Spot 25 sx (360') Cl C @ 2,600' - 2,240'. Tag TOC. (B.Salt / Yates @ 2,510')				
4. Spot 25 sx (360') Cl C @ 1,350' – 990'. Tag TQC. (B.Salt @ 1,311')				
5. Cut & pull 4-1/2" casing from 750'. Pump 20'sx (100') stub plug @ 800' – 700'. Tag TOC.				
6. Perf 8-5/8" casing @ 680'. Pump 100 sx Cl C @ in/out @ 700'-550'. Tag TOC. (13-3/8" shoe @ 631')				
7. Perf 8-5/8" casing @ 150'. Pump 95 sx Cl C in/out to surface.				
8. Cut wellhead off. Set dry l	note marker.			
			RIOR TO BEGINNIN	IG
Spud Date:	PLUGGIN	G OPERATIONS		
T1 1 2 3 4 4 5 5 4 4 5 5 4 4 5 5 4 4 5 5 4 5 5 4 5				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
0	00 L			11 - 11
SIGNATURE KOMING &	TITLE Pro	duction Technologis	stDATE	E 4-5-16
T	F 1 - 11	01	IONE: 405 550 4615	/
Type or print name Ronnie Slack E-mail address: _Ronnie.Slack@dvn.com PHONE: _405-552-4615 For State Use Only				
APPROVED BY: Wal Withele TITLE Petroleum Engn Specialist DATE 4-26-2016				
Conditions of Approval (if any):				



