State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

David Martin

Cabinet Secretary

Brett F. Woods, Ph.D. Deputy Cabinet Secretary David Catanach, Director Oil Conservation Division



Response Required - Deadline Enclosed

Underground Injection Control Program "Protecting Our Underground Sources of Drinking Water"

26-Apr-16

EOR OPERATING COMPANY

777 N. Eldridge Pkwy Suite 150 Houston TX 77079-7079

LETTER OF VIOLATION and SHUT-IN DIRECTIVE **Failed Mechanical Integrity Test**

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MILNESAND	UNIT No.182			30-041-00131-00-00
		Active Injection - (All Types)		D-18-8S-35E
Test Date:	4/26/2016	Permitted Injection PSI:	Actual PSI:	
Test Reason:	Annual IMIT	Test Result: F	Repair Due:	7/30/2016
Test Type:	Std. Annulus Pres. Test	FAIL TYPE: Other Internal Failure	FAIL CAUSE:	
	THE PART OF THE PA	10 15 06 11 HAVE NOT WORKED ON W	THE OWNER TAIL	TIPET LOWING
Comments on 1	MIT: MIT-FAILURE. RULE 2ND LETTER OF VIO	: 19.15.26.11, HAVE NOT WORKED ON W LATION.	ELL SINCE FAII	LURE LAST YEAR.
MILNESAND	2ND LETTER OF VIO		ELL SINCE FAII	
	2ND LETTER OF VIO		ELL SINCE FAII	
	2ND LETTER OF VIO	LATION.	Actual PSI:	30-041-10059-00-00
MILNESAND	2ND LETTER OF VIO UNIT No.310	Expired TA Injection - (All Types)		30-041-10059-00-00

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely

Hobbs OCD District Office

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. * Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

HOBBS NM 88240 OIL CONSERVATION DIVISION 1625 N FRENCH DRIVE EMNRD

Houston TX 77079-7079 EOR OPERATING COMPANY 777 N. Eldridge Pkwy Suite 150



#ASLER
FIRST-CLASS MAIL

\$000.46⁵
04/26/2016 ZIP 88240
012E14642224
US