State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

David Martin

Cabinet Secretary

Tony Delfin

Deputy Cabinet Secretary

David Catanach, Director Oil Conservation Division

Response Required - Deadline Enclosed

Underground Injection Control Program "Protecting Our Underground Sources of Drinking Water"

23-Jun-16

OCCIDENTAL PERMIAN LTD 1017 W STANOLIND ROAD



HOBBS OCD

JUN 2 3 2016

RECEIVED

LETTER OF VIOLATION and SHUT-IN DIRECTIVE Failed Mechanical Integrity Test

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

Active Injection - (All Types)

NORTH HOBBS G/SA UNIT No.242

30-025-28413-00-00

N-29-18S-38E

Test Date:

6/23/2016

Permitted Injection PSI:

Actual PSI:

Test Reason:

Annual IMIT

Test Result:

Repair Due:

9/26/2016

Test Type:

Bradenhead Test

FAIL TYPE: Other Internal Failure

FAIL CAUSE:

OPERATOR REPORTED BHT-FAILURE. RULE: 19.15.26.11.

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely

Hobbs OCK District Office

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. * Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

OIL CONSERVATION DIVISION 1625 N FRENCH DRIVE **EMNRD HOBBS NM 88240**

1017 W. STANOLIND ROAD HOBBS N.M. 88240 OCCIDENTAL PERMIAN LTD



#ASLER
FIRST-CLASS MAIL

\$000.46⁵
06/23/2016 ZIP 88240
012E14642224
US