Form 3160-5

FORM APPROVED

	UNITED STATES PARTMENT OF THE INT JREAU OF LAND MANAGE		OMB	NO. 1004-0135 St. July 31, 2010			
SUNDRY I	5. Lease Serial No. NMNM90161	5. Lease Serial No.					
Do not use this abandoned well	6. If Indian, Allottee						
SUBMIT IN TRIE	7. If Unit or CA/Agr NMNM120042	7. If Unit or CA/Agreement, Name and/or No. NMNM120042X  8. Well Name and No. WEST BLINEBRY DRINKARD UNIT 52					
Type of Well     ☐ Gas Well ☐ Oth	Well Name and No     WEST BLINEBR						
Name of Operator     APACHE CORPORATION	9. API Well No. 30-025-38198						
3a. Address 303 VETERANS AIRPARK LA MIDLAND, TX 79705		10. Field and Pool, or Exploratory EUNICE; B-T-D, NORTH					
4. Location of Well (Footage, Sec., T.	11. County or Parish	11. County or Parish, and State					
Sec 9 T21S R37E SWSE 1908	FSL 1461FEL		LEA COUNTY COUNTY, NM				
12. CHECK APPR	COPRIATE BOX(ES) TO I	NDICATE NATURE OF	NOTICE, REPORT, OR OTHI	ER DATA			
TYPE OF SUBMISSION		F ACTION	1				
Notice of Intent	□ Acidize	□ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off			
☐ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	Reclamation	☐ Well Integrity			
	☐ Casing Repair	□ New Construction	☐ Recomplete	☐ Other			
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection	☐ Plug and Abandon☐ Plug Back	☐ Temporarily Abandon ☐ Water Disposal				
following completion of the involved	operations. If the operation results and onment Notices shall be filed on all inspection.)	s in a multiple completion or reconly after all requirements, inclu	A. Required subsequent reports shall be completion in a new interval, a Form 31 ding reclamation, have been completed	60-4 shall be filed once			
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #342 For APACHE	2627 verified by the BLM We	ell Information System e Hobbs				
Name (Printed/Typed) REESA FI	SHER	Title SR ST	Title SR STAFF REGULATORY ANALYST				
Signature (Electronic S	ubmission)	Date 06/20/2	2016				
	THIS SPACE FOR	FEDERAL OR STATE	OFFICE USE				
A		Tiele		Date			
Approved By	Approval of this notice does not	Title		Dutc			
certify that the applicant holds legal or equ which would entitle the applicant to condu	itable title to those rights in the sul	bject lease Office					

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*\* OPERATOR-SUBMITTED \*\* OPERATOR-SUBMITTED \*\*

1000 6 27/2016

## WBDU 52 (API: 30-25-38198) Proposed Procedure

Clean out, add pay, and acid stimulate Blinebry, Tubb, Drinkard

- Day 1: MIRU. NU HBOP. POOH w/pump and rods. Scan out of hole w/ 2-7/8" tubing. PU and RIH w/bit and drill collars on 2-7/8" work string.
- Day 2: RU and break circulation with foam nitrogen unit. Clean out well to PBTD. Circulate clean. POOH and LD bit and drill collars.
- Day 3: MIRU WL. RIH and perforate the Drinkard as per the attached sheet w/ 3-3/8" slick guns loaded w/ Owen TAG-3375-311SL charges (or similar) @ 1 SPF, 180 deg phasing (total 41 ft, 41 shots), POOH
- Day 4: RIH w/ 2-7/8" work string, treating packer, and RBP. Set RBP at +/-6,750'. Set packer at +/-6,500'. Acidize the Drinkard formation down 2-7/8" work string w/5,000 gal of 15% HCl-NE-FE-BXDX acid w/scale inhibitor and rock salt @ +/-10 BPM (max pressure = 4,000 psia). Release packer. Wash out salt.

Retrieve RBP and PUH to 6,400'. Set RBP at +/-6,400'. Set packer at +/-6,075'. Acidize the Tubb formation down 2-7/8" work string w/3,000 gal of 15% HCl-NE-FE-BXDX acid w/scale inhibitor and rock salt @ +/-10 BPM (max pressure = 4,000 psia). Release packer. Wash out salt.

Retrieve RBP and PUH to 6,050'. Set RBP at +/- 6,075'. Set packer at +/- 5,550'. Acidize the Blinebry formation down 2-7/8" work string w/3,000 gal of 15% HCl-NE-FE-BXDX acid w/scale inhibitor and rock salt @ +/- 10 BPM (max pressure = 4,000 psia). Release packer. Wash out salt.

Retrieve RBP. POOH w/ 2-7/8" work string, packer, and RBP. LD 2-7/8" work string.

Day 5: RIH w/ 2-7/8" tubing and SN to +/- 6,718'. Swab well for approximately 4 hours to flow back any scale and/or insoluble iron. RIH w/ pump and rods. Place well on production. RDMO.

	WBD	OU 52 Perfora	tions			
	Guns: 3-3,	/8" TAG w/SD	P Charg	es	H 1	
Zone	Тор	Bottom	Feet	SPF	Shots	
Drinkard	6468	6469	2	1	2	
Drinkard 6485 6490		6490	6	1	6	
Drinkard	Orinkard 6502 6504					
Drinkard	6512	6513	2	1	2	
Drinkard	6567	6572	6	1	6	
Drinkard	6581	6585	5	1	5	
Drinkard	6604	6607	4	1	4	
Drinkard	6642	6646	5	1	5	
Drinkard	6655	6662	8	1	8	
		Total	41	125	41	

IWI		Surface Legal Location	Field Name	-	License #		State/Province		Well Purpose	
253 Date	8198	190' FSL, 140' FEL, Unit O, Sec 9, T- Orginal Drilling Rig Release	Original KB Ele		Ground Elevati	on (ft)	NEW MEXICO		PUD Casing Flange Ele	vation (ft)
200	7 16:30		3,485.0	3,474.0 (Total Depth All (TVD) (19(B)		11.0		3,474.0		
na	Hole - 6,791				Total Deput A	(140)(88)				
UD	- West Blinebry D	rinkard Unit 52 - Original Hole, 5/2/	2016 8:51:30 AM	Casing Strip	nos					
דס				Csg Des		OD (In)	Willen (bft)		rade Set	Depth (ft)
to(B)		Vertical schematic (actual)		Surface Prod 1	- NEW	8 5/8 5 1/2		J-55	THE PARTY OF	6,8
				AND DESCRIPTION OF THE PARTY OF		0 112	17.00	1300		0,0
				Tubing Strip Tubing Descriptor		un Date	String Len	क्री (दे)	Set Depth (ft)	B)
				- Per	n Des	Jts   Mak		del (	OD (in)   Wit (ib/ft)   C	rade L
				RET	ii Des	JE MEN	E NK	NE I	SO (IN) VAC (IDAL)	Face L
	Www.	w W		Rod Strings						
0		<b>/</b>		Rod Description		un Date	String Len	क्री (द)	Set Depth (ftx	B)
		— Surface; 11.0-1,	296.0 ftKB	iten	n Des	Jts Mak	e Mc	del (	OD (in)   Wt (ib/ft)   C	rade La
00				Other In Ho Description	le		[00 (n)	Too	(fb(B)   Run Date	
9	8			Perforations	5					
000				Date	Туре	Top (ftKB)	Bitm (ftKB)	Prop?	Shot Dens (shots/ft)	Entered Total
				2/28/2007	Blinebry	5,610	5,616 5,684	No No	2.0	
		<b>(</b>		2/28/2007	Blinebry	5,706	5,712	No	2.0	
00				2/28/2007	Blinebry	5,804	5,810	No	2.0	A 164
				2/23/2007	Tubb	6,124	6,128	No	2.0	TO THE
				2/23/2007	Tubb	6,156	6,160	No No	2.0	
2,000			2/23/2007	Tubb	6,246	6,250	No	2.0	1	
				2/23/2007	Tubb	6,270	6,274	No	2.0	
000				2/23/2007	Tubb	6,310	6,314	No	2.0	
				2/23/2007	Tubb Drinkard	6,342	6,346	No No	2.0	THE STATE OF
				2/19/2007	Drinkard	6,586	6,590	No	2.0	
too		· · · · · · · · · · · · · · · · · · ·	Control of the section of the sectio	2/19/2007	Drinkard	6,596	6,600	No	2.0	
		Production; 300.	0-6,870.0 ftKB	2/19/2007	Drinkard	6,614	6,618	No	2.0	57.0
	8			2/19/2007	Drinkard	6,632	6,636	No	2.0	
000	- 8			2/19/2007	Drinkard Drinkard	6,648	6,654 6,668	No No	2.0	
	9	<b>X</b>		Plug Back T	A STATE OF THE PARTY OF THE PAR	3,001	0,000			
				Date 1/16/2007	Ту	pė			Depth (fb(B) De 6,791	epth (TVD)
200	7	<b>*</b>		Comments					0,761	
				Comment					E 77 - 1 2 4 7 2	
18										
000	8									
				1						
000										
	9	2								
	- 81	7								
00		*		1						
	===									
	= 0									
100	- 8	Cement Plug; 6,	791.0-6,870.0	1						
	E 20	ftKB Flug Back Total	Depth: 6,791.0							
	<b>1000000</b>	tike		1						