Submit 1 Copy To Appropriate District Office	State of New Me		Form C-103 Revised July 18, 2013
District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 District III – (505) 334-6178 District III – (505) 334-6178 1220 South St. Francis Dr.			WELL API NO.
		DIVISION	30-025-02345
		5. Indicate Type of Lease STATE FEE	
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	CEIVE Santa Fe, NM 8	7505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			EK Penrose Sand Unit
1. Type of Well: Oil Well Gas Well Other Water Injection			8. Well Number 122
2. Name of Operator Seely Oil Company			9. OGRID Number 20497
3. Address of Operator		10. Pool name or Wildcat	
815 W. 10 th Street, Fort Worth, TX 76102			EK-Yates-SR-Queen
4. Well Location			
Unit Letter K: 1980 feet from the South line and 1887 feet from the West line			
Section 19 – Township 18S – Range 34E NMPM Lea County, New Mexico 11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
11. Elevation (Snow whether DR, RRB, R1, GR, etc.)			
	A SECOND SECOND		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL			
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB DOWNHOLE COMMINGLE			
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM			
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
1. MI & RU CU, TOH w/Salta lined tbg & pkr.			
2. Re-perforate from 4678'- 4686' w/8 spf.			
3. TIH w/pkr & tbg. to 4700'±			
Spot xylene across perforations overnight. Set also a critical system of the sys			
 Set pkr & acidize w/750 gals 71/2% NEFE. Swab load back Fractures treat w/10,000 gallons gelled KCL w/25,000 lbs sand. 			
7. Swab part of load back			
 Release pkr & circulate hole TOH w/pkr & tbg. 	clean.		Condition of Approval: notify
 TOH w/pkr & tbg. TIH w/plastic lined pkr & Salta tbg. Set pkr @ 4600'+ 			
11. Run MIT test for NMOCD			OCD Hobbs office 24 hours
12. Return well to injection Prior of running MTT Test & Chart			
Saud Data:	Rig Release D	ata:	
Spud Date:	Kig Kelease D	ate.	
I hereby certify that the information abo	ve is true and complete to the b	est of my knowled	ge and belief.
SIGNATURE Jana Abrole	TITLE_Presid	lent	DATEJune 23,2016
Type or print name David L. Henderson E-mail address: <u>dhenderson@seelyoil.com</u> PHONE: (817) 332-1377			
For State Use Only			
APPROVED BY: Maleu & Show Fithe Dist Supervisor DATE 6/23/2016			
Conditions of Approval (if any):	Sum Chile	a super	DAIL - J- J