UNITED STATES

FORM APPROVED

7-24-16

Date

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT OCD Hobbs			bs	OMB NO. 1004-0135 Expires: July 31, 2010	
SUNDRY NOTICES AND REPORTS ON WELLS-LOBBS OC				5. Lease Serial No. NMNM14497	
	s form for proposals to II. Use form 3160-3 (API		6. If Ind	ian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side. 1. Type of Well Gas Well Other				7. If Unit or CA/Agreement, Name and/or No. 8. Well Name and No. DIAMOND 5 FED 03	
3a. Address MIDLAND, TX 79702		8b. Phone No. (include area code) 10. Field Ph: 432-686-3689 PITC		and Pool, or Exploratory CHFORK RANCH	
4. Location of Well (Footage, Sec., T. Sec 5 T25S R34E NENW 660	FNL 2230FWL		LEA .	COUNTY, NM OR OTHER DATA	
TYPE OF SUBMISSION	ROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION				
□ Notice of Intent ☑ Subsequent Report	Acidize	Deepen	☐ Production (Star	uction (Star	
	Alter Casing	☐ Fracture Treat	Reclamation Recomplete	P&A R R	
	Casing Repair	☐ New Construction			
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	☐ Temporarily Ab		
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal		
13. Describe Proposed or Completed Ope If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for fi	ally or recomplete horizontally, rk will be performed or provide operations. If the operation re bandonment Notices shall be fil	give subsurface locations and meas the Bond No. on file with BLM/BI sults in a multiple completion or rec	nured and true vertical dept A. Required subsequent re- completion in a new interveding reclamation, have been	hs of all pertinent markers and zones. ports shall be filed within 30 days al, a Form 3160-4 shall be filed once en completed, and the operator has	
5/31/16 MIRU to P&A. 6/02/16 POOH w/ 2-7/8" tubing. 6/03/16 RIH w/ 3-1/2" CIBP set at 13480' as instructed 6/06/16 Spot 60 sx Class H cement plug from 13480' to RIH and tag plug at 12745'. John Staton - BLM on locat		o 12600'. WOC 5 hrs.	Liability unde Surface restor	p plugging of the well bore, or bond is retained until ation is completed.	
12420' to 12066". 6/07/16 RIH and tag plug at 1 hrs. RIH and tag plug at 8995' 6/08/16 RIH and cut 5-1/2" ca 6/09/16 Spot 40 sx Class C c 6/10/16 RIH and tag plug at 5 RIH and tag plug at 5135'. Re-	. Spot 25 sx Class C nea asing at 5750'. POOH. La ement plug from 5800' to 6615'. Spot 45 sx Class C	t cement plug from 6300' to 6 ydown 5-1/2" casing. 5621'. cement plug from 5270' to 5	5047'. 104'. WOC 4 hrs.		

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #342230 verified by the BLM Well Information System

For EOG RESOURCES INCORPORATED, sent to the Hobbs

Committed to AFMSS for processing by PRISCILLA PEREZ on 06/16/2016 (16PP0038SE)

Title

Name (Printed/Typed) STAN WAGNER REGULATORY ANALYST

(Electronic Submission) Date 06/16/2016

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By.

Conditions of approval of any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

MW/OCD 8-3-2016

Additional data for EC transaction #342230 that would not fit on the form

32. Additional remarks, continued

RIH and tag plug at 5110'. Spot 35 sx Class C cement plug from 3000' to 2871'. Spot 45 sx Class C neat coment plug from 1650' to 1484'.
6/13/16 PiH and tag plug at 1485'. Spot 50 sx Class C cement plug from 687' to 502'. WOC 4 hrs.
RIH and tag plug at 520'. Spot 15 sx Class C neat cement plug from 60' to surface. John Staton BLM witnessed.
Cut off wellhead, weld on P&A marker. Clean location.