2	
Submit 1 Copy To Appropriate District Office State of New Mexico	Form C-103
District I – (575) 393-6161 Energy, Minerals and Natural Resources	Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 811 S. First St. Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-28838
811 S. First St., Artesia, NM 88210 AUG 0 8 2016 220 South St. Francis Dr. 1000 Bin Brazos Rd Artec. NM 87410 AUG 0 8 2016 220 South St. Francis Dr.	5. Indicate Type of Lease
Santa Fe NM 87505	STATE FEE
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NMRECEIVED	6. State Oil & Gas Lease No.
67505	LG1543
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	State VW
PROPOSALS.) 1. Type of Well: Oil Well 🗗 Gas Well 🗌 Other	8. Well Number 6
2. Name of Operator	9. OGRID Number
OXY USA WTP LP	192463
3. Address of Operator	10. Pool name or Wildcat
P.O. Box 50250 Midland, TX 79710	Mescalero Escarpe Bone Spring
4. Well Location	
Unit Letter I: 1980 feet from the South line and 3	
Section 12 Township 135 Range 33E 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	NMPM County Lea
The Elevation (Show whether DK, KKB, KT, OK, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, I	Report or Other Data
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A	
PULL OR ALTER CASINGMULTIPLE COMPL CASING/CEMENT	
DOWNHOLE COMMINGLE	
CLOSED-LOOP SYSTEM	
OTHER: Part Add'(Interval & Frac D) OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
1. MIRU PU. TOH w/ pump & rods & LD. NDWH, NUBOP. TOH w	v/ tubing & pump.
 PU 4-5/8" bit and scraper and C/O well to PBTD. Set RBP at <u>+</u>8570'. Pressure test to 70% of burst for 30 min. 	
4. Perf @ $8455-8465^{\circ}$, 4 spf, 40 holes, using $3-1/8^{\circ}$ guns loaded w/ 23 gm charge.	
5. Load hole and establish injection rate. RDMO PU.	
6. MI 6 frac tanks and load with fw. MIRU frac & WL co. Frac stage 1 with 100 mlb 20/40 white sand.	
7. RIH & Set CBP at 8400'.	
8. Perf 8298-8302' & 8179-8187'; 4 spf, 48 holes, using 3-1/8" guns l	oaded w/ 23 gm charge.
 Frac well with 200 mlb 20/40 sand. RU flow back iron and equipme 10. C/O well to RBP at 8570', Run BHA on 2-7/8" tubing: NC at 8505' 	ent. Flow back well until clean.
11. Run pump and rods per lift specialist. Put well to production equip	
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge	and belief.
111	
SIGNATURE TITLE Sr. Regulatory Advis	SOTDATE_SUU
Type or print name <u>David Stewart</u> E-mail address: <u>david stewart@ox</u>	y.com PHONE: <u>432-685-5717</u>
For State Use Only AA	
APPROVED BY: Maley Brown PITLE Dist Supervisor DATE 8/10/2016	
Conditions of Approval (if any):	
U	


/

L

2

OXY USA WTP LP - Proposed State DW #6 API No. 30-025-28838

.



17-1/2" hole @ 349' 13-3/8" csg @ 349' w/ 500sx-TOC-Surf-Circ

11" hole @ 3300' 8-5/8" csg @ 3300' w/ 1300sx-TOC-Surf-Circ

7-7/8" hole @ 8914' 5-1/2" csg @ 8914' w/ 1265sx-TOC-3310'-TS

2-7/8' tbg @ 8505' w/ TAC @ 8150'

OXY USA WTP LP - Current State DW #6 API No. 30-025-28838

TD-8914'

17-1/2" hole @ 349' 13-3/8" csg @ 349' w/ 500sx-TOC-Surf-Circ

11" hole @ 3300' 8-5/8" csg @ 3300' w/ 1300sx-TOC-Surf-Circ

7-7/8" hole @ 8914' 5-1/2" csg @ 8914' w/ 1265sx-TOC-3310'-TS

Perfs @ 8606-8789'

2-7/8' tbg @ 8787' w/ TAC @ 8568'

PB-8868'